



# Smithsonian

*Institution Archives*

## Project Files, 1975-1984

Finding aid prepared by Smithsonian Institution Archives

Smithsonian Institution Archives  
Washington, D.C.  
Contact us at [osiaref@si.edu](mailto:osiaref@si.edu)

## Table of Contents

Collection Overview .....	1
Administrative Information .....	1
Descriptive Entry.....	1
Names and Subjects .....	1
Container Listing .....	3

## Collection Overview

<b>Repository:</b>	Smithsonian Institution Archives, Washington, D.C., <a href="mailto:osiaref@si.edu">osiaref@si.edu</a>
<b>Title:</b>	Project Files
<b>Date:</b>	1975-1984
<b>Identifier:</b>	Accession 85-204
<b>Creator::</b>	Smithsonian Institution. Office of Design and Construction
<b>Extent:</b>	19 cu. ft. (19 record storage boxes)
<b>Language:</b>	English

---

## Administrative Information

### Preferred Citation

Smithsonian Institution Archives, Accession 85-204, Smithsonian Institution. Office of Design and Construction, Project Files

---

## Descriptive Entry

This accession consists of memoranda, blueprints, drawings, specifications, and correspondence. Museums and facilities documented in this accession include the National Museum of Natural History, the Smithsonian Institution Building, the Arts & Industries Building, the Silver Hill Facility, the National Museum of American History, the American Art and Portrait Gallery Building, the National Air and Space Museum, the Museum Support Center, the Smithsonian Environmental Research Center (formerly Chesapeake Bay Center for Environmental Studies), the Hirshhorn Museum and Sculpture Garden, the Cooper-Hewitt Museum, the Freer Gallery of Art, and general files.

---

## Names and Subject Terms

This collection is indexed in the online catalog of the Smithsonian Institution under the following terms:

### Subjects:

- Architectural design
- Buildings -- Maintenance
- Buildings -- Repair and reconstruction
- Museum buildings

### Types of Materials:

- Architectural drawings
- Drawings
- Manuscripts

Names:

Arts and Industries Building (Washington, D.C.)  
Chesapeake Bay Center for Environmental Studies  
Cooper-Hewitt Museum  
Freer Gallery of Art  
Hirshhorn Museum and Sculpture Garden  
National Air and Space Museum (U.S.)  
National Air and Space Museum (U.S.). Silver Hill Facility  
National Museum of American Art (U.S.)  
National Museum of American History (U.S.)  
National Museum of Natural History (U.S.)  
National Portrait Gallery (Smithsonian Institution)  
Smithsonian Environmental Research Center  
Smithsonian Institution Building (Washington, D.C.)  
Smithsonian Institution. Museum Support Center  
Smithsonian buildings

---

## Container Listing

Box 1	
	National Museum of Natural History Summary: National Museum of Natural History
Box 1 of 19	8431124, Browsers to Grazers
Box 1 of 19	8431125, New Secretary's Office (3 folders)
Box 1 of 19	8431126, Kalwall Window Treatment
Box 1 of 19	8431127, Film Archives Design (HVAC)
Box 1 of 19	8431128, Hall 22 Renovation
Box 1 of 19	8431129, Revised #k726B date 1A, 3/28/1984
Box 1 of 19	8431134, Views of a Vanishing Frontier
Box 1 of 19	8531101, Renovation Learning Center
Box 1 of 19	8531104, Window Modification Baird Projection Booth
Box 1 of 19	8531105, Refurbishment of Lunar Hall 1-20
	Smithsonian Institution Building Summary: Smithsonian Institution Building
Box 1 of 19	7832107, Replacement Gutter Smithsonian Institution Building (3 folders)
Box 1 of 19	7932109, Handicapped Modification Smithsonian Institution Building (2 folders)
Box 1 of 19	8132103, Fire Protection/Alarm Specification, Smithsonian Institution Building (2 folders)
Box 2	
	Arts & Industries Building Summary: Arts & Industries Building
Box 2 of 19	8133111, Computer Equipment Halon System
Box 2 of 19	8033101, Arts & Industries Building Exterior (5 folders)
Box 2 of 19	8133111, Modification of Halon Fire Extinguishing System

Box 2 of 19 8233101, Arts & Industries Building Painting

General Files  
Summary: General Files

Box 2 of 19 Selection Criteria - Evaluations

Box 3

Box 3 of 19 FY 1978 Repair and Renovation (R&R) Backup Information

Box 3 of 19 FY 1974 Financial Reports

Box 3 of 19 FY 1975 R&R Backup Information

Box 3 of 19 FY 1979 R&R of Building Account

Box 3 of 19 FY 1980 R&R General Repairs and Improvements

Box 3 of 19 Statement of R&R Obligations

Box 3 of 19 Project Status Report

Box 3 of 19 FY 1977 Allotments

Box 3 of 19 Oversight Hearings

Box 3 of 19 FY 1978 R&R Account Programming (2 folders)

Box 4

Box 4 of 19 Beta Videocassette - Smithsonian (old storm sewer)

Arts & Industries Building  
Summary: Arts & Industries Building

Box 4 of 19 7533243, East Garden (3 folders)

Box 4 of 19 8433114, Funds for R&R Work in Office of Personnel Administration (OpersA)

Box 4 of 19 8433111, Environmental Controls for Room 2370

Box 4 of 19 8433112, Identifying Ceiling Plenum Areas - Arts & Industries Building

Box 4 of 19 8433110, Office of Membership and Development (OMD) Renovation - Arts & Industries Building

Box 4 of 19	8433109, Office Modification
Box 4 of 19	8433103, Arts & Industries Building Phase 990-3
Box 4 of 19	8433102, Arts & Industries Building Restroom Improvements
Box 4 of 19	8333129, Construction Work in Office of General Counsel
Box 4 of 19	8333126, Relocation due to Arts & Industries Building Exterior Repair
Box 4 of 19	8333123, Paint Plan at Northeast Pavilion
Box 4 of 19	8333122, Valley Repairs Arts & Industries Building
Box 4 of 19	8333121, Fire Detection, Alarm Equipment and Air Conditioning Interlocks
Box 4 of 19	8333120, Storm Sewer Replacement (2 folders)
Box 4 of 19	8333119, Modifications to Office Space Third Floor Northwest Pavilion
Box 4 of 19	8333118, Replace Door
Box 4 of 19	8333117, Smithsonian Magazine Space Plan Change Order
Box 4 of 19	8333116, Toilet Rehab. First Floor Southeast Pavilion
Box 4 of 19	8333115, Exhaust System for Emergency Generator Arts & Industries Building
Box 4 of 19	8333114, HVAC Requirements for Room 2370, 2301, 3301, 309 and 2305
Box 4 of 19	8333113, Room 2261 HVAC Arts & Industries Building
Box 4 of 19	8333112, Air Conditioning Rooms 1313 through 1321 Arts & Industries Building
Box 4 of 19	8333111, Personnel Office Modifications Arts & Industries Building
Box 4 of 19	8333110, Exhibit Halls Smoke Detection - Arts & Industries Building (2 folders)
Box 4 of 19	8333109, Relocation of Resident Associates Program (RAP) Classroom
Box 4 of 19	8333108, TV and Studio - National Museum of American History
Box 4 of 19	8333107, Smithsonian Magazine Space Plan

- Box 4 of 19 8233107, Arts & Industries Building Smoke Detection
- Box 4 of 19 8233108, Cold Storage Facilities for Photographic Materials - Museum Support Center (MSC) and Arts & Industries Building
- Box 4 of 19 8233109, Relocation of RAP Classroom
- Box 4 of 19 8233110, R&R Appropriation FY 1983 Budget Allocation
- Box 4 of 19 8333103, Schedule for Exterior Repairs Phase II and III
- Box 4 of 19 8333105, Handicapped Ramps/North Entrance
- Box 4 of 19 8333104, Drawings
- Box 4 of 19 8333106, Office of Protection Services (OPS) Modification Arts & Industries Building (2 folders)
- Box 4 of 19 8333107, Arts & Industries Building Smithsonian Magazine (2 folders)

Box 5

Smithsonian Institution Building  
Summary: Smithsonian Institution Building

- Box 5 of 19 7932105, Woodrow Wilson Center for International Scholars Fourth Floor Modification (4 folders)

National Museum of Natural History  
Summary: National Museum of Natural History

- Box 5 of 19 7531110, West Court (3 folders)

- Box 5 of 19 7531102, Osteoprep Lab (2 folders)

Silver Hill Facility  
Summary: Silver Hill Facility

- Box 5 of 19 8238101, Renovation of Buildings 15, 16, 18 (4 folders)

Box 6

National Museum of American History  
Summary: National Museum of American History

- Box 6 of 19 8030125, New Bookstore Layout (4 folders)

Box 7



	National Museum of Natural History Summary: National Museum of Natural History
Box 7 of 19	8031115, National Museum of Natural History (NMNH) Paleo Hall, Phase III (2 folders)
	National Museum of American History Summary: National Museum of American History
Box 7 of 19	8030102, Lighting Hall (2 folders)
	National Museum of Natural History Summary: National Museum of Natural History
Box 7 of 19	7931114, Smithsonian Institution Library Phase I - Natural History Building (NHB) (4 folders)
Box 7 of 19	7731112, Inspection of Packed Towers
Box 7 of 19	7531102, Conservation Analytical Lab (CAL) and Paint Shop Ventilation Systems (4 folders)
	National Museum of American History Summary: National Museum of American History
Box 7 of 19	8430119, Office of Printing and Photographic Services (OPPS) Cold Room Flood Barrier/National Museum of American History
Box 7 of 19	8530102, Trees of Christmas
Box 7 of 19	8530101, Nimlock Panel System for Exhibit in National Museum of American History
Box 7 of 19	8430129, Health Unit Air Handler
Box 7 of 19	8430126, Eleanor Roosevelt Exhibit (2 folders)
Box 7 of 19	8430125, Installation of 14 Workstation Coaxial Cables - National Museum of American History
Box 7 of 19	8430124, NCR Electrical Installation (Ice Cream Parlor)
Box 7 of 19	8430123, Library Shelf Stabilization - National Museum of American History
Box 7 of 19	8430114, Philatelic Environmental Study - National Museum of American History
Box 7 of 19	8430109, Renovation of the Former Hall of Minerals (2 folders)

Box 7 of 19                      8430132, Security Barrier Room 4007 - National Museum of American History

Box 8

National Museum of Natural History  
Summary:            National Museum of Natural History

Box 8 of 19                      8331131, Art of Cameroons

Box 8 of 19                      8331132, Scanning Election Microscopes

Box 8 of 19                      8331133, Precious Legacy

Box 8 of 19                      8331138, Wethersfield Meteorites

Box 8 of 19                      8331139, I-Beam Runner for Chain Hoist

Box 8 of 19                      8331144, Smithsonian Institution Library Mezzanine Sound Abatement

Box 8 of 19                      8331145, Handrail for the Coal Swamp Exhibit/National Museum of Natural History

Box 8 of 19                      8431103, Renovation to the Secretary Research Laboratory

Box 8 of 19                      8431108, Pedestal for the Petrified Wood and Banded Iron

Box 8 of 19                      8431111, Smithsonian Institution Bibliographic Information System (SIBIS) Computer Room Construction

Box 8 of 19                      8431112, India Photos Exhibit (2 folders)

Box 8 of 19                      8431114, MMB Modification/Natural History Building

Box 8 of 19                      8431115, Naturalist Center Modifications

Box 8 of 19                      8431119, Trilobite Exhibit

Box 8 of 19                      8431123, Waldo Schmitt Conference Room

Box 8 of 19                      8331120, Schmitt Conference Room Interiors

Box 8 of 19                      8331130, Installation and Dismantling (2 folders)

Box 8 of 19                      8331129, Treasure from the Shanghai Museum (lighting)

Box 8 of 19                      8331128, Israeli Archaeology: The Holy Land

Box 8 of 19	8331127, Office Space for Supervisors
Box 8 of 19	8331125, Koaba Diorama Exhibit/National Museum of Natural History
Box 8 of 19	8331123, Sprinkler System East Wing Fifth Floor (2 folders)
Box 8 of 19	8331118, The Heritage of Islam Exhibit/National Museum of Natural History
Box 8 of 19	8331117, Storage Deck/Office of Plant Services (OplantS) Electric Shop
Box 8 of 19	8331116, Patch and Seal Parking Lot/National Museum of Natural History
Box 8 of 19	8331115, Battery Storage and Charging Room/National Museum of Natural History
Box 8 of 19	8331114, Sidewalk Repair
Box 8 of 19	8331113, SIBIS Computer Room/National Museum of Natural History (2 folders)
Box 8 of 19	8331111, Change Order (2 folders)
Box 8 of 19	8331109, East Court Greenhouse Heating Improvements
Box 8 of 19	8331106, Sawdust Collection and Electrical Renovation
Box 8 of 19	8331105, National Museum of Natural History Handicapped Restrooms (2 folders)
Box 8 of 19	8331101, Fire Protection, Phase VII (2 folders)
Box 8 of 19	8231130, Japanese Ceramics Project Exhibition
Box 8 of 19	8231129, Japanese Ceramics Project Submittal
Box 8 of 19	8231127, Laboratory Facilities for Department of Botany
Box 8 of 19	8231124, Attic Areas to Office Space
Box 8 of 19	8231123, Relocation of Junction Box (2 folders)
Box 8 of 19	8231121, Northwest Coast Masks Case (2 folders)
Box 8 of 19	8231118, Contract for Lobby Floor Covering, National Museum of Natural History North Portal (2 folders)

Box 9

Arts & Industries Building  
Summary: Arts & Industries Building

Box 9 of 19	8233103, Exterior Restoration of Arts and Industries Building (6 folders)
Box 9 of 19	8233104, Fire Detection and Supression
Box 10	
Box 10 of 19	8033101, Emergency Roof Repairs (2 folders)
Box 10 of 19	8133101, Retrofit Program (2 folders)
Box 10 of 19	8133103, Environmental Control and Emergency Conservation Study (5 folders)
Box 10 of 19	8233101, Interior Painting and Repair
Box 10 of 19	8233102, Space Utilization Study (2 folders)
Box 10 of 19	Estimate - Phase I (Exterior Restoration of the A&I Building Record Copy)
Box 10 of 19	Specification - Exterior Restoration of A&I Building (record set - McGaughy, Marshall and McMillan)
Box 10 of 19	Preliminary Survey Report A&I Building Roof and Facade Rehabilitation

Box 11

National Museum of Natural History Summary: National Museum of Natural History	
Box 11 of 19	8031118, Special Exhibits Hall
Box 11 of 19	8031117, Fire Protection Phase V (3 folders)
Box 11 of 19	8131137, Exhibits Lab Wall - National Museum of Natural History
Box 11 of 19	8131123, Fire Protection Phase VI
Box 11 of 19	8131117, R&R Update
Box 11 of 19	8131116, Fourth Floor Restroom Alterations
Box 11 of 19	8031118, Fabrication and Installation of Work Platforms (3 folders)
Box 11 of 19	8231105, National Museum of Natural History Window Repairs
Box 11 of 19	8231102, Exterior Window Repairs, East and West Wings

Box 12

Arts & Industries Building  
Summary: Arts & Industries Building

Box 12 of 19 7533243, Specifications for East and Sensory Garden (5 folders)

Smithsonian Institution Building  
Summary: Smithsonian Institution Building

Box 12 of 19 8532104, Visitors Information and Associates Reception Center (VIARC)  
Space Planning

Box 12 of 19 8432123, Communications Raceway (2 folders)

Box 12 of 19 8432122, Installation of TV Antenna (2 folders)

Box 12 of 19 8432121, Traditional Architecture of Saudi Arabia

Box 12 of 19 8432119, Miscellaneous Renovations Phase I/Smithsonian Institution  
Building

Box 12 of 19 8432112, New East Garden

Box 12 of 19 8432111, Convert Restroom to Laundry

Box 12 of 19 8432110, Boiler Room

Box 12 of 19 8432109, Smithsonian Institution Building Smoke Detection Electrical  
Wiring Renovation

Box 12 of 19 8432106, Oman Exhibition

Box 12 of 19 8332116, Installation of Herman Miller Furniture

Box 12 of 19 8332115, Ceiling Inspection Room 1495

Box 12 of 19 8332113, Proprietary Security System

Box 12 of 19 8332112, Cleaning and Repairs of Facade

Box 12 of 19 8332111, Churchill Exhibit

Box 12 of 19 8332110, Floor Plan for Commons and Lounge Area

Box 12 of 19 8332105, Copier Room Renovations

Box 12 of 19 8332102, Cable Plan for Smithsonian Institution Building

Box 12 of 19	8332101, Smithsonian Institution Building Smoke Detection
Box 12 of 19	8232119, Renovation of APSE Roof
Box 12 of 19	8232118, Cabinet Units (3)
Box 12 of 19	8232117, Invoice Work Order #16
Box 12 of 19	8232114, Office of Programming and Budget Space Plan
Box 12 of 19	8232107, Smithsonian Institution Building South Portal Doors and Tympan Replication
Box 12 of 19	8232106, East Lobby Vestibule, Smithsonian Institution Building
Box 12 of 19	8232104, Smoke Detection
Box 12 of 19	8232103, Renumbering of Existing Smoke Detection
Box 12 of 19	8232102, Cable Plan for Smithsonian Institution Building
Box 13	
National Museum of American History Summary: National Museum of American History	
Box 13 of 19	8030125, Basement Demolition for Bookstore - National Museum of American History
Box 13 of 19	8130129 and 8030139, Ice Cream Parlor - National Museum of American History
Box 13 of 19	8230137, Transformer Replacement
Box 13 of 19	8230116, Cafeteria Drain Lines - National Museum of American History
National Museum of Natural History Summary: National Museum of Natural History	
Box 13 of 19	8231117, Rotunda Wall System - National Museum of Natural History
Box 13 of 19	8331118, Evans Gallery Floor
Box 13 of 19	8331133, Precious Legacy Exhibit - National Museum of Natural History
Smithsonian Institution Building Summary: Smithsonian Institution Building	
Box 13 of 19	8232119, West APSE Roof, Smithsonian Institution Building

Box 13 of 19	8332101, Smoke Detection and Wiring Renovation
Box 13 of 19	8332113, Computer Room A/E - B-30 - Smithsonian Institution Building
	Arts & Industries Building Summary: Arts & Industries Building
Box 13 of 19	8333119, Modification to Office Space, Third Floor
	American Art and Portrait Gallery Building Summary: American Art and Portrait Gallery Building
Box 13 of 19	8334102, Basement Fire Sprinkler System Extension (AAPG)
	National Air and Space Museum Summary: National Air and Space Museum
Box 13 of 19	8135129, Sewage Ejector Room P-721 - National Air and Space Museum
Box 13 of 19	8135146, Spacearium Air Filtration - National Air and Space Museum
Box 13 of 19	8335113, Outdoor Special Event Sign - National Air and Space Museum
	Arts & Industries Building Summary: Arts & Industries Building
Box 13 of 19	8333519, Gift Shops/Spacearium Theatre - National Air and Space Museum
	Silver Hill Facility Summary: Silver Hill Facility
Box 13 of 19	8238104, Fire Protection Building 8, 9, 11, Paul Garber
Box 13 of 19	8238106, Water - See page 20
	Museum Support Center Summary: Museum Support Center
Box 13 of 19	8239113, Waste Disposal
	Silver Hill Facility Summary: Silver Hill Facility
Box 13 of 19	8238210, Drainage Improvements
Box 13 of 19	8238121, Insulation of Building 20
	Box 14

Box 14 of 19	8138115, Paint Buildings 1, 1A, 2, 3, 4, 5 and 6 - Silver Hill
Box 14 of 19	8138119, Exterior Repainting Building 15 - Silver Hill
Box 14 of 19	8138123, Insulation of Building 21 - Paul Garber
	Smithsonian Environmental Research Center (formerly Chesapeake Bay Center for Environmental Studies) Summary: Smithsonian Environmental Research Center (formerly Chesapeake Bay Center for Environmental Studies)
Box 14 of 19	7844101, Maintenance Building (2 folders) - Chesapeake Bay Center for Environmental Studies (CBCES)
Box 14 of 19	8044102 and 8044104, Fire Detection and Alarm Systems - CBCES (4 folders)
Box 14 of 19	8044108, Miscellaneous Modifications
	Hirshhorn Museum and Sculpture Garden Summary: Hirshhorn Museum and Sculpture Garden
Box 14 of 19	7645406, Handicapped Ramps - Hirshhorn Museum and Sculpture Garden (HMSG) (3 folders)
	Cooper-Hewitt Museum Summary: Cooper-Hewitt Museum
Box 14 of 19	7948112, Guard Station
Box 14 of 19	8048102, Window Restoration Exterior - Cooper-Hewitt
Box 14 of 19	8048123, Woodmarking Shop and Cellar - Cooper-Hewitt
	Museum Support Center Summary: Museum Support Center
Box 14 of 19	7939050, Hirshhorn Repairs
	Box 15
	American Art and Portrait Gallery Building Summary: American Art and Portrait Gallery Building
Box 15 of 19	7534209, East Portico - Fine Arts and Portrait Gallery
Box 15 of 19	8034103, Facade Repair - Fine Arts and Portrait Gallery (3 folders)



	National Air and Space Museum Summary: National Air and Space Museum
Box 15 of 19	8035101, Stairs #5, #6 - National Air and Space Museum (3 folders)
	Freer Gallery of Art Summary: Freer Gallery of Art
Box 15 of 19	8037118, Roof Repair West Freer Gallery
	Silver Hill Facility Summary: Silver Hill Facility
Box 15 of 19	7538206, Storm Drainage and Sanitary Sewer - Silver Hill (4 folders)
Box 15 of 19	8038101, Additional Fire Protection - Silver Hill (4 folders)
Box 15 of 19	8038110, Repair Sewer Line
Box 15 of 19	8038112, Renovation of Building 18 - Silver Hill (2 folders)
Box 15 of 19	8038113, Storm Water Management - Silver Hill
	General Files Summary: General Files
Box 15 of 19	Specifications for Restoration of A&I Building, 1973
Box 15 of 19	Specifications for Restoration of Masonry at the Renwick
	Box 16
	American Art and Portrait Gallery Building Summary: American Art and Portrait Gallery Building
Box 16 of 19	8034106, Replacement of Transformer and Network - American Art and Portrait Gallery (3 folders)
Box 16 of 19	8034136, Asbestos Removal - American Art and Portrait Gallery (5 folders)
Box 16 of 19	8134106, New Roofing/Raking and Paint Chimney and Stone - American Art and Portrait Gallery
Box 16 of 19	8134107, Facade Repair, Northwest - American Art and Portrait Gallery
Box 16 of 19	8134113, Construction of an Office in the Garage Area - American Art and Portrait Gallery

Box 16 of 19	8234102, Column Study - American Art and Portrait Gallery
Box 16 of 19	8234103, Rake Joints and Repoint - American Art and Portrait Gallery (2 folders)
Box 16 of 19	8234120, Asbestos Containment - American Art and Portrait Gallery (2 folders)
Box 16 of 19	8234125, Fair Coil Unit Room 175 - American Art and Portrait Gallery
Box 16 of 19	8334119, Museum Shop Alterations - American Art and Portrait Gallery

Box 17

	National Museum of American History Summary: National Museum of American History
Box 17 of 19	8130102, Toilet Room Modifications for Handicapped
Box 17 of 19	8130129, Ice Cream Parlor Modifications (2 folders)
Box 17 of 19	8130134, George Washington Exhibit Hall (2 folders)
Box 17 of 19	8130143, New Exhibits Offices PDA
Box 17 of 19	8130147, Office of Printing and Photographic Services (OPPS) Handicapped Door (2 folders)
Box 17 of 19	8130151, Archive Storage and Offices - Third Floor
Box 17 of 19	8230103, Fire Protection Phase II (2 folders)
Box 17 of 19	8230108, Study Service Entrance Conditions
Box 17 of 19	8230109, Basement Water Intrusion Study
Box 17 of 19	8230110, Phat Library Modifications (2 folders)
Box 17 of 19	8230111, OPPS Studio Modifications
Box 17 of 19	8230112, Temporary Offices of Public Affairs
Box 17 of 19	8230113, Modifications of HVAC System Flag Hall
Box 17 of 19	8230114, Terrace Drain Repair (2 folders)
Box 17 of 19	8230117, Sidewalk Repairs

Box 17 of 19	8230118, Fumigation Chamber Ventilation Improvements
Box 17 of 19	8230121, Garage Exhaust Duct Changes
Box 17 of 19	8230124, Emergency Chiller Replacement (2 folders)
Box 17 of 19	8230128, Atomic Clock Exhibit
Box 18	
Box 18 of 19	8330115, Flag Hall Lighting - Phase II (2 folders). Also investigation of an injury to visitor in Flag Hall.
Box 18 of 19	8330116, Drain Lines Soda Dispensers (basement)
Box 18 of 19	8330117, "Workers World" Exhibit
Box 18 of 19	8330118, "Old Glory Case Move"
Box 18 of 19	8330120, Room 5707A Heater and Fan Installation
Box 18 of 19	8330124, Fire Protection, Phase IIA
Box 18 of 19	8330125, Doubleday Lecture Pendulum Platform
Box 18 of 19	8330126, Temporary Vestibule Doors, Cafeteria
Box 18 of 19	8330128, "Pain" Exhibit
Box 18 of 19	8330127, Barrier Room 40105A, Philately
Box 18 of 19	8330131, M*A*S*H* Exhibit
Box 18 of 19	8330132, Convert Room B3034 to Offices and Conference
Box 18 of 19	8330133, "Pain" Exhibit and New Service Area
Box 18 of 19	8330135, Floor Plans Buildings 15, 16, 17, 18 and 19 - Silver Hill
Box 18 of 19	8330137, Transformer Replacement (2 folders)
Box 18 of 19	8330138, New Movie Screen for Carmichael Auditorium
Box 18 of 19	8330142, Renovation Elevation Cabinets 3 and 4
Box 18 of 19	8330144, "Standard Time" Exhibit
Box 18 of 19	8330145, Computer Service Office - Northwest Corner

Box 18 of 19	8330146, Cafeteria Automated Vestibule Doors
Box 18 of 19	8330149, Conversion of Room AB039 - Division of Performing Arts (DPA) Temporary Offices
Box 18 of 19	8330150, Conversion of Room BB018 - Division of Performing Arts (DPA) Temporary Offices
Box 18 of 19	8330151, Film Storage A/C Unit Room CB041 (2 folders)
Box 18 of 19	8330152, M*A*S*H* Sales Booth
Box 18 of 19	8330153, National Heritage Award Exhibit
Box 18 of 19	8330154, Fume Hood Vent Silk Screen Room
Box 18 of 19	8330155, Lektriever Relocation
Box 18 of 19	8330156, Rooms AB052/AB052A Kardex Lektriever (2 folders)
Box 18 of 19	8330158, "Waldseemuller Map" Exhibit
Box 18 of 19	8330160, Calder Relocation Foundation
Box 18 of 19	8330161, Bandstand/Pool Foundation
Box 18 of 19	8430101, Temporary Offices, Iron and Steel Hall
Box 18 of 19	8430103, "Trees of Christmas"
Box 18 of 19	8430106, Radio Smithsonian (2 folders)
Box 18 of 19	8430107, Discover Graphics
Box 18 of 19	8430108, Temporary A/V Control Room
Box 19	
Box 19 of 19	7930101 and 8030126, Fire Protection Master Plan
Box 19 of 19	8130102, Toilet Modifications Handicapped
Box 19 of 19	8230104, Environmental Control and Energy Conservation Study
Box 19 of 19	8230106, Terrace Retain, Phase V (2 folders)
Box 19 of 19	8130114, 12 AHO - Replacement (5 folders)

Box 19 of 19

8130117, Reheat Coils (2 folders)