

Project Files and Drawings, 1982-1996

Finding aid prepared by Smithsonian Institution Archives

Smithsonian Institution Archives Washington, D.C. Contact us at osiaref@si.edu

Table of Contents

Collection Overview	1
Administrative Information	1
Descriptive Entry	1
Names and Subjects	1
Container Listing	3

Repository:	Smithsonian Institution Archives, Washington, D.C., osiaref@si.edu
Title:	Project Files and Drawings
Date:	1982-1996
Identifier:	Accession 98-130
Creator::	Smithsonian Institution. Office of Physical Plant
Extent:	58 cu. ft. (58 record storage boxes) (3 oversize folders)
Language:	English

Collection Overview

Administrative Information

Prefered Citation

Smithsonian Institution Archives, Accession 98-130, Smithsonian Institution. Office of Physical Plant, Project Files and Drawings

Descriptive Entry

This accession consists of project files for renovation and reconstruction activities of the Office of Physical Plant, including memoranda, correspondence, photographs, blueprints and drawings, and other materials pertaining to each project. Box listings show Project Number, Project Name, and Facility.

Museums, buildings and events documented in this collection include: the National Air and Space Museum, the Cooper-Hewitt Museum, the Paul Garber Facility, the National Museum of American History, the National Museum of American Art, the National Portrait Gallery, the Quadrangle Building, the National Museum of Natural History, the Renwick Gallery, the Museum Support Center, the Hirshhorn Museum and Sculpture Garden, the Arts and Industries Building, the National Museum of African Art, the Folklife Festival, the National Museum of the American Indian, the Arthur M. Sackler Gallery, the Smithsonian Institution Building, the Anacostia Neighborhood Museum, the Smithsonian Environmental Research Center, the Freer Gallery of Art, the National Mall, L'Enfant Plaza offices, the Smithsonian Astrophysical Observatory, and miscellaneous locations.

Names and Subject Terms

This collection is indexed in the online catalog of the Smithsonian Institution under the following terms:

Subjects:

Architectural design Buildings -- Maintenance Buildings -- Repair and reconstruction Museum buildings Smithsonian buildings Types of Materials:

Architectural drawings Black-and-white photographs Color photographs Drawings Manuscripts

Names:

Anacostia Neighborhood Museum Arthur M. Sackler Gallery (Smithsonian Institution) Arts and Industries Building (Washington, D.C.) **Cooper-Hewitt Museum** Freer Gallery of Art Hirshhorn Museum and Sculpture Garden L'Enfant Plaza (Washington, D.C.) National Air and Space Museum (U.S.) National Air and Space Museum (U.S.). Paul E. Garber Preservation, Restoration, and Storage Facility National Museum of African Art (U.S.) National Museum of American Art (U.S.) National Museum of American History (U.S.) National Museum of Natural History (U.S.) National Museum of the American Indian (U.S.) National Portrait Gallery (Smithsonian Institution) Quadrangle Building (Washington, D.C.) **Renwick Gallery** Smithsonian Astrophysical Observatory Smithsonian Environmental Research Center Smithsonian Folklife Festival Smithsonian Institution Building (Washington, D.C.) Smithsonian Institution. Museum Support Center

Places:

Mall, The (Washington, D.C.)

	Box 1
Box 1 of 62	913507B, First and Third Floor Ceiling Replacement, National Air and Space Museum (NASM)
	Box 2
Box 2 of 62	913507A, Snow Melter Repairs, NASM
	Box 3
Box 3 of 62	8748105, Handicapped Accessibility Implementation Phase III, Cooper- Hewitt Museum (CHM)
Box 3 of 62	933814, Decontamination of Collections, Paul Garber Facility (PGF)
Box 3 of 62	933814, Asbestos Abatement, PGF
Box 3 of 62	917003 (Miscellaneous Locations)
	Box 4
Box 4 of 62	8748119, Fire Protection Improvements, CHM
	Box 5
Box 5 of 62	883021, Radio Smithsonian: Control Room Modifications, National Museum of American History (NMAH)
Box 5 of 62 Box 5 of 62	
	Museum of American History (NMAH) 923421, National Museum of American Art/National Portrait Gallery
Box 5 of 62	Museum of American History (NMAH) 923421, National Museum of American Art/National Portrait Gallery (AAPG)
Box 5 of 62 Box 5 of 62	Museum of American History (NMAH) 923421, National Museum of American Art/National Portrait Gallery (AAPG) 917003 (Miscellaneous Locations)
Box 5 of 62 Box 5 of 62 Box 5 of 62	Museum of American History (NMAH) 923421, National Museum of American Art/National Portrait Gallery (AAPG) 917003 (Miscellaneous Locations) 906310, Quadrangle Building Leaks , Quad
Box 5 of 62 Box 5 of 62 Box 5 of 62 Box 5 of 62	Museum of American History (NMAH)923421, National Museum of American Art/National Portrait Gallery (AAPG)917003 (Miscellaneous Locations)906310, Quadrangle Building Leaks , Quad923005, Science Museum Shop, NMAH923105, Library Security Door, National Museum of Natural History
Box 5 of 62 Box 5 of 62 Box 5 of 62 Box 5 of 62 Box 5 of 62	Museum of American History (NMAH)923421, National Museum of American Art/National Portrait Gallery (AAPG)917003 (Miscellaneous Locations)906310, Quadrangle Building Leaks , Quad923005, Science Museum Shop, NMAH923105, Library Security Door, National Museum of Natural History (NMNH)
Box 5 of 62 Box 5 of 62 Box 5 of 62 Box 5 of 62 Box 5 of 62	Museum of American History (NMAH)923421, National Museum of American Art/National Portrait Gallery (AAPG)917003 (Miscellaneous Locations)906310, Quadrangle Building Leaks , Quad923005, Science Museum Shop, NMAH923105, Library Security Door, National Museum of Natural History (NMNH)943112, Replace Main Steam Station, NMNH

Container Listing

Box 6 of 62	943603, ACM Floor Tile Removal, Renwick Gallery of Art (RGA)
Box 6 of 62	893605, Upgrade Electrical Service, RGA
Box 6 of 62	923003, Roof Terrace Railing, NMAH
Box 6 of 62	913005, Dibner Library Renovation, NMAH
Box 6 of 62	903017, American Encounters Entrance Hallway, NMAH
	Box 7
Box 7 of 62	897106, Door Replacement Pod 4, Museum Support Center (MSC)
Box 7 of 62	897106, Door Replacement Pod 4, MSC
Box 7 of 62	913509, Secondary Power Distribution, NASM
Box 7 of 62	923010, Conservation Laboratory, NMAH
Box 7 of 62	923105, Library Security Door, NMNH
Box 7 of 62	933114, Asbestos Removal: West Attic and NW, NMNH
Box 7 of 62	934512, Auditorium Asbestos Tile Removal, Hirshhorn Museum and Sculpture Garden (HMSG)
	Box 8
Box 8 of 62	906310, Quadrangle Building Leaks, Quad
Box 8 of 62	923005, Science Museum Shop, NMAH
Box 8 of 62	933303, Roof, Skylights, and Roof Repairs, Arts and Industries Building (AIB)
	Box 9
Box 9 of 62	893113, Chiller Plant Relocation: Correspondence September 1991-April 1992, NMNH
	Box 10
Box 10 of 62	893113, Chiller Plant Relocation: Correspondence: May 1992-October 1992, NMNH
	Box 11

Box 11 of 62	893113, Chiller Plant Relocation: Correspondence: November 1992- January 1995, NMNH
	Box 12
Box 12 of 62	Contract File
Box 12 of 62	SI Construction estimate and SI Technical Proposal Evaluation Format
Box 12 of 62	Hyman Tech. Proposal
Box 12 of 62	Applicatons for Payment
Box 12 of 62	Pay Request Draft Files
Box 12 of 62	Preconstruction Meeting Minutes
Box 12 of 62	Monthly Project Report, 12/1991-3/1993
Box 12 of 62	Progress Meeting Minutes, 6/1992-2/1993
Box 12 of 62	Progress Meeting Minutes, 9/1991-5/1992
Box 12 of 62	Pepco File
Box 12 of 62	893113, Chiller Plant Relocation: Contractor, Pepco, Change Orders (1-35), NMNH
	Box 13
Box 13 of 62	893113, Chiller Plant Relocation: Change Orders (36-95), NMNH
Box 13 of 62	RFI 1-206 Log-In Sheets
Box 13 of 62	RFI 206-141
Box 13 of 62	RFI 141-91
Box 13 of 62	RFI 90-41
Box 13 of 62	RFI 40-1
Box 13 of 62	Sketch Log
	Box 14
Box 14 of 62	893113, Chiller Plant Relocation: Contract Modifications (1-14), NMNH

	Box 15
Box 15 of 62	893113, Chiller Plant Relocation: Submittals (01000 - 02975), NMNH
	Box 16
Box 16 of 62	893113, Chiller Plant Relocation: Submittals (03300 - 15250), NMNH
	Box 17
Box 17 of 62	893113, Chiller Plant Relocation: Submittals (15400 - 16400), NMNH
	Box 18
Box 18 of 62	893113, Chiller Plant Relocation: Submittals (16428 - 16950), NMNH
	Box 19
Box 19 of 62	893113, Chiller Plant Relocation: O & M Manuals, NMNH
Box 19 of 62	893113, Chiller Plant Relocation: Electrical Manuals, NMNH
	Box 20
Box 20 of 62	893113, Chiller Plant Relocation: Progress Photographs, O & M Manual, NMNH
	Box 21
Box 21 of 62	[Does not exist - contents are merged into other boxes.]
	Box 22
Box 22 of 62	893113, Chiller Plant Relocation: Hill Inspections; ATEC Reports, NMNH
	Box 23
Box 23 of 62	893113, Chiller Plant Relocation: Hyman Daily Reports: 9/30/1990-11/16/1992, NMNH
	Box 24
Box 24 of 62	893113, Chiller Plant Relocation: Certified Payrolls: 9/1991-2/1993, NMNH
	Box 25
Box 25 of 62	883123, Executive Conference Room, NMNH Notes: • Contract File

	 Progress Meeting Minutes File Pay Requests File Incoming Correspondence: August 1992-January 1995 Outgoing Correspondence: August 1992-January 1995
	Box 26
Box 26 of 62	 883123, Executive Conference Room, NMNH Notes: Modifications (1-5) Change Orders (1-37) Daily Reports Operation and Maintenance Manuals. (Volume 1 and 2) Certified Payrolls
	Box 27
Box 27 of 62	 883123, Executive Conference Room, NMNH Notes: Submittals (00800-16728) Request for Information (1-2)
	Box 28
Box 28 of 62	903116, East and West Penthouse Roof and Window Replacement, NMNH Notes: • General File • Modifications (2-12) • Payment Requests (11-33)
	Box 29
Box 29 of 62	903116, East and West Penthouse Roof and Window Replacement, NMNH Notes: Correspondence: 11/18/1992-2/25/1993 Correspondence: 2/26/1993-5/28/1993 Correspondence: 6/1/1993-9/20/1993
	Box 30
Box 30 of 62	903116, East and West Penthouse Roof and Window Replacement, NMNH Notes: Correspondence: 9/21/1993-4/20/1994 Correspondence: 4/21/1994-9/2/1994 Correspondence: 9/6/1994-6/31/1995
	Box 31
Box 31 of 62	903116, East and West Penthouse Roof and Window Replacement, NMNH

	Notes:Correspondence: 2/1/1995-5/14/1996• Requests for Information (1-68)• Window Exterior Punch List• Critical Path Schedule• Technical Proposal
	Box 32
Box 32 of 62	903116, East and West Penthouse Roof And Window Replacement, NMNH Notes: • Change Orders (46-81) • Submittals (01000-07260)
	Box 33
Box 33 of 62	903116, East and West Penthouse Roof And Window Replacement, NMNH Notes: • Submittals (07420-16727)
	Box 34
Box 34 of 62	 903116, East and West Penthouse Roof And Window Replacement, NMNH Notes: Window Identification Daily Work Orders (Beta Construction Company) Daily Logs (Beta Construction Company) Daily Logs (Grunley Construction Company)
	Box 35
Box 35 of 62	903116, East and West Penthouse Roof and Window Replacement, NMNH Notes: • Contractor Certified Payrolls (1-18)
	Box 36
Box 36 of 62	[Does not exist - contents are merged into other boxes.]
	Box 37
Box 37 of 62	913012, HVAC Master Implementation Phase IV-B, NMNH
	Box 38
Box 38 of 62	913012, HVAC Master Implementation Phase IV-B, NMNH
	Box 39
Box 39 of 62	913012, HVAC Master Implementation Phase IV-B, NMNH

Box 40 of 62 923118, Data Cable and Raceway System, NMNH Box 41 Box 41 Box 41 of 62 923118, Data Cable and Raceway System, NMNH
Box 41 of 62 923118, Data Cable and Raceway System, NMNH
Box 41 of 62 943135, East Attic Asbestos Removal, NMNH
Box 41 of 62 946309, Modern Art Exhibit, National Museum of African Art (NMAfA)
Box 41 of 62 956303, Pool Repairs, NMAfA
Box 41 of 62 934509, Sculpture Garden Walls, HMSG
Box 41 of 62 956301, Ancient Nubia Exhibit, NMAfA
Box 42
Box 42 of 62 933501, Garage Level Door Controls, NASM
Box 42 of 62 906313, Handicap Access for Lecture Hall Stage, Quad
Box 42 of 62 953502, Water Heater Emergency Replacement, NASM
Box 42 of 62 953008, Pipe Chase Asbestos Abatement, NMAH
Box 42 of 62 957002, 1995 Folklife Festival on the Mall, Mall
Box 42 of 62953306, Steam Drain Cover and Walkway Repair, National Museum of the American Indian (NMAI)
Box 42 of 62 956308, East Galleries, Arthur M. Sackler Gallery (AMSG)
Box 42 of 62 956306, Kerma/Benin Exhibit, NMAfA
Box 42 of 62 944513, Second Floor Asbestos Abatement, AMSG
Box 42 of 62 933814, Building 26 Reconstruction, PGF
Box 43
Box 43 of 62 [Does not exist - contents are merged into other boxes.]
Box 44
Box 44 of 62 883011, Elevator Modifications, NMAH

Box 44 of 62	883018B, Terrace Repairs, NMAH
Box 44 of 62	913002, Data Communications Backbone System, NMAH
Box 44 of 62	913020, Replace Cast Iron Drainage Pipe with PVC, NMAH
Box 44 of 62	913021, P.A. System Repairs, NMAH
Box 44 of 62	923003, Roof Terrace Railing, NMAH
Box 44 of 62	933001, Archives Security CCTV, NMAH
Box 44 of 62	933018, New Designs Offices Fourth Floor, NMNH
	Box 45
Box 45 of 62	913114, East and West Court Ledge Repair, NMNH
Box 45 of 62	893113, Chiller Plant Relocation, NMNH
Box 45 of 62	903116, NMNH
Box 45 of 62	913123, Extend Detection & Fire Suppression System, NMNH
Box 45 of 62	953126, Landscape Kimonos, NMNH
Box 45 of 62	933119, Asbestos Removal-Hall 7, NMNH
Box 45 of 62	933112, Asbestos Removal, NMNH
Box 45 of 62	943116, Hall 7 Fire Protection, NMNH
Box 45 of 62	943135, Asbestos Removal East Attic, NMNH
Box 45 of 62	933107, Asbestos Removal/Reinsulation North Attic, NMNH
	Box 46
Box 46 of 62	932107, Plumbing Repair and Toilet Room Renovations, NMAI
Box 46 of 62	903322, Security Lighting, A&I
Box 46 of 62	8633113, Handicapped Accessibility, A&I
Box 46 of 62	903321, Repainting Walls and Rotunda Walls, A&I
Box 46 of 62	903315, Magnetic Door Hold-Open Devices, A&I

Box 46 of 62	943129, Hall 7 Electrical and Drywall Partitions, NMNH
Box 46 of 62	943111, NMNH
Box 46 of 62	943110, Vertebrae Zoology Darkroom, NMNH
Box 46 of 62	903116, East and West Wing Penthouses, Roof and Window Renovation, NMNH
Box 46 of 62	943127, Main Building Fire Pump, NMNH
Box 46 of 62	954606, Electrical/Mechanical Study and Mods, Anacostia Neighborhood Mueum (ANM)
Box 46 of 62	943112, Replace Main Steam Station, NMNH
Box 46 of 62	943102, Cooling Coil Replacement, NMNH
Box 46 of 62	953204, Exhaust System for Room 336, SIB
Box 46 of 62	943205, Small HVAC Projects / SIB, SIB
Box 46 of 62	943202, Room 309 Ceiling Fans, SIB
Box 46 of 62	943203, Ceiling Fan - Room 318, SIB
Box 46 of 62	953206, Clock Tower Bell, SIB
Box 46 of 62	943130, Chiller Plant Location, NMNH
	Box 47
Box 47 of 62	893413, NPG Education Space Layout, American Art/Portrait Gallery (AAPG)
Box 47 of 62	923421, Walk-in Refrigerator - Patent Pending Restaurant, AAPG
Box 47 of 62	8634142, Fire Protection Phase 3, AAPG
Box 47 of 62	923411, Emergency Repair Apse Roof, AAPG
Box 47 of 62	903418, Fire Alarm and Doors, AAPG
	Box 48
Box 48 of 62	8634140, Window Restoration, AAPG
Box 48 of 62	8636102, Renwick Roof Repairs, RGA

- Box 48 of 62 893604, Fire Detection Phase 2, RGA
- Box 48 of 62 914405, General Repairs Phase 2, SERC
- Box 48 of 62 894410, SERC

Box 49

Box 49 of 62	893506, Electrical Reliability Improvements, NASM
Box 49 of 62	8635108, Plaza Surface Replacement, NASM
Box 49 of 62	913507B, First and Third Ceiling Replacement, NASM

f 62 933501, Garage Level Door Controls, NASM

Box 50

Box 49 of 62

- Box 50 of 62 903506, Fire Protection Phase 6 and 7, NASM
- Box 50 of 62 953502, Water Heater Emergency Replacement, NASM
- Box 50 of 62 953503, OPS Cashroom Modifications, NASM
- Box 50 of 62 933513, New Office Room 3343, NASM
- Box 50 of 62 943525, Exhibits Typesetting Area Room P170, NASM
- Box 50 of 62 933506, Partitions Rooms 3401 and 3402, NASM
- Box 50 of 62 943501, HIIQ Lamp Unit Room 114, NASM
- Box 50 of 62 923519, Modifications To Stairwell Number 5, NASM
- Box 50 of 62 923520, CEPS Electrical Closet Modifications, NASM
- Box 50 of 62 954507, Boardroom Conversion, HMSG
- Box 50 of 62 923522, Fire Protection Improvements, NASM
- Box 50 of 62 954509, Interior Renovation, HMSG
- Box 50 of 62 944508, Hirshhorn Cafe, HMSG
- Box 50 of 62 894503, Fire Protection Improvements, HMSG

Box 51

Box 51 of 62	913701, Roof and Skylights Replacement, Freer Gallery of Art (FGA)
	Box 52
Box 52 of 62	8245104, Plaza Resurfacing and Landscaping, NMNH
Box 52 of 62	934509, Sculpture Garden Walls, HMSG
	Box 53
Box 53 of 62	883021, Radio Smithsonian: Control Room Modifications, NMAH
Box 53 of 62	893605, Upgrade Electrical System, RGA
Box 53 of 62	903015, Security Lighting, NMAH
Box 53 of 62	913602, Energy Study Implementation Phase 2, RGA
Box 53 of 62	916321, Freight Elevator Study, Quad
Box 53 of 62	926303, Quad
Box 53 of 62	953014, Temporary Carry-Out, NMAH
	Box 54
Box 54 of 62	897108, Loading Dock Weather Enclosure, MSC
Box 54 of 62	897110, Facade Renovation, MSC
	ost i to, racade Renovation, MSC
Box 54 of 62	916317, HVAC in Gallery 1128, Quad
Box 54 of 62 Box 54 of 62	
	916317, HVAC in Gallery 1128, Quad
Box 54 of 62	916317, HVAC in Gallery 1128, Quad 917003, Relocation of Protection Division, Mall
Box 54 of 62 Box 54 of 62	916317, HVAC in Gallery 1128, Quad 917003, Relocation of Protection Division, Mall 944603, Exterior Renovation, Anacostia Neighborhood Museum (ANM)
Box 54 of 62 Box 54 of 62 Box 54 of 62	 916317, HVAC in Gallery 1128, Quad 917003, Relocation of Protection Division, Mall 944603, Exterior Renovation, Anacostia Neighborhood Museum (ANM) 947104, De-Ionized Water System, MSC 957107, Equipment Relocation - Laboratory of Molecular Systematics
Box 54 of 62 Box 54 of 62 Box 54 of 62	 916317, HVAC in Gallery 1128, Quad 917003, Relocation of Protection Division, Mall 944603, Exterior Renovation, Anacostia Neighborhood Museum (ANM) 947104, De-Ionized Water System, MSC 957107, Equipment Relocation - Laboratory of Molecular Systematics (LMS), MSC
Box 54 of 62 Box 54 of 62 Box 54 of 62 Box 54 of 62	 916317, HVAC in Gallery 1128, Quad 917003, Relocation of Protection Division, Mall 944603, Exterior Renovation, Anacostia Neighborhood Museum (ANM) 947104, De-Ionized Water System, MSC 957107, Equipment Relocation - Laboratory of Molecular Systematics (LMS), MSC

Box 55 of 62	894410, CO2 Lab Fire/Security Repairs, SERC
Box 55 of 62	923022, Replace Vat in CB041 and CB054, NMAH
Box 55 of 62	933008, Duke Ellington Exhibit, NMAH
	Box 56
Box 56 of 62	944403, General Repairs, SERC
Box 56 of 62	944603, Entrance Driveway Repair, ANM
Box 56 of 62	953126, Landscape Kimonos, NMNH
Box 56 of 62	954505, Lobby Doors, HMSG
Box 56 of 62	956316, NMAfA: Explorations, Quad
Box 56 of 62	934511, Glass Replacement, HMSG
Box 56 of 62	947502, Program Support/Office Renovation, L'Enfant Plaza Offices (LEP)
Box 56 of 62	953005, First Ladies Theater, NMAH
	Box 57
Box 57 of 62	[Does not exist - contents are merged into other boxes.]
	Box 58
Box 58 of 62	923127, Museum Shop Evans Gallery, NMNH
	Box 59
Box 59 of 62	923127, Museum Shop Evans Gallery, NMNH
Box 59 of 62	933115, North Lobby Women's Restroom Improvements, NMNH
Box 59 of 62	943115, West Court Office Relocations, NMNH
	Box 60
Box 60 of 62	903108, Public Area Restoration Planning, NMNH
Box 60 of 62	923124, Roof Repairs, Phase 2, NMNH
Box 60 of 62	943127, Main Building Fire Pump, NMNH

	Box 61
Box 61 of 62	907104, Employee Facility Expansion, MSC
Box 61 of 62	933001, Archives Security CCTV, NMAH
Box 61 of 62	934401, General Repairs FY93, SERC
Box 61 of 62	953011, Lemelson Center, NMAH
	Box 62
Box 62 of 62	915811, Miller-Fox House Measured Drawing, CHM
	Oversize
	Architectural and engineering drawings show Project Number, Project Name, Facility, and Number of Drawings Summary: Architectural and engineering drawings show Project Number, Project Name, Facility, and Number of Drawings
Oversize	953001, EDS Office Modifications, NMAH, 3
Oversize	927102, Add Fume Hood to Room E-2111, MSC, 1
Oversize	953417, Office of Production and Design, National Museum of American Art (NMAA), 4
Oversize	943307, Miscellaneous Projects Phase II, AIB, 5
Oversize	953005, First Ladies Theater, NMAH, 5
Oversize	933001, Archives Security CCTV, NMAH, 1
Oversize	913507B, First and Third Floor Ceilings Replacement, NASM, 14
Oversize	943112, Replace Main Steam Station, NMNH, 5
Oversize	906314, Coat Check Room, Quad, 6
Oversize	906313, Handicap Access for Lecture Hall, Quad, 5
Oversize	923201, Improvements to SI T650, SIB, 2
Oversize	903504, Handicap Accessibility Improvements, NASM, 1
Oversize	887007, Upgrade Controls to DDC, Mall, 6

- Oversize 913507A, Snow Melter Repairs, NASM, 4
- Oversize 913002A, Data Communications Backbone Systems, NMAH, 9
- Oversize 883206A, Fire Protection Improvements Phase IX, SIB, 15
- Oversize 883201, Tunnel Repair and Waterproofing, SIB, 8
- Oversize 883212, Modifications to Restrooms, SIB, 17
- Oversize 8732110, Flag Tower Renovation, SIB, 3
- Oversize 883204, O.P.S. Space Modifications, SIB, 13
- Oversize 8632107W, Window Restoration Phase 2 and 3, SIB, 35
- Oversize 883210, Repointing of Facade, SIB, 10
- Oversize 903201, Relocation of Credit Union, SIB, 11
- Oversize 884504, Redesign Spray Paint Booth, HMSG, 5
- Oversize 903504, Handicapped Accessibility Improvements, NASM, 8
- Oversize 883417, General Exterior Repairs, AAPG, 22
- Oversize 943127, Main Building Fire Pump (As-Builts), NMNH, 5
- Oversize 883015, Carmichael Auditorium Light Controls, NMAH, 7
- Oversize 913012, Master Implementation Plan Phase IVB(As-Builts), NMAH, 3
- Oversize 923001, Renovation of Mall Shop, NMAH, 18
- Oversize 933515, Employees Restrooms Modifications, NASM, 10
- Oversize 933515A, Renovations to Employee Locker Rooms, NASM, 14
- Oversize 956320, Loading Dock HVAC, Quad, 10
- Oversize 883401, Waterproofing and Detection, AAPG, 9
- Oversize 923127, Museum Shop Evans Gallery, NMNH, 7
- Oversize 933115, North Lobby Women's Restroom Improvements, NMNH, 18
- Oversize 893113, Chiller Plant Relocation, NMNH, 79

Oversize	903017, HVAC Implementation Phase IVA (As-Builts), NMAH, 54
----------	-------------------------------------------------------------

- Oversize 927102, Building Central Ventilation Retrofit, MSC, 70
- Oversize 903105, East Court Addition, NMNH, 37
- Oversize 913005, Dibner Library Renovation, NMAH, 9

Oversize 933011, Carmichael Theater Organ, NMAH, 6

- Oversize 903116, East and West Wing Penthouses, Roof and Window Repair, NMNH, 52
- Oversize 904406, Laboratory Modules, Phase1, SERC, 21
- Oversize 904406, Laboratory Modules, Phase 1, Addenda, SERC, 5
- Oversize 912205, CRC / Horticultural Building, NMAI, 34
- Oversize 922105, GHCC / Museum Shops, NMAI, 26
- Oversize 953413, Emergency Repairs to Apse Windows, AAPG, 7
- Oversize 943127, Main Building Fire Pump, NMNH, 5
- Oversize 943115, West Court Office Relocation, NMNH, 10
- Oversize 902002, Research Branch Annex New Laboratory Annex, NMAI, 6
- Oversize 895106, Infrared Optical Telescope Array F. L. Whipple Observatory, Smithsonian Astrophysical Observatory (SAO), 11
- Oversize 923124, Roof Repairs, Phase One, NMNH, 9
- Oversize 923124, Roof Repairs, Phase Two, NMNH, 4
- Oversize 916308, Courtyard Gates, Quadrangle, 3
- Oversize 926317, Installation of Safety Barrier / Railing, Quadrangle, 3