



Smithsonian Institution Archives

Records, 1899-1913, 1949, 1960-1978

Finding aid prepared by Smithsonian Institution Archives

Smithsonian Institution Archives
Washington, D.C.
Contact us at osiaref@si.edu

Table of Contents

Collection Overview	1
Administrative Information	1
Descriptive Entry.....	1
Names and Subjects	1
Container Listing	3

Collection Overview

Repository:	Smithsonian Institution Archives, Washington, D.C., osiaref@si.edu
Title:	Records
Identifier:	Record Unit 637
Date:	1899-1913, 1949, 1960-1978
Extent:	12 cu. ft. (12 record storage boxes) (13 oversize folders)
Creator::	Smithsonian Institution. Office of Facilities Planning and Engineering Services
Language:	Language of Materials: English

Administrative Information

Preferred Citation

Smithsonian Institution Archives, Record Unit 637, Smithsonian Institution. Office of Facilities Planning and Engineering Services, Records

Descriptive Entry

These records contain project files, blueprints, contract and work files, photographs, and correspondence related to several renovation projects. Included are renovation and restoration plans for the Arts and Industries Building, the Patent Office Building (home to the National Collection of Fine Arts and National Portrait Gallery), and the Freer Gallery of Art. Also included are original blueprints, drawings, and renovation plans from the Carnegie Mansion located at 91st Street and 5th Avenue, New York City, which is now the home of the Cooper-Hewitt Museum.

Names and Subject Terms

This collection is indexed in the online catalog of the Smithsonian Institution under the following terms:

Subjects:

- Architectural design
- Buildings -- Maintenance
- Buildings -- Repair and reconstruction
- Museum buildings
- Smithsonian buildings

Types of Materials:

Architectural drawings
Black-and-white photographs
Manuscripts

Names:

Arts and Industries Building (Washington, D.C.)
Carnegie Mansion (New York, N.Y.)
Cooper-Hewitt Museum
Freer Gallery of Art
National Collection of Fine Arts (U.S.)
National Portrait Gallery (Smithsonian Institution)
Patent Office Building (Washington, D.C.)

Container Listing

Box 1

Arts and Industries Building

- Box 1 of 12 Separation of Sanitary and Storm Sewers - Contract SFA-2-1650, 1971-1972
- Box 1 of 12 Separation of Sanitary and Storm Sewers - AI 721A, 1972
- Box 1 of 12 East-South Range and West-South Range Mezzanine Filler Panel - AI 722A - Drawings (2 folders)
- Box 1 of 12 Specs - East-South Range - AI 722A, 1972
- Box 1 of 12 Mezzanine Additions - East-South and West-South Ranges - AI 722A - Contract, 1972-1973
- Box 1 of 12 East-South and West-South Ranges - AI 722A - Contract FC-3-04193, 1972-1973 (3 folders)
- Box 1 of 12 West-South Range Survey and Structural Design - AI 722A
- Box 1 of 12 East-South Range Survey and Structural Design - AI 722A
- Box 1 of 12 Provide Office Space - East-South and West-South Ranges - Contract SFA-2-3654
- Box 1 of 12 South-West Range - Structural design file - AI 714A, 1971
- Box 1 of 12 Relocate systems division - South-West Range, 3rd floor - AI 716A, 1969
- Box 1 of 12 Mezzanine Additions - North-West Range - AI 713A - Contract, 1971-1972
- Box 1 of 12 Mezzanine Additions - North-West Range - AI 713A - Work files, 1971-1972
- Box 1 of 12 Mezzanine Additions - North-West Range - AI 713A - Drawings and specs (sprinklers), 1971 (2 folders)
- Box 1 of 12 Mezzanine Additions - North-West Range - AI 713A Submittals, 1971-1972
- Box 1 of 12 Renovate 2nd floor Annex north-west pavilion for Office of Museum Programs - AI 7211A, 1972
- Box 1 of 12 North-West range mezzanine addition - Existing conditions survey - AI 713A, 1970
- Box 1 of 12 Photos existing conditions - North-west range - AI 713A, October 1970
- Box 1 of 12 Footings excavated in North-west range and court - AI 713A, 1968-1969

- Box 1 of 12 North-west range mezzanine - Structural design file, AI 713A
- Box 1 of 12 A&I Water service increase design file, 1970
- Box 1 of 12 AI 7215B Exterior lighting of SI and A&I Building, 1972-1973 (see also SI 722B)
- Box 2
- Box 2 of 12 AI 728A - Painting East Hall, A&I, 1972
- Box 2 of 12 AI 7213A - Install bar joists in room 1410, 1972
- Box 2 of 12 AI 7212A - Relocation of conservation lab to A&I Building, 1972
- Box 2 of 12 AI 7211A - Renovate 2nd floor annex, NW pavilion for Office of Museum Programs, 1972
- Box 2 of 12 AI 7214A - Ventilation of SW range using existing skylight, 1972
- Box 2 of 12 AI 732A - Installation of restrooms - SW pavilion annex, 1973
- Box 2 of 12 AI 714A - SW range structural design notes, 1971
- Box 2 of 12 AI 728A - Painting East Hall, 1972
- Box 2 of 12 AI 729C - Drug exhibit, 1972
- Box 2 of 12 AI 727A - Fiscal Division - SE Court - A/C problem, 1971
- Box 2 of 12 AI 7210A - A&I ventilation (Halls), 1971
- Box 2 of 12 AI 732A - Installation of 4 toilet rooms - SW pavilion annex - Design, 1973 (3 folders)
- Box 2 of 12 AI 732A - Rest room installation - Original specifications, 1973
- Box 2 of 12 AI 747A - Proposed south entrance, 1975-1976 (3 folders)
- Box 2 of 12 AI 733A - Fire extinguishing system for computer room, 1973
- Box 2 of 12 AI 731A - Relocation of circuit breaker panel (SW3) from room 1369 to Puppet Theatre, 1973
- Box 2 of 12 AI 743A - New office space, WS, ES, SE ranges ground floor, 1973
- Box 2 of 12 AI 746A - Stenciling major exhibit halls and rotunda, 1975-1976
- Box 2 of 12 AI 742A - Move of museum shop into Space Art Hall, 1973
- Box 2 of 12 AI 741A - A/C to offices, north corridor, WS range, second floor, 1973

- Box 2 of 12 AI 7512 - Archives: NE range, NE court, and EN range, 1975-1976
- Box 2 of 12 AI 7512 - Relative humidity and temperature tolerances for Archives, 1975 (3 folders)
- Box 2 of 12 AI 7513A - Plumbing and electrical study, 1975
- Box 2 of 12 AI 761A - Mechanical/Electrical systems updating, 1975
- Box 2 of 12 AI 769A - OEO (Office of Equal Opportunity) suite, NE pavilion, 3rd floor, 1975
- Box 2 of 12 AI 762A - Museum shop-1876, 1975-1976 (3 folders)

Box 3

- Box 3 of 12 AI 763A - Modifications for SITES (Smithsonian Institution Traveling Exhibition Service), SE quadrant, 2nd floor, 1975
- Box 3 of 12 AI 765A - Demolition and installation of slab - Rotunda, 1975
- Box 3 of 12 AI 766A - Museum shop-1876 - Cabinet work, 1975-1976
- Box 3 of 12 AI 767A - Exit night light emergency circuit, 1976
- Box 3 of 12 AI 768A - Information booths for 1876, 1975
- Box 3 of 12 AI 769A - Relocation of OEO from L'Enfant Plaza to A&I Building, 1976
- Box 3 of 12 AI 7610A - SI Press - SE and ES ranges, 1976
- Box 3 of 12 Contract FC-4-61680 - Restoration and Renovation of the Arts and Industries Building, 1974
- Box 3 of 12 Miscellaneous documents, 1971-1974 (8 folders)
- Box 3 of 12 AI 754A - Proposed north entrance, 1975
- Box 3 of 12 AI 751A - Restore floor in the South Hall, 1974
- Box 3 of 12 AI 758A - "1876: A Centennial Exhibition" - Steam engine platform and line shaft system, 1975
- Box 3 of 12 AI 755A - Structural and roof survey, 1975
- Box 3 of 12 AI 7510A - "1876" contracts, 1975
- Box 3 of 12 AI 7611A - Relocation of SITES from Barney House to 2nd floor, NE range, NE court
- Box 3 of 12 AI 7511A - Roof restoration, 1975

National Collection of Fine Arts (NCFA) and National Portrait Gallery (NPG) -
Old Patent Office Building

- Box 3 of 12 Remodeling of Courtyard (contract FC-6-60746) - Contract documents, 1975
- Box 3 of 12 Remodeling of Courtyard (contract FC-6-60746) - Correspondence, 1975-1976
- Box 3 of 12 Remodeling of Courtyard (contract FC-6-60746) - Shop drawings, 1975
- Box 3 of 12 Remodeling of Courtyard (contract FC-6-60746) - Payments, 1975-1976
- Box 3 of 12 Fabrication of walls (contract FC-5-50400) - Contract documents, 1975
- Box 3 of 12 Fabrication of walls (contract FC-5-50400) - Payments to contractor, 1975
- Box 3 of 12 Modifications and additions to Galleries 3B and 3C, NCFA (Contract FC-6-64489) - Contract, 1976
- Box 3 of 12 Modifications and additions to Galleries 3B and 3C, NCFA (Contract FC-6-64489) - Payment, 1976
- Box 3 of 12 Made in Chicago (contract FC-5-47250), 1974
- Box 3 of 12 Modifications and additions to Print Study Room, Room 153 (contract FC-5-49657) - Correspondence, 1975
- Box 3 of 12 Modifications and additions to Print Study Room, Room 153 (contract FC-5-49657) - Contract documents, 1975
- Box 3 of 12 Modifications and additions to Print Study Room, Room 153 (contract FC-5-49657) - Payments, 1975
- Box 3 of 12 Modifications and additions to Print Study Room, Room 153 (contract FC-5-49657) - Shop drawings and materials, 1975
- Box 3 of 12 Third floor renovation (contract FC-4-63610) - Contract documents, 1975
- Box 3 of 12 Third floor renovation (contract FC-4-63610) - Proposals pending, 1974-1975
- Box 3 of 12 Third floor renovation (contract FC-4-63610) - Correspondence, 1974-1975
- Box 3 of 12 Third floor renovation (contract FC-4-63610) - Payment to contract, 1974-1975
- Box 3 of 12 Third floor renovation (contracts FC-3-08077 and SF-4-63104) - Architects, 1974-1976
- Box 3 of 12 Painting of walls, ceiling, and trim (contract FC-5-50989) - Contract documents, 1975

Box 3 of 12 Painting of walls, ceiling, and trim (contract FC-5-50989) - Payments, 1975

Box 3 of 12 Gallery 3B (contract FC-6-63449) - Payments, 1976

Box 3 of 12 Dining facility and kitchen storage area, room 183 and 183A (Contract FC-5-53467), 1975

Box 4

Box 4 of 12 665-B - Millwork, 2nd floor, 1966-1967 (2 folders)

Box 4 of 12 738C - Renovate 1st floor, 7th St., 1973-1974 (3 folders)

Box 4 of 12 754A - Conduit layout, 1975

Box 4 of 12 621-C - Lighting system improvement, 1962

Box 4 of 12 735-C - Renovate 3rd floor, 1974 (2 folders)

Box 4 of 12 9th St. Main entrance and step modification, 1975

Box 4 of 12 756-B - Courtyard and HVAC improvements, 1975

Box 4 of 12 715C - Renovate F St. Wing, 1st floor, 1971

Box 4 of 12 7111-B - G St. Metro, 1966-1967, 1971-1972 (2 folders)

Box 4 of 12 676-B - Modify wire mesh panels at 24th St. and install storage area, 1967

Box 4 of 12 673A - Resilient floor covering for library

Box 4 of 12 691-C - Storage racks for space, 1968-1969

Box 4 of 12 725-C - Renovate gallery 341, 1975

Box 4 of 12 The Academy exhibit

Box 4 of 12 "Made in Chicago" exhibit

Box 4 of 12 1st floor plan

Box 4 of 12 731-C - Director's suite modifications, 1972 (2 folders)

Box 4 of 12 European Gallery, room 182 (contract FC-3-09277), 1972-1973

Box 4 of 12 723-C - Banner support on south portico, 1971

Box 4 of 12 732-B - Exterior lighting, 1973

Box 4 of 12 757B - Additional 3rd floor electrical work, 1975

Box 4 of 12 754A - Wiring diagram, 1975

Box 4 of 12 Sculpture Unlimited (contract FC-5-50430) - Contract documents, 1975

Box 4 of 12 Sculpture Unlimited (contract FC-5-50430) - Payments, 1975

Box 4 of 12 663B - Additional millwork, 1966-1967

Box 4 of 12 721C - Renovation of F St. entrance, 1971

Box 4 of 12 724B - Indirect lighting - Room 138 - David Finley Conference Room, 1971

Box 4 of 12 761A - Specifications for modifications and additions to Room 153 (print Study Room), 1974

Box 4 of 12 737B - Miniature gallery, 1973

Box 4 of 12 741B - Cafeteria, 1973

Box 4 of 12 752-A - Electric dimmer switches, 1975

Box 4 of 12 715A - Sidewalk repairs on north side of F St., between 7th and 9th Sts., 1971

Box 5

Box 5 of 12 "The Academy" exhibit (contract FC-5-51314) - Contract documents, 1975

Box 5 of 12 "The Academy" exhibit (contract FC-5-51314) - Payments, 1975

Box 5 of 12 "The Academy" exhibit (contract FC-5-51314) - Correspondence, 1975

Box 5 of 12 "The Academy" exhibit (contract FC-5-51314) - Shop drawings and materials, 1975

Box 5 of 12 7th St., 1st floor (contract FC-4-63394) - Contract documents, 1973-1974

Box 5 of 12 7th St., 1st floor (contract FC-4-63394) - Payments to contractor, 1974

Box 5 of 12 7th St., 1st floor (contract FC-4-63394) - Correspondence, 1973-1974

Box 5 of 12 7th St., 1st floor (contract FC-4-63394) - Proposal requests, 1974

Box 5 of 12 Stone steps (contract FC-5-51645) - Contract documents, 1975

Box 5 of 12 Stone steps (contract FC-5-51645) - Payments, 1975

Box 5 of 12 Stone steps (contract FC-5-51645) - Shop drawings and materials, 1975

Box 5 of 12 Additional 3rd floor electrical work (contract FC-6-60744) - Contract documents, 1975

Box 5 of 12 Additional 3rd floor electrical work (contract FC-6-60744) - Payments, 1975

- Box 5 of 12 Additional 3rd floor electrical work (contract FC-6-60744) - Correspondence, 1975
- Box 5 of 12 Additional 3rd floor electrical work (contract FC-6-60744) - Shop drawings and materials, 1975
- Box 5 of 12 Dining facility and modifications, east 1st floor, 1973
- Box 5 of 12 Gallery 341, Tribute to Mark Tobey exhibition (contract FC-4-065805) - Contract documents, 1974
- Box 5 of 12 Gallery 341, Tribute to Mark Tobey exhibition (contract FC-4-065805) - Correspondence, 1974
- Box 5 of 12 Modifications and additions to Galleries 102 and 103 (contract FC-5-52508) - Contract documents, 1975
- Box 5 of 12 2nd floor lighting (contract FC-6-50015) - Contract documents, 1975
- Box 5 of 12 2nd floor lighting (contract FC-6-50015) - Correspondence, 1975
- Box 5 of 12 2nd floor lighting (contract FC-6-50015) - Payment to contractor, 1975
- Box 5 of 12 2nd floor lighting (contract FC-6-50015) - Shop drawings, 1975
- Box 5 of 12 3rd floor renovations (contract FC-4-63610) - Contract documents, 1974
- Box 5 of 12 3rd floor renovations (contract FC-4-63610) - Shop drawings, 1974
- Box 5 of 12 3rd floor renovations (contract FC-3-08077), 1973-1973
- Box 5 of 12 3rd floor painting (contract FC-6-61370), 1975
- Box 5 of 12 Modification and additions to Gallery 3B (contract FC-6-63449), 1975
- Box 5 of 12 Gallery Station Metro, 1971-1972
- Box 5 of 12 731C - Director's suite modifications - Contract, 1972
- Box 5 of 12 732B - Exterior lighting - Design, 1972-1974
- Box 5 of 12 733A - Painting, interior - Office space - Exhibit area, 1972
- Box 5 of 12 734A - Air conditioning systems - Contract, 1973
- Box 5 of 12 753B - Exhibit programs for NCFA, NPG, and Renwick, 1975
- Box 5 of 12 752A - 2nd floor lighting renovation - South and east wings - Design, 1975
- Box 5 of 12 756B - Courtyard and HVAC improvements, 1975

- Box 5 of 12 761A - Restaurant and kitchen - Heating and air conditions, 1975
- Box 5 of 12 763D - Asbestos dust, 1976
- Box 5 of 12 735B - 3rd floor renovation - Design, 1973
- Box 5 of 12 735C - 3rd floor renovations (contract FC-3-08077), 1972-1974
- Box 5 of 12 757B - Lighting system additions to 3rd floor renovation, 1975
- Box 5 of 12 762A - Elevator modifications, 1975
- Box 5 of 12 Interior painting, 1st and 2nd floor of southeast corridor (contract FC-708795), 1977-1978
- Box 5 of 12 774A - Exterior repairs and exterior painting, 1977
- Box 5 of 12 754A - Fire and smoke detection system, 1975-1977 (2 folders)
- Box 5 of 12 Fire and smoke detection system (contract FC-6-60743) - Contract documents, 1975
- Box 5 of 12 Fire and smoke detection system (contract FC-6-60743) - Correspondence, 1975-1976
- Box 5 of 12 Fire and smoke detection system (contract FC-6-60743) - Payments, 1976
- Box 5 of 12 Fire and smoke detection system (contract FC-6-60743) - Shop drawings and materials, 1975-1976
- Box 5 of 12 764A - Air circulation, 1976
- Box 5 of 12 742C - Tribute to Mark Tobey exhibition - Design, 1974
- Box 5 of 12 725C - Renovate Gallery 341 to receive National Parks exhibition, 1972
- Box 5 of 12 733A - Interior painting, 1972
- Box 5 of 12 734A - Air conditioning systems - Specifications sections, 1972-1973

Box 6

Freer Gallery of Art

- Box 6 of 12 662A - Repaint Freer Building (contract 66-SI-1051), 1966 (2 folders)
- Box 6 of 12 63 - Repaint walls (contract 60-Si-788), 1959
- Box 6 of 12 673C - Freer freight elevator modernization (contract GS-03B-14588), 1968-1972
- Box 6 of 12 661A - South Entrance Loading Area, 1963-1964

Box 6 of 12 Vinyl wall covering etc., 1963

Box 6 of 12 754A - Hand rails, south entrance, 1963

Box 6 of 12 621C - Miscellaneous, 1970-1971

Box 6 of 12 724A - Replace gate on elevator car, 1972-1973

Box 6 of 12 723B - Exterior lighting - Design, 1972-1973 (2 folders)

Box 6 of 12 761A - Fire detection - Phase II, 1975

Box 6 of 12 682A - Freer skylight alterations

Box 6 of 12 681A - Projects for fiscal year 1970

Box 6 of 12 Photographs

Box 6 of 12 762A - Elevator modifications

Box 6 of 12 661A - Construct one taxi bay on Independence Ave. NW, 1966-1967

Box 6 of 12 753B - Smoke detection system (contract FC-5-51941), 1975 (2 folders)

Box 6 of 12 731A - Lawn sprinkler system - Design, 1973-1974

Box 6 of 12 Miscellaneous documents, 1962-1978 (5 folders)

Box 7

Carnegie Mansion, East 91st St. and 5th Ave., New York City (Cooper-Hewitt Museum)

Box 7 of 12 Drawing numbers 231-233, 235, 241, 244, 248-249a, 255-257, 261
[Digital Content: South elevation of 1st story waiting room, drawing 248 \(partial\). \[SIA2013-11266\]](#)

Box 7 of 12 Drawing numbers 269, 275, 300

Box 7 of 12 Drawing numbers 373-410 (6 folders)

Box 7 of 12 Drawing numbers 411-418, 420-422, 424-428, 430-433, 435-444 (4 folders)

Box 7 of 12 Drawing numbers 445a-446, 449-450a, 452-454, 459-464, 466-475, 480-494 (3 folders)
[Digital Content: Marble basin for fountain in conservatory, drawing 469. \[SIA2013-11252\]](#)
[Digital Content: Ceiling light--3rd floor, drawing 463. \[SIA2013-11249\]](#)
[Digital Content: Gallery ceiling light, drawing 466. \[SIA2013-11251\]](#)

[Digital Content: Ceiling light--maids' hall, 4th floor, drawing 464. \[SIA2013-11250\]](#)

[Digital Content: Elevation, plan, and detail drawings for door between hall and reception room--revised drawing, drawing 492. \[SIA2013-11253\]](#)

Box 8

- Box 8 of 12 Drawing numbers 498-503, 510, 512, 514, 515-524, 527-536, 539-550, 551-556, 559-560, 563-565, [566 - see Oversize Folder 13], 567-574, 576, 578-579 (5 folders)
[Digital Content: Pavement in entrance hall and vestibule, drawing 533. \[SIA2013-11255\]](#)
[Digital Content: Register for library, private room, dining room, etc., drawing 530. \[SIA2013-11254\]](#)
- Box 8 of 12 Drawings - Cellar drainage
- Box 8 of 12 Drawings - G. A. Suter's heating plans
- Box 8 of 12 Drawing - Gerhard #1 - Cellar
- Box 8 of 12 Drawing - Gerhard #2 - Basement
- Box 8 of 12 Drawing - Gerhard #3 - 1st floor
- Box 8 of 12 Drawing - Gerhard #4 - 2nd floor
- Box 8 of 12 Drawing - Gerhard #5 - 3rd floor
- Box 8 of 12 Drawing - Gerhard #6 - 4th floor
- Box 8 of 12 Drawing - Gerhard #7
- Box 8 of 12 Drawing - Gerhard - Lines of pipes
- Box 8 of 12 Drawing - G. A. Suter - heating - Change, Bedrooms, 3rd floor
- Box 8 of 12 Drawing - G. A. Suter - Roof plan
- Box 8 of 12 Drawing - G. A. Suter - Cellar plan
- Box 8 of 12 Drawing - G. A. Suter - Basement plan, 1956
- Box 8 of 12 Drawing - G. A. Suter - 1st floor
- Box 8 of 12 Drawing - G. A. Suter - 2nd floor
- Box 8 of 12 Drawing - G. A. Suter - 3rd floor
- Box 8 of 12 Drawing - G. A. Suter - 4th floor
- Box 8 of 12 Drawing - G. A. Suter - Change in blue, NE corner

Box 8 of 12 Drawing - Pump room, 1900

Box 8 of 12 Drawing - G. A. Suter - Hot water heating in conservatory

Box 8 of 12 Drawing - Gerhard #16

Box 8 of 12 Drawing - Change of sewing room closet to bathroom

Box 8 of 12 Drawing - Gerhard - Profile 91st St. and sewer

Box 8 of 12 Drawing - Gerhard - Sewer connections

Box 8 of 12 Drawing - Gerhard #10

Box 8 of 12 Drawing - Gerhard #14

Box 8 of 12 Drawing - Gerhard - Sewer drawings

Box 8 of 12 Drawing - G. A. Suter - Heating main entrance, 1st floor

Box 8 of 12 Drawing - Changes, radiators

Box 8 of 12 Drawing - Boilers

Box 8 of 12 Drawing - Gerhard - Sewage tank

Box 8 of 12 Drawing - Gerhard - Boiler room

Box 8 of 12 Drawing - Changes, Exhaust flues

Box 8 of 12 Drawing - Concrete foundations for heaters

Box 8 of 12 Drawings - 1913 alterations (Folders 1-2 of 5)
[Digital Content: First floor plan: alteration to residence 2 East 91st Street NYC. \[SIA2013-11256\]](#)

Box 9

Box 9 of 12 Drawings - 1913 alterations (Folders 3-5 of 5)

Box 9 of 12 Drawings - Miller house alterations 1965 (6 folders)

Box 9 of 12 Drawings - Carnegie alterations 1949 (6 folders)

Box 10

Box 10 of 12 Documents used for litigation against Carnegie, 1906 (3 folders)

Box 10 of 12 Various architectural drawings (9 folders)

Civil Service Commission Building (National Collection of Fine Arts and National Portrait Gallery/Old Patent Office Building)

- Box 10 of 12 Piping equipment room, piping and cooling tower layout, 1965
- Box 10 of 12 Drawing number 26-141 - Flange details, low impedance duct, 1965
- Box 10 of 12 Drawing number 26-142 - Electric service rooms, 1965
- Box 10 of 12 Drawing number 26-143 - Ventilated bus ducts, 1965
- Box 10 of 12 Drawing number 26-145 - Pressure reducing station rooms, 1965
- Box 10 of 12 Drawing number 26-154 - Mechanical layout, 2nd floor conservation lab, 1965
- Box 10 of 12 Drawing number 26-156 - Revised pipe and duct layout, 1965
- Box 10 of 12 Drawing number 26-58 - Wall chase drawing, 1965
- Box 11
- Box 11 of 12 Drawing number 26-57 - Wall openings - Pipes and ducts, 1965
- Box 11 of 12 Drawing number 26-59 - Wall chases, 1965
- Box 11 of 12 Drawing number 24-9B - Hollow metal doors and bucks, 1965
- Box 11 of 12 Drawing number 24-6 - Trap doors, 1965
- Box 11 of 12 Drawing number 24-4 - Stair no. 4 railings, 1965
- Box 11 of 12 Drawing number 24-5 - Metal corner guards, 1965
- Box 11 of 12 Drawing number 24-3 - Sump pit cover and frame - Loading dock, 1965
- Box 11 of 12 Drawing number 24-2 - Jamb and soffit plates, doors 303 and 312, 1965
- Box 11 of 12 Drawing number 26-261 - "CL" layout, 1961
- Box 11 of 12 Drawing number 25-11 - Framing det. 18 C51.9, 1965
- Box 11 of 12 Drawing number 25-61 - Stair no. 4 beams, 1965
- Box 11 of 12 Drawing number 11248 - Rails, E St. 10 and 11, 1966
- Box 11 of 12 Drawing number 7583 - Repair ornamental railing
- Box 11 of 12 Drawing number 7093 - Window framing - Rooms 341, 346, 347
- Box 11 of 12 Drawing number 7092 - Closure angle

Box 11 of 12	Drawing number 7095 - Pipe rail
Box 11 of 12	Drawing number 7114 - Relocate rail at room 111 and 112
Box 11 of 12	Drawing number 7110 - Wire mesh partition
Box 11 of 12	Drawing number 7064 - Mop racks
Box 11 of 12	Drawing number 7063 - E-Ships ladder at project room
Box 11 of 12	Drawing number 7079 - Pipe railing
Box 11 of 12	Drawing number 25-15, 15-15A - Framing G St. lobby lounges 1, 2, 3
Box 11 of 12	Drawing number 25-16, 25-16A - Connection details, framing G St., 1st floor
Box 11 of 12	Drawings - Framing
Box 11 of 12	Drawings - New duct shaft, Stair no. 7
Box 11 of 12	Drawings - Elevators
Box 11 of 12	Drawing number 6645-30 - Elevation and details fo recess cabinet in Room 119
Box 11 of 12	Drawings - Door frames
Box 11 of 12	Drawing number 24-10 - Stair no. 6 railings
Box 11 of 12	Drawing number 24-11 - Platform bumpers - Steel only, G St. truck dock
Box 11 of 12	Drawing number 24-12 - Pipe rails G St. truck dock
Box 11 of 12	Drawing number 24-13 - Rail detail, 3rd floor lobby, F St.
Box 11 of 12	Drawing number 24-14 - Railing - Fascia detail, 4th floor library
Box 11 of 12	Drawing number 24-15 - Relocate mezzanine railing
Box 11 of 12	Drawing number 24-16 - Trench drains
Box 11 of 12	Drawing number 24-17 - Manhole frames and covers
Box 11 of 12	Drawing number 24-20 - Balcony railing detail, 3rd floor mezzanine
Box 11 of 12	Drawing number 24-22 - Relocate metal stairs, 3rd floor mezzanine
Box 11 of 12	Drawing number 24-23 - Alter railing, 2nd floor lounge, F St.
Box 11 of 12	Drawing number 24-24 - Pipe railings, basement
Box 11 of 12	Drawing number 24-25 - Balcony changes, 4th floor, stairs 2, 9

- Box 11 of 12 Drawing number 24-26 - Sub-frame detail, 1st floor doors 1301 to 1306
- Box 11 of 12 Drawing number 24-27 - Railing repair, courtyard
- Box 11 of 12 Drawing number 24-28 - Railing detail, stair no. 5
- Box 11 of 12 Drawing number 24-30 - Name plate brackets
- Box 11 of 12 Drawing number 24-31 - Truck dock, collar for post of hydraulic lift
- Box 11 of 12 Drawing number 24-32 - Trench cover plates, court area way
- Box 11 of 12 Drawing number 24-33 - Metal cover plate, B50
- Box 11 of 12 Drawing number 24-34 - Trap doors, elevators 3, 4, 5
- Box 11 of 12 Drawing number 24-35 - Entrance gates
- Box 11 of 12 Drawing number 24-36 - Lift guard post, truck dock
- Box 11 of 12 Drawing number 24-38 - Wire mesh partitions, elevator 3
- Box 11 of 12 Drawing number 24-42 to 24-44 - Roof scuttle
- Box 11 of 12 Drawing number 24-8 - Roof for support angles, 7th St. roof
- Box 11 of 12 Drawing number 24-54 - Bonding angles
- Box 11 of 12 Drawing number 24-184C - Flagpole, aluminum
- Box 11 of 12 Drawing number 25-90 - New roof framing details
- Box 11 of 12 Drawing number 25-16 - Framing detail, lobby, lounge
- Box 11 of 12 Drawing number 25-16A - Structural beam
- Box 11 of 12 Drawing number 7083 - Angle guards
- Box 11 of 12 Drawing number 69-1A - Floor plans
- Box 11 of 12 Various architectural drawings (Folders 1-3 of 7)
- Box 12
- Box 12 of 12 Various architectural drawings (Folders 4-7 of 7)
- Carnegie Mansion, East 91st St. and 5th Ave., New York City (Cooper-Hewitt Museum)
- Box 12 of 12 Agreements - Subcontracted work: NYC-1-A 701 to 737 (3 folders)

- Box 12 of 12 New York Residence of Andrew Carnegie, 1910
- Box 12 of 12 Original Carnegie plans (no cellar plan included), 1901
[Digital Content: First floor plan, drawing 10A. \[SIA2013-11258\]](#)
[Digital Content: Second floor plan, drawing 11A. \[SIA2013-11259\]](#)
[Digital Content: Third floor plan, drawing 12A. \[SIA2013-11260\]](#)
[Digital Content: Fourth floor plan, drawing 13A. \[SIA2013-11261\]](#)
[Digital Content: Copy of basement plan. \[SIA2013-11257\]](#)
- Arts and Industries Building
- Box 12 of 12 Drawing number A1 753A - Floor plans and elevations, 1975
- Box 12 of 12 Roof, phase I, 1973-1975
- Civil Service Commission Building (National Collection of Fine Arts and National Portrait Gallery/Old Patent Office Building)
- Box 12 of 12 Various architectural drawings (5 folders)
- Oversize
- Oversize Arts and Industries Building drawings (Folders 1-7)
- Oversize Carnegie Mansion (Cooper-Hewitt Museum) drawings (Folders 8-13)