



Smithsonian

Institution Archives

Project Files, *circa* 1960-1980

Finding aid prepared by Smithsonian Institution Archives

Smithsonian Institution Archives
Washington, D.C.
Contact us at osiaref@si.edu

Table of Contents

Collection Overview	1
Administrative Information	1
Descriptive Entry.....	1
Names and Subjects	1
Container Listing	3

Collection Overview

Repository:	Smithsonian Institution Archives, Washington, D.C., osiaref@si.edu
Title:	Project Files
Date:	<i>circa</i> 1960-1980
Identifier:	Record Unit 638
Creator::	Smithsonian Institution. Office of Design and Construction
Extent:	107.16 cu. ft. (105 record storage boxes) (2 document boxes) (2 tall document boxes)
Language:	English

Administrative Information

Preferred Citation

Smithsonian Institution Archives, Record Unit 638, Smithsonian Institution. Office of Design and Construction, Project Files

Descriptive Entry

This record unit consists of project files documenting the repairs, improvement, and renovation of existing Smithsonian buildings. The records include memoranda with Smithsonian offices, correspondence with contractors, blueprints, cost analyses, specifications, and photographs.

Buildings and museums documented in this collection include: the Smithsonian Institution Building, the National Mall, the Silver Hill Facility, the Barney Studio House, the Belmont Estate, the Canal Zone Biological Area at Barro Colorado Island (now the Smithsonian Tropical Research Institute), the Cooper-Hewitt Museum (Carnegie Mansion), the John F. Kennedy Center for Performing Arts, the Government Printing Office at Lamont Street, the Anacostia Neighborhood Museum, the Renwick Gallery, the National Air and Space Museum, the National Museum of History and Technology (now the National Museum of American History), the National Museum of Natural History, the Hirshhorn Museum and Sculpture Garden, the Arts and Industries Building, L'Enfant Plaza offices, the Chesapeake Bay Center for Environmental Studies (now the Smithsonian Environmental Research Center), the Freer Gallery of Art, the National Collection of Fine Arts (later named the National Museum of American Art), the National Portrait Gallery, the Museum Support Center, the Smithsonian Astrophysical Observatory, the Smithsonian Institution Service Center, the Hillwood Museum, the Old Post Office Building, the National Zoological Park, the Quadrangle Complex, and miscellaneous other facilities.

Names and Subject Terms

This collection is indexed in the online catalog of the Smithsonian Institution under the following terms:

Subjects:

Architectural design

Buildings -- Maintenance
Buildings -- Repair and reconstruction
Museum buildings
Smithsonian buildings

Types of Materials:

Architectural drawings
Black-and-white photographs
Manuscripts

Names:

Anacostia Neighborhood Museum
Arts and Industries Building (Washington, D.C.)
Barney Studio House (Washington, D.C.)
Belmont Conference Center (Elk Ridge, Md.)
Carnegie Mansion (New York, N.Y.)
Chesapeake Bay Center for Environmental Studies
Cooper-Hewitt Museum
Freer Gallery of Art
Hillwood Museum (Washington, D.C.)
Hirshhorn Museum and Sculpture Garden
John F. Kennedy Center for the Performing Arts (U.S.)
L'Enfant Plaza (Washington, D.C.)
National Air and Space Museum (U.S.)
National Air and Space Museum (U.S.). Silver Hill Facility
National Collection of Fine Arts (U.S.)
National Museum of American Art (U.S.)
National Museum of American History (U.S.)
National Museum of History and Technology (U.S.)
National Museum of Natural History (U.S.)
National Portrait Gallery (Smithsonian Institution)
National Zoological Park (U.S.)
Post Office Building (Washington, D.C.)
Renwick Gallery
Smithsonian Astrophysical Observatory
Smithsonian Environmental Research Center
Smithsonian Institution Building (Washington, D.C.)
Smithsonian Institution Service Center (Washington, D.C.)
Smithsonian Institution. Museum Support Center
Smithsonian Institution. Office of Facilities Planning and Engineering Services
Smithsonian Institution. Quadrangle Complex
Smithsonian Tropical Research Institute
United States. Canal Zone Biological Area, Barro Colorado Island
United States. Government Printing Office

Places:

Mall, The (Washington, D.C.)

Container Listing

Box 1	
	Smithsonian Institution Building Summary: Smithsonian Institution Building
Box 1 of 109	SI762A Elevator Modifications
Box 1 of 109	SI751B Fire Detection - Basement Level
Box 1 of 109	SI742C Updating Food Service Facility
Box 1 of 109	SI733A Lawn Sprinkler System
Box 1 of 109	SI733A SI and Freer Sprinklers
Box 1 of 109	SI731C Restoration of Exterior Spalling Stone
Box 1 of 109	SI723A Resodding Around Building
Box 1 of 109	SI732B(a) Specification Masters
Box 1 of 109	SI732B(a) Specifications - Air Conditioning Humidification - Master
Box 1 of 109	SI722B Exterior Lighting
Box 1 of 109	SI721A Separating Storm and Sanitary - SI Building, Arts and Industries Building (A&I), Freer (2 folders)
Box 1 of 109	SI7112A Parking Lot and Independence Avenue Access
Box 1 of 109	SI7111D Fire in Room 27-B - Basement Floor
Box 1 of 109	SI719A Renovate Rooms B73 and B74 (West Basement) for Kitchen Employees
Box 1 of 109	SI717A Install New Exhaust System for Dining Area
Box 1 of 109	SI711A Demolition Work in Rooms B6, B15, B16, B17, B18 for New Protection Division Offices (2 folders)
Box 1 of 109	SI702A Paint First, Second, Third, Fourth Floors (East End) and Common and Dining Rooms (West End) (3 folders)
Box 1 of 109	Smithsonian Institution - Common Room, Scheme IV
Box 1 of 109	Smithsonian Institution - Dining Hall, Scheme III

Box 1 of 109	SI701A Feasibility Study for Humidity Control
Box 1 of 109	SI664A Study to Relocate Radiation Biology Laboratory (RBL)
Box 1 of 109	SI663A - RBL - Electrical Service for Durco Light Units
Box 1 of 109	SI662A SI Renovation West Basement, January 1966
Box 1 of 109	SI662A RBL - West Basement
Box 1 of 109	SI Building - Miscellaneous
	Mall and Grounds Summary: Mall and Grounds
Box 1 of 109	MALL751B Power Management Program
Box 1 of 109	MALL731A Outdoor Sprinkler System - South Group
Box 1 of 109	MALL722B Exterior Lighting Buildings - South Group
Box 1 of 109	MALL721C Pave 10th Street Access Road to Parking Lot
Box 1 of 109	MALL713A Demolish, Remove Debris, Grade, and Topsoil Area Bounded by Madison and Washington Drive (2 folders)
Box 1 of 109	MALL713A Remove Concrete Ring and Restore Area
Box 1 of 109	MALL 712A Relocate Street Lamps from Hirshhorn to Spots on Adams and Jefferson Drives
Box 1 of 109	MALL711C Folklife Festival
Box 1 of 109	MALL704C Underground Electric Service - 14th Street to 10th Street
Box 1 of 109	MALL703C Traffic Route About the Hirshhorn Site
Box 1 of 109	MALL702A Plant 17 Elm Trees on Madison Drive, 9th to 12th Streets
Box 1 of 109	MALL701A Provide New Sidewalk in Lawn Area on Madison Drive Between 9th and 12th Streets (2 folders)
	Box 2
Box 2 of 109	MALL693B Concrete Foundation for Tent Theater
Box 2 of 109	MALL693A Tent Theater, Division of Performing Arts, 1969

Box 2 of 109	MALL692B Provide Topographic Survey of SI Building Site
Box 2 of 109	MALL691A Water Pollution Control on SI Properties
Box 2 of 109	MALL684C Conduit and Manhole Construction from 12th and Constitution Avenue NW to Independence Avenue SW
Box 2 of 109	MALL683C 12th Street Subway
Box 2 of 109	MALL681A McMillan Fountain North of Freer Gallery
Box 2 of 109	MALL675A Erect Full-Scale Polaris A-3 Missile
Box 2 of 109	MALL674A Plaques for SI and A&I Buildings
Box 2 of 109	MALL672C Additional Traffic Lights at SW Corner of Constitution Avenue and 12th Streets on the Mall
Box 2 of 109	MALL671D Local Climatological Data, January 1, 1967-Present
Box 2 of 109	MALL662C Sound and Light Program Planning
Box 2 of 109	MALL661C 9th Street Expressway
Box 2 of 109	MALL591C Construct Parking and Rest Area South and East of SI Building
Box 2 of 109	Mall Miscellaneous
Box 2 of 109	Construction Photographs
	Silver Hill Summary: Silver Hill
Box 2 of 109	Doors and Flooring
Box 2 of 109	Silver Hill Building 13 and 14
Box 2 of 109	Buildings 13 and 14 - Approved Transmittals
Box 2 of 109	SIF743B Construct Building 25
Box 2 of 109	SIF742A Electric Service to Building 10
Box 2 of 109	Leveler Dock - Buildings 20 and 21
Box 2 of 109	SIF751A Loading Dock

Box 2 of 109	SIF741A Void Specifications - Copy Clipped to AFM Changes
Box 2 of 109	SIF731B Original Specifications - Building 24 (2 folders)
Box 2 of 109	Gate - Building 24
Box 2 of 109	SIF722A Musical Instruments Storage Structure in Building 15
Box 2 of 109	SIF676B Building 15 Music Exhibits
Box 3	
Box 3 of 109	SIF721B Ramsey Building (3 folders)
Box 3 of 109	SIF703A Enclosure of and Structural Changes to Buildings 1 and 1A
Box 3 of 109	SIF702A Sewer System at Southeast Corner of Building 10
Box 3 of 109	SIF701A Conference Room and Locker/Shower Room - Building 10
Box 3 of 109	SIF693B Relocate Guard House at Silver Hill
Box 3 of 109	SIF692B Master Planning Study for Development at SI Storage Facility, Silver Hill, MD
Box 3 of 109	SIF691B Periguard Intrusion Detection System
Box 3 of 109	SIF682A Steel Mezzanine Frame for Building 22 (2 folders)
Box 3 of 109	SIF681A Insulation for Buildings 7D and 7E
Box 3 of 109	SIF675A Building 22 (4 folders)
Box 3 of 109	SIF674A Contract A - Storage Area in Building 16
Box 3 of 109	SIF673A Clearing and Grading Behind Buildings 3, 4, 5, 6, April 1967
Box 3 of 109	SIF672A New Panel and Service Drop - Building 17, March 1967
Box 3 of 109	SIF671A Install Bank Lun Gravel Behind Buildings 10, 11, 12
Box 3 of 109	Silver Hill - Miscellaneous
Barney Studio House Summary: Barney Studio House	
Box 3 of 109	BSH672A Central Air Conditioning Plant

Box 3 of 109	BSH671A Renovation
Box 3 of 109	BSH671A Renovate Fourth and Fifth Floors for Apartments
Box 3 of 109	BSH673A Install New Heating Plant
Box 4	
Box 4 of 109	BSH671A Renovate Fourth and Fifth Floors for Apartments (2 folders)
Box 4 of 109	BSH671A Specifications
Box 4 of 109	Barney Studio House - Miscellaneous
	Belmont Estate Summary: Belmont Estate
Box 4 of 109	BEL711A Pave Front and Rear Roadway Areas of Main Building
	Canal Zone Summary: Canal Zone
Box 4 of 109	C2BA711C Laboratory Building on Naos Island (2 folders)
Box 4 of 109	66-SI-1047 Canal Zone Building - Master Specifications
Box 4 of 109	C2BA Progress Report
Box 4 of 109	C2BA671C Construct New Boys House - Barro Colorado Island
Box 4 of 109	C2BA661C Construct New Resident Scientist Quarters, February 1966 (3 folders)
	Cooper-Hewitt Museum Summary: Cooper-Hewitt Museum
Box 4 of 109	CHM752A Empty Conduit for Fire Alarm and Security System
Box 4 of 109	CHM741B Renovation of the Cooper-Hewitt Museum
Box 4 of 109	CHM751A New Library Extension
Box 4 of 109	CHM721C Renovation - Carnegie Mansion - Phase I
Box 4 of 109	CHM711A Miller House Apartment - Interface Construction Corporation
Box 4 of 109	CHM711A Gas Conversion of Heating Plant in Carnegie House (3 folders)

Box 4 of 109	CHM701C Design for Museum in Carnegie House
Box 4 of 109	CHM691B Cooper-Hewitt Museum
	John F. Kennedy Center Summary: John F. Kennedy Center
Box 4 of 109	JFKC661C Contract File, October 20, 1966
	Lamont Street Summary: Lamont Street
Box 4 of 109	LST701A GPO (Government Printing Office) Unit Relocation to Lamont Street
Box 4 of 109	LST663D Preparing Blueprint Plans for Insect Traps
Box 4 of 109	LST661A Air Conditioning Survey
Box 4 of 109	LST662D Modify Insect Drawers for Department of Entomology
Box 4 of 109	Lamont Street - Miscellaneous
Box 4 of 109	Lamont Street - Air Conditioning
	Federal Records Center (Building 3) Summary: Federal Records Center (Building 3)
Box 4 of 109	FRC691B SI Spaces in Warehouse Building 3 (Alexandria, VA)
	Navy Yard Annex Summary: Navy Yard Annex
Box 4 of 109	NYA691C Additional Modifications to Space at Sorting Center
Box 4 of 109	NYA681C Electrical, Mechanical and Architectural Revision of Entire Smithsonian Oceanographic Sorting (SOSC) Area
Box 4 of 109	NYA671C Install Air Conditioning in Building 159
Box 4 of 109	NYA672C Renovation of East Side of SOSC Including Plankton, Geology Sections
Box 4 of 109	NYS662C Geophysical Data Facility
Box 4 of 109	NYA661C NWP Preliminary Fish Storage, Photographic Laboratory, and Oceanographic Sorting Center
Box 4 of 109	NYA661C Second Floor Alteration - Building 159

Anacostia Neighborhood Museum
Summary: Anacostia Neighborhood Museum

Box 4 of 109 ANM761A Enclosure for Woodworking and Paint Shop

Box 5

Box 5 of 109 ANM741B Exhibits Training Laboratory

Box 5 of 109 NMB671A Carver Theater - 2405 Nichols Avenue, SE, April 1967

Box 5 of 109 Miscellaneous Buildings

Box 5 of 109 691A Tariff

Box 5 of 109 STAR701C Star Company Property, Anne Arundel, MD

Box 5 of 109 701D Condenser Water Treatment Plant for All Facilities

Box 5 of 109 Reducing Seasonal Variation in Construction Activity and Employment

Box 5 of 109 Prevention, Control, and Abatement of Air and Water Pollution at Federal Facilities

Box 5 of 109 NGA711A Renovation of the First Floor of the West Wing

Box 5 of 109 NGA701D Elevator Installation at the National Gallery of Art (NGA)

Box 5 of 109 NGA Exterior Alterations to 7th Street Entrance

Box 5 of 109 NPG691B Install Light Track and Fixtures in Building

Box 5 of 109 RBL Equipment Layout, Rockville, MD

Box 5 of 109 Scientific Facility at Beltsville, MD

Box 5 of 109 LLB711B Relocation of Smithsonian Staff from Pension Building to Liberty Loan Building

Renwick Gallery
Summary: Renwick Gallery

Box 5 of 109 REN762 Exhibit Lighting

Box 5 of 109 REN761A Elevator Modifications

Box 5 of 109 REN751C Modifications and Additions to Galleries 102 and 103 for the Raymond Loewy Exhibit

Box 5 of 109	REN7212A Chandelier
Box 5 of 109	REN731A Roof (3 folders)
Box 5 of 109	REN7210A Birdproofing
Box 5 of 109	REN691A Birdproofing of Renwick Museum
Box 5 of 109	REN721C Fabrication of Platforms for Woodwork Show
Box 5 of 109	REN727C Marbelizing (Paint) Stairwell
Box 5 of 109	REN729A Clean and Restore Stone Staircase
Box 5 of 109	REN728B Shop Drawings
Box 5 of 109	REN728A Display Cases for Room 106
Box 5 of 109	REN726A Sidewalk Repair (3 folders)
Box 5 of 109	REN723A Ornamental Railing - Roof (3 folders)
Box 5 of 109	REN724B Etching - Main Entrance Doors
Box 5 of 109	REN722B Painting Interior and Exterior (3 folders)
Box 5 of 109	REN725A Cleaning Exterior Masonry (2 folders)
Box 6	
Box 6 of 109	REN721B Phase II Renovation (4 folders)
Box 6 of 109	REN721B Renovation Specifications
Box 6 of 109	REN721B Alteration and Renovation - Portion of Building Interior
Box 6 of 109	Saddle Exhibition
	National Air and Space Museum Summary: National Air and Space Museum
Box 6 of 109	Power Management System
Box 6 of 109	NASM753B Automatic Central Control System
Box 6 of 109	NASM752A Engineering System and Power Management
Box 6 of 109	NASM752C Engineering Systems and Power Management

Box 6 of 109	NASM751A Design, Fabricate, Deliver, and Install Space Area Turn Table
Box 6 of 109	NASM741C CPM Sub-Network of NASM Activity
Box 6 of 109	NASM731C Grandstand Theater
Box 6 of 109	NASM721C Experimentarium (2 folders)
Box 6 of 109	Planetarium and A&S Building
Box 6 of 109	NASM701A Floor Covering for Building
Box 6 of 109	NASM701A Floor Covering for Aircraft Building
Box 6 of 109	NASM671 Evaluation of Probability of Flooding on Potomac River
Box 6 of 109	NASM653A Apply Glass Cloth to Joints and to Cover Roof of Metal Building
Box 6 of 109	Air and Space Metal Building Air Conditioning
Box 7	
Box 7 of 109	SI725 Air Conditioning Contracts (2 folders)
Box 7 of 109	NASM651C Museum Planning - Preliminary Design
Box 7 of 109	NASM - Miscellaneous
Box 7 of 109	Miscellaneous Service Contracts
	Renwick Gallery Summary: Renwick Gallery
Box 7 of 109	REN712B Finish and Install Conduit Bank for Additional Electrical Service to Gallery
Box 7 of 109	REN711A Additional Chiller, Condenser, Cooling Tower to Gallery (4 folders)
Box 7 of 109	Maintenance Manuals
Box 7 of 109	Existing Conditions - Photographs, November 2, 1970
Box 7 of 109	Submittals for Renwick Building
Box 7 of 109	REN701B Modifications for Initial Exhibits (2 folders)

Box 7 of 109 REN701B Alteration and Restoration of Building

Box 7 of 109 REN661C Alteration Project for Court of Claims Building

Box 8

Box 8 of 109 REN661C Elevators

Box 8 of 109 Renwick - Miscellaneous

Box 8 of 109 Renwick Building Exterior - Photographs

Box 8 of 109 Renwick Gallery Design

History and Technology Building
Summary: History and Technology Building

Box 8 of 109 HTB752A Exhibit on the History of American Banking

Box 8 of 109 HTB37410A Museum Shops

Box 8 of 109 HTB749A S.S. Oak Exhibit - Maritime Hall

Box 8 of 109 HTB748A Suiting Everyone Hall

Box 8 of 109 HTB745B Environmental Additions to Musical Instruments Laboratory

Box 8 of 109 HTB744A Addition to Fire Protection System (2 folders)

Box 8 of 109 HTB755B Sprinkler System for Conservation Analytical Laboratory (CAL)
- Basement

Box 8 of 109 HTB743B Of the People, By the People, For the People Exhibit

Box 8 of 109 HTB742A Expansion and Modifications to CAL (3 folders)

Box 8 of 109 HTB741C Glazing Modification - Fifth Floor

Box 8 of 109 HTB732B Exterior Lighting - FAPG, MNH, HTB

Box 8 of 109 Painting Interior Exhibit Area, Office Space, Garage

Box 8 of 109 HTB731C Additional Library Space - Sixth Floor

Box 8 of 109 MHT729B Construct New Stage Over Existing Hall of Musical
Instruments

Box 8 of 109 MHT728A Removal of Escalators at North Entrance

Box 8 of 109	MHT727A Sanitary Sewer Extension (2 folders)
Box 8 of 109	MHT726C Construction of McGraw Hill Bookstore
Box 8 of 109	MHT725C Exhibit Hall - American Maritime Enterprise
Box 8 of 109	MHT724C Exhibit on Productivity - Iron and Steel Hall
Box 8 of 109	MHT722C Specimens - Graphic Arts Hall
Box 8 of 109	MHT7114A Conversion and Extension of Sprinkler System - Third Floor East
Box 8 of 109	MHT7113A Construct and Install Walls, Platforms, Exhibit Cases, etc. for Halls of Numismatics and Graphic Arts
Box 8 of 109	MHT7112A Expansion of Guard Office
Box 8 of 109	MHT7111A Conversion to Steel Insect Cabinets
Box 8 of 109	MHT7110C Install 5 30-Ampere Circuits in Existing Conduit from OLA and OLB Panels, Replace Lights on North Terrace
Box 8 of 109	MHT719C IBM Exhibit on First Floor
Box 8 of 109	MHT718A Fire Protection at MHT Building
Box 8 of 109	MHT7176C Bicentennial Celebration Pavilion
Box 9	
Box 9 of 109	HTB - Miscellaneous
Box 9 of 109	MHT716A Interior Painting
	Natural History Building Summary: Natural History Building
Box 9 of 109	NHB7610B Sprinkler Additions
Box 9 of 109	NHB767A Caulk Blocks Expansion Joints and Gutter at South Retaining Wall
Box 9 of 109	NHB675 Meteorite Saw (3 folders)
Box 9 of 109	NHB763A Sprinkler Installation - Hall 29
Box 9 of 109	NHB761A HVAC Update

Box 9 of 109	NHB762A Elevator Alterations
Box 9 of 109	NHB7513B Installation of Sprinkler Systems
Box 9 of 109	NHB7513B Sprinkler Additions
Box 9 of 109	Fire Protection System Specifications
Box 9 of 109	NHB - Miscellaneous
Box 9 of 109	NHB742B Two Escalators Between Ground Floor Foyer and First Floor Rotunda
Box 9 of 109	NHB745A Mineral Science Security Vault (2 folders)
Box 9 of 109	NHB746A Air Filtration System (3 folders)
Box 9 of 109	NHB747A Air Duct Revisions to North Hall, Ground Floor
Box 9 of 109	NHB748B Lighting and Power (Our Changing Land Exhibit) Exhibit Hall
Box 9 of 109	NHB753B Cafeteria Area in the West Court
Box 9 of 109	NHB754B South America (A Continent and Its Culture) - Hall 23
Box 10	
Box 10 of 109	NHB755B South America (A Continent and Its Culture) - Hall 23 - New Ceiling - Mechanical and Electrical
Box 10 of 109	NHB757A Reflected Ceiling Plan (Our Changing Land Exhibit) - North Hall
Box 10 of 109	NHB759B Provide Engineering Services to Cover Mechanical and Electrical Utilities for Addition to West Court
Box 10 of 109	NHB7511A SI Library
Box 10 of 109	NHB7510A Additional Drinking Fountains
Box 10 of 109	NHB 7512A Botany Greenhouse (2 folders)
Box 10 of 109	NHB7511A SI Library
Box 10 of 109	McNabb Association
Box 10 of 109	NHB763B Sprinkler Installation - Hall 29

	Hirshhorn Museum and Sculpture Garden Summary: Hirshhorn Museum and Sculpture Garden
Box 10 of 109	Preliminary Drawings - Pre-construction (4 folders)
	Box 11
Box 11 of 109	Construction Photographs
Box 11 of 109	HMSG - Miscellaneous
	Arts and Industries Building Summary: Arts and Industries Building
Box 11 of 109	Glassware Pavilion
Box 11 of 109	Hall - Light
Box 11 of 109	WD Floor - A&I South
Box 11 of 109	FC-6-20545 Museum Shop
Box 11 of 109	Steam Engine Platform
Box 11 of 109	FC-5-49161 Partition Modifications Correspondence
Box 11 of 109	A&I - Miscellaneous
Box 11 of 109	FC-5-51199 Install Wood Flooring in South Hall - 1876 Centennial Exhibition (3 folders)
Box 11 of 109	PC-6-20545 Northeast Court Museum Shop (3 folders)
Box 11 of 109	CP-6-20886 Millwork Museum Shop (4 folders)
Box 11 of 109	FC-6-61145 South Entrance Restoration (3 folders)
Box 11 of 109	Museum Shop - Approved Samples
Box 11 of 109	FC-5-50727 Painting of Decor Stencils
Box 11 of 109	FC-5-51081 Painting Exhibit Halls and Rotunda (2 folders)
Box 11 of 109	FC-6-61159 Manufactures Hall - Blue Ridge Cabinetmakers
Box 11 of 109	FC-4-61680 R&R of Range Areas
Box 11 of 109	Air and Space Museum

Box 11 of 109	FC-5-51795 Air Compressor (3 folders)
Box 11 of 109	FC-5-52915 Three Additional Associates Classrooms (4 folders)
Box 11 of 109	FC-5-51938 Fabrication of Steam Engine Platforms
Box 11 of 109	FC-5-46249 Space Suit Exhibit (3 folders)
Box 11 of 109	FC-3-10831 Rest Rooms
Box 11 of 109	FC-4-62803 Range Areas (3 folders)
Box 11 of 109	FC-5-49161 Partition Modification
Box 11 of 109	FC-5-49161 Southeast Court Modifications and SI Associate Offices
Box 11 of 109	FC-4-63611 Life on Earth (3 folders)
Box 11 of 109	Renovation and Restoration - Daily Job Reports, February 1974-March 1976
Box 11 of 109	Grunley Claim
Box 11 of 109	Grunley-Walsh Project Reports, 1975-1976
Box 11 of 109	Certificates of Performance and Operation
Box 11 of 109	Anticipated Work Schedules
Box 11 of 109	FC-5-51794 Woodworking and Metalworking Machine Platforms
Box 11 of 109	FC-5-51292 1876 - West Hall - Norwalk Steam Engine Support Framing (3 folders)
	Renwick Gallery Summary: Renwick Gallery
Box 11 of 109	FC-3-08891 Roof Railing and Light (2 folders)
Box 11 of 109	FC-5-50718 Modern Consciousness Exhibit (2 folders)
Box 11 of 109	FC-6-63002 Galleries 102, 103, 104
	Box 12
Box 12 of 109	FA-4-65481 Man Made Mobile - The Western Saddle
Box 12 of 109	FC-4-65481 Additions to Gallery 206

Box 12 of 109	FC-5-50014 Renwick Gallery (2 folders)
Box 12 of 109	FC-4-62212 Statues
	Arts and Industries Building Summary: Arts and Industries Building
Box 12 of 109	FC-6-60605 Fixtures per Hall
Box 12 of 109	HVAC, Plumbing, Sprinkler
Box 12 of 109	HVAC
Box 12 of 109	Change Orders and Modifications
Box 12 of 109	Change Orders CP 14-CP 74 (61 folders)
	Box 13
Box 13 of 109	Change Orders CP 1-CP 13 (13 folders)
Box 13 of 109	Power System Study (3 folders)
Box 13 of 109	Relocation of Office of Equal Opportunities (OEO)
Box 13 of 109	Archives (4 folders)
Box 13 of 109	Arts and Industries Building - Miscellaneous
	History and Technology Building Summary: History and Technology Building
Box 13 of 109	Second Floor - Part Plan - Unit C
Box 13 of 109	Third Floor - Part Plan - Unit C
Box 13 of 109	Fire Control System, July 23, 1975
Box 13 of 109	Exhibit Construction Specifications, Second Floor, West Wing
Box 13 of 109	Construction Specifications for Canopy and Ramp - Nation of Nations
Box 13 of 109	Ramp and Canopy Contract
Box 13 of 109	Olomana Locomotive
	Box 14

Box 14 of 109	FC-707058 Photography Laboratory (2 folders)
Box 14 of 109	FC-707058 Printing and Photographic Services (2 folders)
Box 14 of 109	Photography Laboratory, 1978
Box 14 of 109	FC-4-66162 Receiving Facility in Basement - Contract Documents
Box 14 of 109	FC-706007 Atom Smasher Exhibit (4 folders)
Box 14 of 109	Air Handlers 4 and 5
Box 14 of 109	FC-705054 Replacement HVAC Units (3 folders)
Box 14 of 109	Conference Room Cases
Box 14 of 109	FC-708-SIL Maritime Hall (3 folders)
Box 14 of 109	FC-5-531604 Anon Lighting and Maurice Electric
Box 14 of 109	FC-5-53160-1 Nation of Nations Light Fixtures (2 folders)
Box 14 of 109	FC-6-68327 Storage Room
Box 14 of 109	FC-5-53990 Anon Lighting and Branstow
Box 14 of 109	FC-5-51999 Physical Science Renovation Plan (4 folders)
Box 14 of 109	Fire Extinguishing System
Box 14 of 109	Executive Dining Room (2 folders)
Box 14 of 109	Nation of Nations - Requirements and Specifications
Box 14 of 109	FC-5-50845 Ramp and Canopy - Libra Engineering
Box 14 of 109	Sandblasting Granite Steps
Box 14 of 109	Poster Display - East Shop, North Wall

Box 15

Box 15 of 109	Marriott (2 folders)
	Natural History Building Summary: Natural History Building
Box 15 of 109	Construction Contracts - General Conditions, 1976

Box 15 of 109	Wall Plans for Hall 23
Box 15 of 109	Hall 23 Sprinklers
Box 15 of 109	Sprinkler and Duct Work
Box 15 of 109	Environmental Room Shelter for Osteo-Prep Laboratory
Box 15 of 109	Our Changing Land - Lighting and Power
Box 15 of 109	New Acoustical Ceiling
Box 15 of 109	FC-6-62142 Conditions and Requirements
Box 15 of 109	West Court Addition - Utility Services
Box 15 of 109	East Court Greenhouse Performance Specifications
Box 15 of 109	FC-6-60737 Sprinkler Fire Pumping Systems (2 folders)
Box 15 of 109	FC-5-48503 Escalators
Box 15 of 109	Smithsonian Institution Libraries (SIL) - First Floor - HVAC
Box 15 of 109	S7C-2-3656 Correspondence (Library)
Box 15 of 109	Exterior Lighting
Box 15 of 109	Lower Level Lighting Plan
	L'Enfant Plaza Summary: L'Enfant Plaza
Box 15 of 109	FC-5-50220 L'Enfant, Accounting Division Contract
Box 15 of 109	FC-4-66967 Corning Construction Company - Alternative to Third Floor OFPES and Environmental Science Offices
	Anacostia Neighborhood Museum Summary: Anacostia Neighborhood Museum
Box 15 of 109	FC-6-61448 Contract Documents
Box 15 of 109	CP-6-2-329 Partitions and Storage - Correspondence
Box 15 of 109	Anacostia - General Correspondence

Box 16

Box 16 of 109	CP-6-20329 Partitions and Storage
Box 16 of 109	FC-4 Belmont Estates Connecting Trailer
Box 16 of 109	Belmont Estates Fire Damage
Box 16 of 109	Design and Production Laboratory - Fire Damage
Box 16 of 109	Anacostia Fire Job
Box 16 of 109	FC-6-71092 Fire Damage (4 folders)
Box 16 of 109	FC-3-09525 Design and Production Laboratory Submittals
Box 16 of 109	FC-3-09525 Design and Production Laboratory Progress Photographs
Box 16 of 109	FC-3-09525 Design and Production Laboratory
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Concrete Testing (2 folders)
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Proposal
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Approved Transmittals (2 folders)
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Payment Requisitions and Correspondence
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Request for Proposals
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Correspondence
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Payments to Contractors
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Contract Documents
Box 16 of 109	FC-3-09525 Design and Production Laboratory - Correspondence, November 17, 1975
	Cooper-Hewitt Museum Summary: Cooper-Hewitt Museum
Box 16 of 109	NMD Reports
Box 17	
Box 17 of 109	CP-5-31175 Carnegie Mansion Renovation

Box 17 of 109	Smithsonian Institution Correspondence
Box 17 of 109	Wood Doors
Box 17 of 109	Steamfitter and Sheet Metal Strike
Box 17 of 109	Building Development Objections
Box 17 of 109	NMD Plumbing
Box 17 of 109	Le Messurier
Box 17 of 109	NMD Weekly Report
Box 17 of 109	NMD Electrical
Box 17 of 109	Status of Work in Progress - Exhibition
Box 17 of 109	Opening Exhibition
Box 17 of 109	HVAC Completion Testing
Box 17 of 109	Temperature - Heat
Box 17 of 109	Leaders and Drains
Box 17 of 109	CP-5-31175 Electrical Duplex Convenience Receptacles
Box 17 of 109	NMD HVAC
Box 17 of 109	Circuit Changes
Box 17 of 109	Conservatory and Miscellaneous Iron and Steel for Restoration Work
Box 17 of 109	Conservatory - Monitor Vents and Outer Dome
Box 17 of 109	Chandeliers - First Floor Main Hall
Box 17 of 109	Fan Removal - Attic
Box 17 of 109	Edison Price
Box 17 of 109	HVAC Tests
Box 17 of 109	Fourth Floor Closet Under Attic Stairs
Box 17 of 109	Toilet Accessibility

Box 17 of 109	Fourth Floor Electrical
Box 17 of 109	John Dobkin
Box 17 of 109	Exhibit
Box 17 of 109	Flack and Kurte - Grounding (Electrical)
Box 17 of 109	Second Floor - Delete Duct 207
Box 17 of 109	Doors - East End, Hall 201 and Elevator
Box 17 of 109	Revised Details, Room 214
Box 17 of 109	Job Conditions, Details, and Extras
Box 17 of 109	T. O. Between Rooms 207 and 208
Box 17 of 109	Tile Colors
Box 17 of 109	Location of Lavatory Room 416
Box 17 of 109	Corridor 211 - Plaster Soffit and Ceiling
Box 17 of 109	Main Hall Use - Security, etc.
Box 17 of 109	Requests for Work, October 20, 1975
Box 17 of 109	NMD Job Meetings
Box 17 of 109	Proposed Revisions, etc. re: Dobkin
Box 17 of 109	Contract Modification Sheets
Box 17 of 109	NMD New Again Construction
Box 17 of 109	Current
Box 17 of 109	Entrance to Conservatory, Room 109A
Box 17 of 109	New Again Construction - Current Correspondence
Box 17 of 109	Hardy Holzman Pfeiffer Associates (HHPA) Correspondence (2 folders)
Box 17 of 109	Credits and Extras - Field Conditions
Box 17 of 109	HHPA Meeting Memoranda

Box 17 of 109	Insurance Value
Box 17 of 109	Door Opening Between Room 207 and 215
Box 17 of 109	Sketches
Box 17 of 109	Punch Lists
Box 17 of 109	Contract Modifications
Box 17 of 109	Memoranda
Box 17 of 109	Memoranda and Cooper-Hewitt Correspondence
Box 17 of 109	Special Condensing Unit
Box 17 of 109	Front Entrance Doors
Box 17 of 109	Exterior Flagpoles and Associated Lighting, Southwest Corner
Box 17 of 109	Mixing Valve and Hose Bibb
Box 17 of 109	Leaders
Box 17 of 109	NMD Requisitions for Payments
Box 17 of 109	G. C. Elevator Jack Hole
Box 17 of 109	Electrical - Extras
Box 17 of 109	Intrusion System (3 folders)
Box 17 of 109	Electrical Boxes
Box 17 of 109	Alarm and Security System
Box 17 of 109	HVAC C. O. - Revised Drawings
Box 17 of 109	G. C. Revisions - Second Floor, Opening 206A
Box 17 of 109	Anti-Slip Abrasive Tread Strips for Main Stair
Box 17 of 109	HHPA Addendum #2
Box 17 of 109	Library Wing Construction Drawings
Box 17 of 109	Material Manuals

Box 17 of 109	Miscellaneous Restoration (2 folders)
Box 17 of 109	Electrical - New Fix, Room 14
Box 17 of 109	G. C. and Electrical
Box 17 of 109	Revision - Third Floor Rooms
Box 17 of 109	Remedial Work on Fourth Floor
Box 17 of 109	Condensate Pipe Insulation
Box 17 of 109	Remove Existing Stair, Mechanical Room C15
Box 17 of 109	Electrical - New Floor Outlets
Box 17 of 109	Basement Rooms B07 and B08
Box 17 of 109	Plumbing Extras (3 folders)
Box 17 of 109	G. C. Structural Steel
Box 17 of 109	G. C. Wall Surface/Resilient Flooring
Box 17 of 109	Alternates
Box 18	
Box 18 of 109	Extension of Time
Box 18 of 109	Third Floor - VAT Floor
Box 18 of 109	VAT Flooring and Vinyl Base - Third Floor Rooms 312-316
Box 18 of 109	Removal of Existing Plaster Ceiling - Fourth Floor
Box 18 of 109	Contract Modifications (2 folders)
Box 18 of 109	Change Orders
Box 18 of 109	NMD Miscellaneous
Box 18 of 109	Fireplace Removal - Room 304
Box 18 of 109	Revisions to Domestic Water Pump
Box 18 of 109	Electrical Outlets for Water Cooler

Box 18 of 109	Second Floor Rooms 204-215 (2 folders)
Box 18 of 109	New 18" Duct - Basement
Box 18 of 109	Remove Door IOIB Aon Panel - First Floor
Box 18 of 109	Remove Wainscot - Rooms 111-112 (2 folders)
Box 18 of 109	Plumb Risers - East Side
Box 18 of 109	Ceiling Heights - Third Floor Room 308
Box 18 of 109	Second Floor Revisions - Rooms 209 and 209A
Box 18 of 109	Conservatory
Box 18 of 109	Dummy Enclosures - First, Second, and Third Floors
Box 18 of 109	Additional Demolition - Fourth Floor
Box 18 of 109	Ducts Volume Regulator - Fourth Floor
Box 18 of 109	Remove Ornament from Ceiling - Room 205
Box 18 of 109	Additional Anodized Grilles, etc.
Box 18 of 109	Revision of Existing Exhaust Duct - First and Third Floor Toilets
Box 18 of 109	Insulation of Exposed Ductwork
Box 18 of 109	Sheet Metal Work - First Floor Coat Room
Box 18 of 109	Extra Ductwork at New Stair Between First and Second Floor
Box 18 of 109	Extra Ductwork on First Floor
Box 18 of 109	Removal of Marble Plinths in Conservatory
Box 18 of 109	Elevator
Box 18 of 109	Sprinkler in Cellar
Box 18 of 109	Granite Sidewalk Slab
Box 18 of 109	New Concrete Steps - Exit Passageway in Basement
Box 18 of 109	Modifications of Second Floor Elevator Door

Box 18 of 109	New Wood Trim - Elevator Entrance on First Floor
Box 18 of 109	Coal Bin Roof Slab
Box 18 of 109	Conservatory - Additional Work
Box 18 of 109	New Partition Between B22 and B26 - Basement Floor
Box 18 of 109	Basement Finishes - Rooms B17, B18, B19, and B21
Box 18 of 109	Bookshelves - Display Panels
Box 18 of 109	Delete Metal and Glass Partition Between Vestibule (Room 109) and Conservatory
Box 18 of 109	Delete Nine Type A Fixtures, Room 306
Box 18 of 109	Extending Condenser Unit Slab
Box 18 of 109	Third Floor East Elevator at Elevator
Box 18 of 109	Close Up Windows - SK PLY111W Gallery
Box 18 of 109	Revision to Rooms 214, 206, 215 - Collection Display
Box 18 of 109	Electrical Revisions to First and Second Floors
Box 18 of 109	Coat Room Revision
Box 18 of 109	Revisions to Rooms 207-209
Box 18 of 109	Planned Revision to Rooms 203-204
Box 18 of 109	Revision to Paving at Entrance
Box 18 of 109	Ornamental Grilles - First and Second Floor
Box 18 of 109	Ornamental Grille at Room 106A
Box 18 of 109	Canopy
Box 18 of 109	Cap of Headers - Existing Unused Expansion Tank
Box 18 of 109	Announcement Board
Box 18 of 109	Revised Fourth Floor
Box 18 of 109	New Radiator in Maintenance Storage

Box 18 of 109	Elevator - Hold Door Open Device
Box 18 of 109	Duplex Convenience Receptacles - Third Floor
Box 18 of 109	Transom Glass Front Entrance
Box 18 of 109	Add Six New K Fixtures - First Floor Hall
Box 18 of 109	Painting
Box 18 of 109	Paper Conservatory Laboratory - Room B06
Box 18 of 109	Shutters for Blocked Up Windows
Box 18 of 109	Duplex Convenience Receptacles
Box 18 of 109	New Roof
Box 18 of 109	Garden Walk - New Paving
Box 18 of 109	Painting - Third Floor Rooms 301-302
Box 18 of 109	Elevator #2 Machine Room - Housing and Roof Hatch
Box 18 of 109	Display Panel - Room 202
Box 18 of 109	New 4" Concrete Block Enclosure - Attic East End
Box 18 of 109	Conservatory Lights
Box 18 of 109	Second Floor Wood Fillers Around Ducts
Box 18 of 109	Door Alarm Locks
Box 18 of 109	Transom Glass - Interior Main Entrance Hall
Box 18 of 109	Rooms C25-C30
Box 18 of 109	Repaint Rooms 301-302
Box 18 of 109	New Light Fixtures - Room B05
Box 18 of 109	Receiving Room Revision
Box 18 of 109	Enclose Rectangular Ducts - Rooms 407 and 415
Box 18 of 109	Removal of Unused Grilles - New Stair Hall

Box 18 of 109	Waterproof Dormers
Box 18 of 109	Duct Enclosures - Rooms 406-410
Box 18 of 109	Conservatory and Vestibule Floor Tiles
Box 18 of 109	Attic Elevator Shaft
Box 18 of 109	New Floor Outlets
Box 18 of 109	Plaster Impregnated Wall Covering
Box 18 of 109	Refinish Woodwork
Box 18 of 109	Fourth Floor Light Track - South Wall
Box 18 of 109	Plywood Panels at Windows - Rooms 403-405
Box 18 of 109	Slab Replacement - Coal Bin
Box 18 of 109	Closure at Door to Stair #2
Box 18 of 109	Electrical Outlets - Room 114
Box 18 of 109	Door Louver - Room 202
Box 18 of 109	Fourth Floor Completion
Box 18 of 109	Plaster Ceiling - Rooms 401-402
	Silver Hill Summary: Silver Hill
Box 18 of 109	FC-5-52970 Mezzanine Changes to Building 24 - Payment to Contractor
Box 18 of 109	FC-5-52970 Mezzanine Changes to Building 24 - Shop Drawings
Box 18 of 109	FC-5-52970 Mezzanine Changes to Building 24 - Correspondence
Box 18 of 109	FC-5-52970 Mezzanine Changes to Building 24 - Contract Documents
	Box 19
Box 19 of 109	FC-4-66571 Building 24 - Progress Photographs
Box 19 of 109	FC-4-66571 Building 24 - Specifications
Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Payments to Contractor

Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Correspondence
Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Specifications
Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Contract Documents
Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Dust Collecting System
Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Accepted Proposals
Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Approved Shop Drawings and Materials
Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Approval Transmittals
Box 19 of 109	FC-4-66571 Buildings 13 and 14 - Requests for Proposals
Box 19 of 109	FC-4-62483 Silver Facility
Box 19 of 109	FC-5-48222 Loading Dock and Ramp (4 folders)
Box 19 of 109	FC-5-43222 Dock Leveler
Box 19 of 109	FC-4-62483 Fence Contract
Box 19 of 109	FC-5-47786 Dock Leveler - Tester Corporation
Box 19 of 109	FC-6-20135 Building 14 - Barn Exhibit Reconstruction
Box 19 of 109	Building 24 - Payrolls
Box 19 of 109	Building 23 (2 folders)
Box 19 of 109	Silver Hill Gas Company System
Box 19 of 109	Flammable Storage Shed (2 folders)
	Chesapeake Bay Center/Chesapeake Bay Center for Environmental Studies Summary: Chesapeake Bay Center/Chesapeake Bay Center for Environmental Studies
Box 19 of 109	Spray Irrigation Plan
Box 19 of 109	PC-3-0980 Dormitory
Box 19 of 109	Minor Contracts

Box 19 of 109	FC-4-66012 Payment to Contractor
Box 19 of 109	FC-4-65800 Diesel Generator
Box 19 of 109	PC-74-2748 Visitor Center Dormitory (3 folders)
Box 19 of 109	Structural Engineering
Box 19 of 109	Chesapeake Bay Center - Miscellaneous
	Natural History Building Summary: Natural History Building
Box 19 of 109	Botany Greenhouse
	Freer Gallery of Art Summary: Freer Gallery of Art
Box 19 of 109	FC-4-63768 Sprinkler System (5 folders)
Box 19 of 109	Catalog of Architectural Drawings
Box 19 of 109	FC-5-47627 Window Grills (2 folders)
	Fine Arts and Portrait Gallery Summary: Fine Arts and Portrait Gallery
Box 19 of 109	FC-6-60746 Courtyard Modification
Box 19 of 109	Wiring Diagram
Box 19 of 109	Emergency Generator
	Hirshhorn Museum and Sculpture Garden Summary: Hirshhorn Museum and Sculpture Garden
Box 19 of 109	Humidification Deficiency
Box 19 of 109	Doors, Windows, Glass
	National Air and Space Museum Summary: National Air and Space Museum
Box 19 of 109	FC-5-51608 Automobile Parking Facility (2 folders)
Box 19 of 109	FC-5-49658 Hydraulic Lift
Box 19 of 109	FC-5-53255 Vertical Flight Exhibit

Box 19 of 109	FC-5-52466 Apollo to the Moon Exhibit
Box 19 of 109	FC-5-53197 Flight Exhibition
Box 19 of 109	FC-5-47888 Spacearium Turntable (3 folders)
Box 19 of 109	Planetarium Elevator (3 folders)
Box 19 of 109	FC-801313 Stairwell Windscreens
Box 20	
Box 20 of 109	FC-708108 Exploring the Planets (4 folders)
Box 20 of 109	Kitchen and Dining Drawing
Box 20 of 109	Third Floor Cafe (4 folders)
Box 20 of 109	FC-708109 General Aviation Exhibit (4 folders)
Box 20 of 109	FC-70888 Library (3 folders)
Box 20 of 109	Museum Shop (2 folders)
Box 20 of 109	FC-6-65097 Museum Sales Shop (4 folders)
Box 20 of 109	FC-6-68604 Museum Shop
Box 20 of 109	FC-66887 Museum Shop - Singleton Electric (4 folders)
Box 20 of 109	FC-6-66889 Museum Shop (3 folders)
Box 20 of 109	FC-6-66885 Museum Shop (4 folders)
Box 20 of 109	FC-6-66886 Museum Shop (4 folders)
Box 20 of 109	FC-6-66884 Museum Shop (4 folders)
Box 20 of 109	Museum Shop Demolition Plan
Box 20 of 109	FC-5-53956 Earthflight Mural
Box 20 of 109	FC-6-60460 Sculptured Pedestal
Box 20 of 109	Employment Openings
Box 20 of 109	FC-5-50736 Spaceflight Mural

Box 20 of 109	FC-5-54034 Scaffolding
Box 20 of 109	FC-6-60354 Detector System (2 folders)
Box 20 of 109	Automobile Parking Facility
Box 20 of 109	FC-6-69782 Flag Pole (3 folders)
Box 20 of 109	FC-706456 Curved Wall - Gallery 207
	Smithsonian Institution Building Summary: Smithsonian Institution Building
Box 20 of 109	South Yard Development (2 folders)
Box 20 of 109	Stone and Masonry and Terrazzo and Tile
Box 20 of 109	A1752A SI Associates Office and Classroom
	Box 21
Box 21 of 109	SIB752A Construction of Offices and Mezzanine
Box 21 of 109	SIB762A Flammable Storage Shed
Box 21 of 109	Opening Pantry to Dining Room
Box 21 of 109	Interior Wood
Box 21 of 109	Special Public Entrance Doors
Box 21 of 109	SI Renovation - Acoustical Work
Box 21 of 109	SI Renovation - Finish Hardware
Box 21 of 109	SI Renovation - Dry Wall Construction
Box 21 of 109	SI Renovation - Architectural Metal, Doors, Frames, Enclosures
Box 21 of 109	SI Renovation - Miscellaneous Metal
Box 21 of 109	SI Renovation - Lath and Plastic
Box 21 of 109	Elevators (2 folders)
Box 21 of 109	Secretary's Office (Mr. Ripley/Mr. Bradley)
Box 21 of 109	Demolition of Existing Conditions Plan, August 1, 1975

Box 21 of 109	FC-3-09527 Humidification System (2 folders)
Box 21 of 109	EC-4-SF\$-64398 Lambs Tonglues - A&I
Box 21 of 109	FC-4-63769 Sprinkler System (4 folders)
Box 21 of 109	FC-4-63472 Great Hall
Box 21 of 109	FC-4 Step Railings
Box 21 of 109	Crypt Project
Box 21 of 109	Wood and Metal Details
	Natural History Building Summary: Natural History Building
Box 21 of 109	FC-5-50258 Ceiling System for Hall 23 (5 folders)
Box 21 of 109	FN-5-48465 Restoration of Rotunda Area (3 folders)
Box 21 of 109	FN-5-48455 Rotunda Restoration (2 folders)
Box 21 of 109	FC-4-66826 Hall 10 (3 folders)
Box 21 of 109	FC-4-64314 Study of Man Mezzanine and Office Space (5 folders)
Box 21 of 109	FC-4-10708 Baird Auditorium
Box 21 of 109	FC-5-48533 Our Changing Land - Sprinkler and Duct System (5 folders)
Box 21 of 109	FC-4-64459 Hall 6, First Floor (5 folders)
Box 21 of 109	FC-4-67635 Construct Three Platforms - Hall 6
Box 21 of 109	PC-5-31876 Marriott Demolition
Box 21 of 109	FC-5-47402 Our Changing Land - Electrical System (3 folders)
Box 21 of 109	FC-4-65567 Two Power Operators to Operate Two Bronze Doors (2 folders)
Box 21 of 109	FC-5-48638 Hall 23 (4 folders)
Box 21 of 109	FC-5-49534 Dropped Ceiling and Ground Foyer (2 folders)
	Box 22

Box 22 of 109	FN70085900 Hall 23 - Detector System (2 folders)
Box 22 of 109	LG-6-60737 Sprinkler Fire Pumping Systems (4 folders)
Box 22 of 109	FC-5-49146-1 Environmental Room Shelter for Osteo-Prep Facility (4 folders)
Box 22 of 109	Universal Contracting
Box 22 of 109	FC-5-48503 Escalators (4 folders)
Box 22 of 109	FC-5-49534 Dropped Ceiling and Ground Foyer (3 folders)
Box 22 of 109	FC-6-62049 Coat Room at Portico (4 folders)
Box 22 of 109	CP-6-21336 Dining Room Stained Glass
Box 22 of 109	FC-4-65799 Modification of Library
Box 22 of 109	FC-4-67956 New Security Work Area
Box 22 of 109	CP-5-31987 West Court Addition (3 folders)
Box 22 of 109	New Air Filters
Box 22 of 109	Coat Room
Box 22 of 109	RPC-5-32570 West Court Progress Photographs
Box 22 of 109	West Court Concrete Test Reports
Box 22 of 109	West Court Inspection Reports
Box 22 of 109	West Court Progress Payments
Box 22 of 109	West Court Millwork and Museum Shop
Box 22 of 109	West Court Utilities
Box 22 of 109	West Court Revisions
Box 22 of 109	RPC-5-32570 West Court Submittals
Box 22 of 109	RPC-5-32570 West Court Inspection Reports
Box 22 of 109	HVAC Modifications
Box 23	

Box 23 of 109	FC-6-62142 West Court - Utilities Services (4 folders)
Box 23 of 109	FC-6-64142 West Court Facilities
Box 23 of 109	NHB756A Osteo-Prep Facility
Box 23 of 109	Hall 26 Demolition
Box 23 of 109	Sprinkler System
Box 23 of 109	FC-706896-10 J. W. Conway Roofing (2 folders)
Box 23 of 109	FC-706896 Roof Repairs (5 folders)
Box 23 of 109	Sprinkler Additions
Box 23 of 109	FC-70085900 Hall 23 Fire Detection (3 folders)
Box 23 of 109	FL-6-63963 SI Libraries(2 folders)
Box 23 of 109	SI Libraries - HVAC Modifications
Box 23 of 109	FA-6-63963 SI Libraries - New Heating (2 folders)
Box 23 of 109	FC-5-52909 Botany Greenhouse - Phase I (5 folders)
Box 23 of 109	Personnel Safety Nets
Box 23 of 109	FC-6-68032 Mineral Preparation Laboratory (4 folders)
Box 23 of 109	FC-5-47402 Our Changing Land - Electrical
Box 23 of 109	FC-5-48638 Hall 23 - Drywall Partitions
Box 23 of 109	FN-5-48465 Restoration of Columns - Rotunda and Ambulatory
Box 23 of 109	F-5-49534 North Hall Ceiling
Box 23 of 109	FC-5-48533 Our Changing Land - Mechanical
Box 23 of 109	FC-6-63609 Hall 29 Sprinkler System
Box 23 of 109	Hall 23 Ceiling and Sprinkler
Box 23 of 109	Indian Costumes Exhibition
Box 23 of 109	Conservation Analytical Laboratory (2 folders)

Box 23 of 109	FL-6 Demolition
Box 23 of 109	FC-803433 Hall 10 Exhibition (3 folders)
Box 23 of 109	FC A&I Shutters - Room 2209
Box 23 of 109	FC-703105-00 HVAC Repairs (5 folders)
Box 23 of 109	North Foyer Smoke Detection
Box 23 of 109	Hall of Beautiful Things
Box 23 of 109	FC-5-51799-1 Mammal Preparation Facility - Phase II (4 folders)
Box 24	
Box 24 of 109	FC-4-66827 Foyer Demolition (4 folders)
Box 24 of 109	FC-706103 Hall of Beautiful Things - Sprinkler System (4 folders)
Box 24 of 109	Sprinkler Additions
Box 24 of 109	FC Hall 26 - Second Floor (2 folders)
Box 24 of 109	Mineral Preparation Laboratory
Box 24 of 109	FC-6-60737 Fire Pump
Box 24 of 109	CP-6-21267 Museum Sales Shop (2 folders)
Box 24 of 109	FC-70086300 Hall 26 Fire Pump and Sprinkler (3 folders)
Box 24 of 109	FC-6-0741 South Wall (3 folders)
Box 24 of 109	FC-6-60738 Installation of Air Filter
Box 24 of 109	Hall 23 - Smoke Detection
Box 24 of 109	Personnel Nets
Box 24 of 109	Osteo-Prep Floor
Box 24 of 109	MNH731A Archives Modifications (2 folders)
Box 24 of 109	Anthropology Modifications - Ground Floor, West Range
Box 24 of 109	Study of Man

Box 24 of 109	NHB743A New Mezzanine and Office Space (2 folders)
Box 24 of 109	NHB743A South Wing, Ground Floor Modifications
Box 24 of 109	Insect Zoo
Box 24 of 109	SI Libraries Expansion
Box 24 of 109	Marriott Restaurant - West Court
Box 24 of 109	MNH732B Exterior Lighting - FAPG, MNH, and HTB
Box 24 of 109	MNH733A Interior Painting - Hall 11
Box 24 of 109	MNH741C Demolition of Hall 6
Box 24 of 109	MNH745A Mineral Sciences Security Work Area
	Box 25
Box 25 of 109	NHB744B Library Expansion - Phase II (4 folders)
	History and Technology Building Summary: History and Technology Building
Box 25 of 109	Renovation of Cafeteria
Box 25 of 109	CP-5-31014-1 Museum Shops - Alliance Woodworking, Inc.
Box 25 of 109	FC-5-46363 Museum Shops
Box 25 of 109	PN-5-32185-1 Banking in America (2 folders)
Box 25 of 109	Dibner Library (2 folders)
Box 25 of 109	FC-5-52651 Modify Executive Dining Room (3 folders)
Box 25 of 109	Contract Change #29
Box 25 of 109	Window Washing Contract Change
Box 25 of 109	Tools - Change Order 5B
Box 25 of 109	Automobiles - Change Orders 14 and 14A
Box 25 of 109	Change Order 20
Box 25 of 109	Heavy Machinery - Change Order 21

Box 25 of 109	Political History - Change Order 22
Box 25 of 109	Change Order 26
Box 25 of 109	Chemistry - Change Order 30
Box 25 of 109	Change Order 31
Box 25 of 109	Change Order 37
Box 25 of 109	Change Order 41
Box 26	
Box 26 of 109	Philately - Change Order 52 (2 folders)
Box 26 of 109	Stonework
Box 26 of 109	Doors
Box 26 of 109	Change Orders 8 and 9
Box 26 of 109	Exhibits and Interior Work
Box 26 of 109	Political History - Lincoln's Campaign Train
Box 26 of 109	Allyn Correspondence
Box 26 of 109	Calculations
Box 26 of 109	Snow Melting
Box 26 of 109	Structural Sketches and Information
Box 26 of 109	Radiator Enclosure
Box 26 of 109	Fourth and Fifth Floor Offices
Box 26 of 109	Outside Lighting
Box 26 of 109	Toilet Room and Details
Box 26 of 109	Marble Exterior Gross Areas
Box 26 of 109	Television Studio
Box 26 of 109	Apothecary Shop

Box 26 of 109	Corner Windows
Box 26 of 109	Second Floor Drawings
Box 26 of 109	First Floor, North Lobby
Box 26 of 109	Marble Base for Greenough Statue
Box 26 of 109	Physics of Astronomy - Change Order 26B
Box 26 of 109	Floor Inserts
Box 26 of 109	Negotiation Data
Box 26 of 109	Embellishments and Finishes
Box 26 of 109	Miscellaneous Contract Changes
Box 26 of 109	Fire Alarm
Box 26 of 109	Security System - Change Order 40
Box 26 of 109	Paint Schedule
Box 26 of 109	Apothecary Shop Photographs
Box 26 of 109	Mining - Change Order 1
Box 27	
Box 27 of 109	Growth of America - Change Order 5
Box 27 of 109	Costumes - Change Order 5
Box 27 of 109	Engine, Watercraft, Numismatics, and Special Exhibitions - Change Order 5
Box 27 of 109	Ceramics - Change Order 5
Box 27 of 109	Medical and Dental Health - Change Order 5A
Box 27 of 109	Watercraft Hall - Change Order 5C
Box 27 of 109	Electricity - Change Order 5C
Box 27 of 109	Railroad Hall - Change Order 5C
Box 27 of 109	Flag Hall - Change Order 6

Box 27 of 109	First Ladies Hall - Change Order 10
Box 27 of 109	Change Order 11
Box 27 of 109	Snack Bar - Change Order 13
Box 27 of 109	Photography - Change Orders 14 and 14A
Box 27 of 109	FC-6-69406 Objects Processing Room Extension (5 folders)
Box 27 of 109	FC-704788 Olomana Locomotive (3 folders)
Box 27 of 109	FC-6-68327 Bus Ramp
Box 27 of 109	FC-5-53331 Dibner Library - Associate Building (6 folders)
Box 27 of 109	FC-5-53990 Nation of Nations - Illuminating of Exhibits (3 folders)
Box 27 of 109	FC-5-50935 Nation of Nations - Phase II, Second Floor, West Wing (6 folders)
Box 28	
Box 28 of 109	CP-70077910 Person to Person (7 folders)
Box 28 of 109	FC-704259 Skid Proof Front Steps (2 folders)
Box 28 of 109	North Sprinkler Fire Pump Loop
Box 28 of 109	HTB747A Southwest Garage Receiving and Holding Room (2 folders)
Box 28 of 109	All Buildings Restoration and Renovation Fund Prior to FY 1972
Box 28 of 109	Fire, September 30, 1970
Box 28 of 109	HTB746A Nation of Nations Exhibit on the American People (2 folders)
	Arts and Industries Building Summary: Arts and Industries Building
Box 28 of 109	Basement Floor
Box 28 of 109	South Entrance
Box 28 of 109	Heating, Winter 1975
Box 28 of 109	West-North and North-West Ranges - Assignment Study, Personnel Division, December 1971

Box 28 of 109	AI715A Finish Interior Painting - A&I, NHB, HTB, FA&PG
Box 28 of 109	AI715A Exhibit Hall Painting, 1970
Box 28 of 109	Photographs - Interior
Box 28 of 109	Brick Restoration (West Entry) and Tile Floor in Vestibules
Box 28 of 109	AI725C Balloon Exhibit
Box 28 of 109	West-North Range - Electrical
Box 28 of 109	West-North Range - Original Specifications
Box 28 of 109	West-North Range ME22 - Filler Study (Structural)
Box 28 of 109	AI726A Northwest Range - Lower Level (SFC-2-3655-2)
Box 28 of 109	AI726A Northwest Range - Specifications
Box 28 of 109	Northwest Range, Lower Level - Office Space
Box 29	
Box 29 of 109	Index of Catalogue Drawings
Box 29 of 109	AI57 East Entrance Folding Door, 1957
Box 29 of 109	A&I Miscellaneous
Box 29 of 109	Northwest Flagpole Setting
Box 29 of 109	Cleaning and Painting
Box 29 of 109	Floor Plans and Window Details, 1879
Box 29 of 109	Painting Windows
Box 29 of 109	AI641A Space Study, October 1964
Box 29 of 109	Furniture Storage Space - Miscellaneous
Box 29 of 109	SF-70043000 Rail and Gate
Box 29 of 109	FC-6-69184 Information Booth (5 folders)
Box 29 of 109	Modifications to Personnel Office - Phases I and II

Box 29 of 109	FC-6-69479 SI Press (3 folders)
Box 29 of 109	FC-701818 Smoke Detection System (4 folders)
Box 29 of 109	FC-6-65236 OEO Offices, Northeast Pavilion, Third Floor (5 folders)
Box 29 of 109	FC-4-61680 Renovation and Restoration
Box 29 of 109	Millwork
Box 29 of 109	AI7511A Roof Plan
Box 29 of 109	FO-6-09937 Renovation of Offices (4 folders)
Box 29 of 109	South Yard Parking Lot
Box 29 of 109	Greenhouse
Box 29 of 109	Office of Computing Services - Computer Room
Box 29 of 109	FC-6-60936 Renovation of Roof and Windows Around Rotunda (5 folders)
Box 29 of 109	FC-5-51292 "1876" - West Hall (Norwalk Steam Engine Support Framing)
Box 29 of 109	FC-5-51794 Woodworking and Metalworking Machine Room
Box 29 of 109	AI753A Painting North, South, East, and West Halls
Box 29 of 109	For Post-Microfilm Action
Box 29 of 109	FC-6-65236 Door Frames
Box 29 of 109	AI7619A Fire Detection System
Box 30	
Box 30 of 109	CP-6-20886 Museum Shop - Millwork
Box 30 of 109	General Electric
Box 30 of 109	AI661A Fiscal Division
Box 30 of 109	CP-6-20545 Northeast Court Museum Shop
Box 30 of 109	AI7512 Archives, Northeast Range, Northeast Court, East-North Range
Box 30 of 109	FC-5-52915 Three Additional Associates Classrooms

Box 30 of 109	AI664 Computer Room
Box 30 of 109	AI6711A Automate Doors on Elevator
Box 30 of 109	FC-6-64079 Archives (6 folders)
	Hirshhorn Museum and Sculpture Garden Summary: Hirshhorn Museum and Sculpture Garden
Box 30 of 109	FC-705538 Front Elevator Doors
Box 30 of 109	SF-7055038 Freight Elevator Doors (2 folders)
Box 30 of 109	FC-70961 Smoke Detectors (2 folders)
Box 30 of 109	Swenson Drawings
Box 30 of 109	FC-6-70035 Humidification (8 folders)
Box 30 of 109	FC-6-62286 Concrete Planters
Box 30 of 109	FC-4-63995 Information Desk (2 folders)
Box 30 of 109	Paint Spray Booth
Box 30 of 109	Display Screens
	National Air and Space Museum at Arts and Industries Building Summary: National Air and Space Museum at Arts and Industries Building
Box 30 of 109	FC-5-145 Spacearium Turntable
Box 30 of 109	FC-5-46249 Space Suit
	Fine Arts and Portrait Gallery Summary: Fine Arts and Portrait Gallery
Box 30 of 109	FA-6-65238 Granite Gallery
Box 30 of 109	FC-6-64489 Galleries 341-342
Box 30 of 109	Courtyard
	National Mall Summary: National Mall
Box 30 of 109	Rustic Barn

Box 31

Box 31 of 109 FA-6-66140 Folklife Festival (4 folders)

Box 31 of 109 CP-6-21531 Festival of American Folklife (4 folders)

Box 31 of 109 CP-6-21942 Festival of American Folklife (3 folders)

Box 31 of 109 CP-6-22953 Tee Pee

Renwick Gallery
Summary: Renwick Gallery

Box 31 of 109 Galleries 102, 103, 104

Box 31 of 109 Iron Gates

Silver Hill
Summary: Silver Hill

Box 31 of 109 Flammable Liquid Storage Building

Box 31 of 109 Building 24 Mezzanine

Box 31 of 109 Barn

Box 31 of 109 Guardrail - Long Fence Company

Box 31 of 109 FC-702104 Weld Shop - Building 10 (3 folders)

Box 31 of 109 FC-708828 Liner/Sheathing - Building 10 (4 folders)

Box 31 of 109 1111 North Capitol Renovations

Box 31 of 109 FC-706144-00 Gravel Road Between Buildings 11 and 12

Box 31 of 109 Egress Doors (5 folders)

Box 31 of 109 Polaris Missile (2 folders)

Box 31 of 109 FA-6-66582 Guardrails (3 folders)

Box 31 of 109 FC-5-51081

Box 31 of 109 FC-6-65659 Flammable Liquid Storage (2 folders)

Box 31 of 109 FC-702252-10 Paving

Box 31 of 109	FC-702252 Parking Lot (3 folders)
	Hirshhorn Museum and Sculpture Garden Summary: Hirshhorn Museum and Sculpture Garden
Box 31 of 109	FC-6-69781 Spray Booth (4 folders)
	Fine Arts and Portrait Gallery Summary: Fine Arts and Portrait Gallery
Box 31 of 109	FC-70070200 Gallery 1A (Granite)
	Various Buildings Summary: Various Buildings
Box 31 of 109	FC-6-61660 Pyrontronics Equipment (3 folders)
	Natural History Building Summary: Natural History Building
Box 31 of 109	FC-6-63609 Fire Protection System - Hall 29 (4 folders)
Box 31 of 109	FC-6-60738 Installation of Air Filter (3 folders)
	L'Enfant Plaza Summary: L'Enfant Plaza
Box 31 of 109	Suite 3100, 3300, and 3400 (2 folders)
Box 31 of 109	DPA and MAO
	Smithsonian Institution Building Summary: Smithsonian Institution Building
Box 31 of 109	FC-705201 Parking Lot - South Yard (3 folders)
	Box 32
Box 32 of 109	FC-6-9936 Joseph Henry Papers (4 folders)
Box 32 of 109	FC-6-60745 Fire and Smoke Detection System (5 folders)
Box 32 of 109	FC-705511 Shutter Blinds
Box 32 of 109	FC-6-22259 North Tower (4 folders)
Box 32 of 109	FC-703108 South Tower (3 folders)
Box 32 of 109	FC-69935 North Tower Pump Replacement

Natural History Building
Summary: Natural History Building

Box 32 of 109 FC-6-69802 Sprinkler System (4 folders)

Box 32 of 109 FC-7008630 North Sprinkler Fire Pump

Hirshhorn Museum and Sculpture Garden
Summary: Hirshhorn Museum and Sculpture Garden

Box 32 of 109 FC-6-70035 Humidifiers (4 folders)

Box 32 of 109 FC-6-65256 Handrails (4 folders)

Fine Arts and Portrait Gallery
Summary: Fine Arts and Portrait Gallery

Box 32 of 109 FC-6-60520 Emergency Generator System (4 folders)

Box 32 of 109 FC-7-70200 Gallery 1A - Granite Gallery (2 folders)

Box 32 of 109 Exterior Repair and Painting (2 folders)

Renwick Gallery
Summary: Renwick Gallery

Box 32 of 109 FC-703104 Galleries 102 and 103 (3 folders)

Box 32 of 109 FC-6-69786 Galleries 202, 203, 206, and 207 (2 folders)

Box 32 of 109 FC-6-62660 Iron Gates (3 folders)

L'Enfant Plaza
Summary: L'Enfant Plaza

Box 32 of 109 FC-6-68667 Suite 3230 (2 folders)

Arts and Industries Building
Summary: Arts and Industries Building

Box 32 of 109 FC-4-61680 Renovation and Restoration

Freer Gallery of Art
Summary: Freer Gallery of Art

Box 32 of 109 FC-660739 Fire Detection System (4 folders)

Box 32 of 109 FC-6-69403 Doors (2 folders)

	Cooper-Hewitt Museum Summary: Cooper-Hewitt Museum
Box 32 of 109	PC-800431 More Than Meets the Eye (2 folders)
	Museum of History and Technology Summary: Museum of History and Technology
Box 32 of 109	Sprinkler System
Box 32 of 109	Marriott Cafeteria Alteration
	Chesapeake Bay Center for Environmental Studies Summary: Chesapeake Bay Center for Environmental Studies
Box 32 of 109	CBCES711A Facility Fire Protection
Box 32 of 109	CBCES671A Renovation of Barn
Box 32 of 109	CBCES661A Division of Ecology - Scientist Trailer, Quarters, and Laboratory
Box 32 of 109	CBC751C Docking Facility
Box 32 of 109	CBCES641A Survey Plat
Box 32 of 109	IVYN, February 1966
Box 32 of 109	CBCES721A Laboratory and Residential Buildings
	Box 33
Box 33 of 109	CBC731C Visitor's Center/Dormitory
	Natural History Building Summary: Natural History Building
Box 33 of 109	Alterations and Additions - Drawings
	Museum of History and Technology Summary: Museum of History and Technology
Box 33 of 109	FC-4-65736 Nation of Nations (2 folders)
Box 33 of 109	FC-5-4663 Revisions to Vestibule Ceiling
Box 33 of 109	CP-5-32185-2 Banking in America (4 folders)
Box 33 of 109	FC-5-47261 Conservation Analytical Laboratory (4 folders)

Box 33 of 109	PC-5-31014-1 Museum Shop (4 folders)
Box 33 of 109	South Entry Coat Room and Sales Shop Modifications
Box 33 of 109	FC-4-66594 Fire Protection (4 folders)
Box 33 of 109	RCN-061149 Storm Windows
Box 33 of 109	Introduction to Elap Hall - Ipswich House Area
Box 33 of 109	Fire Extinguishing System
Box 33 of 109	SFC-4-63227 Suiting Everyone (5 folders)
Box 33 of 109	FC-5-46358 Spike Building
Box 33 of 109	PC-5-31196 Exhibit on the History of American Banking
Box 33 of 109	CP-5-32185-1 Fabrication and Installation of American Banking Exhibit (5 folders)
Box 34	
Box 34 of 109	FC-5-46363 Coat Rooms and Information Desk (7 folders)
Box 34 of 109	FC-4-65736 A Nation of Nations
Box 34 of 109	FC-3-09109 Of the People Exhibit (6 folders)
Box 34 of 109	FC-5-48804 Health Unit (5 folders)
Box 34 of 109	S. S. Oak Exhibit
Box 34 of 109	CP-5-31174 Marine Hall (3 folders)
Box 34 of 109	CP-5-31174 S. S. Oak Marine Hall (2 folders)
Box 34 of 109	FC-6-60579 Conservation Analytical Laboratory Sprinkler Piping and Alarm System (2 folders)
Box 35	
Box 35 of 109	CP-5-31174 (Phase I)/CP-5-31204 (Phase III) S. S. Oak, 1976
Box 35 of 109	CP-5-31204 S. S. Oak/Marine Exhibit - Phase III (5 folders)
Box 35 of 109	Metro

Conservation Analytical Laboratory
Summary: Conservation Analytical Laboratory

Box 35 of 109 FC-5-50008 Modular Bench Unit (5 folders)

Box 35 of 109 FC-6-6-60579 Sprinkler Piping and Alarm System

Box 36

Arts and Industries Building
Summary: Arts and Industries Building

Box 36 of 109 AI726A Northwest Range, Lower Level (2 folders)

Box 36 of 109 AI715A Interior Painting (3 folders)

Box 36 of 109 AI723A Mezzanine Additions - West-North and Southwest Ranges (2 folders)

Box 36 of 109 76-33-286 Personnel Division Modifications - Phase I Electrical

Box 36 of 109 33101

Box 36 of 109 AI764A Elevator Modifications

Box 36 of 109 AI7611A-AI7617A Renovate Spaces for SITES, Public Affairs, etc.

Box 36 of 109 AI664A Information Services Division

Cooper-Hewitt Museum
Summary: Cooper-Hewitt Museum

Box 36 of 109 Brighton Exhibit

Box 36 of 109 CHM - Miscellaneous

Box 36 of 109 Part II - Pictures

Natural History Building
Summary: Natural History Building

Box 36 of 109 Air Filtration

Box 36 of 109 West Court Specifications

Box 36 of 109 Critical Path Analysis

Box 37

Box 37 of 109	NHB758A Osteo-Preparation Laboratory Environmental Room Shelter (2 folders)
Box 37 of 109	NHB756A Osteo-Preparation Facility
Box 37 of 109	Osteo-Preparation Facility (2 folders)
Box 37 of 109	NHB7611A Smoke Detection System - Hall 23
Box 37 of 109	NHB761A Install New Steam Reheat Coils, etc.
Box 37 of 109	The Natural History Building of the Smithsonian Institution: A Brief History
Box 37 of 109	Hall of Beautiful Things
Box 37 of 109	North Sprinkler Fire Pump Loop - Main and Hall 26 Sprinkler System
Box 37 of 109	Hall 29 Sprinkler Protection System
	Fine Arts and Portrait Gallery Summary: Fine Arts and Portrait Gallery
Box 37 of 109	Metro (2 folders)
Box 37 of 109	34438 Relocation of Toilet
Box 37 of 109	FAPG775B Renovation of Paint Shop and Silk Screen Rooms
	Renwick Gallery Summary: Renwick Gallery
Box 37 of 109	Modifications to Elevators
	Silver Hill Summary: Silver Hill
Box 37 of 109	SIF771A Parking Lot Paving
Box 37 of 109	SIF762A Flammable Liquid Storage Building
Box 37 of 109	7738405 Egress Doors - Fifteen Buildings
Box 37 of 109	7738103 Road Repairs
Box 37 of 109	7738111 O. H. Doors - Building 10
Box 37 of 109	7738116 Fire Protection Water Supply

Box 37 of 109	7738117 Gravel Road Between Buildings 11 and 12
Box 37 of 109	7738118 Lights - Thirteen Buildings
Box 37 of 109	SIF778A Road Repairs
Box 37 of 109	Water Main Extensions
Box 37 of 109	SIF779B Limited Alterations and Additions
Box 38	
	Chesapeake Bay Center for Environmental Studies Summary: Chesapeake Bay Center for Environmental Studies
Box 38 of 109	Jefferson Island Bulking Heading
	L'Enfant Plaza Summary: L'Enfant Plaza
Box 38 of 109	FC-4-61941 Astral Building, L'Enfant Plaza, Third Floor
Box 38 of 109	FC-4-66967 Third Floor Renovations
Box 38 of 109	Modifications to Suite 3230 - OFPES
Box 38 of 109	Room 2211
	Anacostia Neighborhood Museum Summary: Anacostia Neighborhood Museum
Box 38 of 109	Laboratory Mezzanine
	Smithsonian Institution Building Summary: Smithsonian Institution Building
Box 38 of 109	7763442 Parking Lot Repairs - South Yard
Box 38 of 109	SI764A Joseph Henry Papers
Box 38 of 109	South Yard Development Specification Index
	National Air and Space Museum Summary: National Air and Space Museum
Box 38 of 109	7735114 Spacearium
Box 38 of 109	7735123 Library Room

Box 38 of 109	Air Transportation Exhibit
Box 38 of 109	Special Truck Trailer Booth
	Hirshhorn Museum and Sculpture Garden Summary: Hirshhorn Museum and Sculpture Garden
Box 38 of 109	JHHM762A Install Humidifiers to Air Handlers S-1 and S-3
Box 38 of 109	JHHM761A Paint Spray Booth in Room G-32
	Arts and Industries Building Summary: Arts and Industries Building
Box 38 of 109	AI7619A Install Detector System for Archives
	History and Technology Building Summary: History and Technology Building
Box 38 of 109	HTB773A Replace Air Handling Units 4 and 5 in Fourth Floor Fan Rooms
Box 38 of 109	HTB775A Sandblast Granite Steps Around North Fountain
Box 38 of 109	HTB762A Addition to Objects Processing Room
Box 38 of 109	Fire, 1970 (3 folders)
Box 38 of 109	Nation of Nations Exhibition
	Administrative Records Summary: Administrative Records
Box 38 of 109	Reading Files, February 1979
Box 38 of 109	Reading Files, January-March 1977 (3 folders)
Box 38 of 109	Reading Files, January-October 1976 (10 folders)
Box 38 of 109	Reading File, December 1976
Box 38 of 109	Reading Files, July 1975-December 1975 (6 folders)
Box 38 of 109	Master Specifications - Section I
Box 38 of 109	Master Specifications - Sections III-XII (10 folders)
Box 38 of 109	Index - Master Specifications

Box 38 of 109	Engineering and Construction Division-Director's Office - Interoffice Correspondence
Box 38 of 109	Engineering and Construction Division-Facilities Planning Office - Interoffice Correspondence
Box 38 of 109	Engineering and Construction Division-Building Services Division - Interoffice Correspondence
Box 38 of 109	Engineering and Construction Division-Protection Division - Interoffice Correspondence
Box 39	
Box 39 of 109	Communications
Box 39 of 109	Engineering and Construction Division-Mechanical Services Branch - Interoffice Correspondence
Box 39 of 109	Engineering and Construction Division-Design and Construction Branch - Interoffice Correspondence
Box 39 of 109	Safety/Health Committee
Box 39 of 109	Cabinet Shop Correspondence
Box 39 of 109	Paint Shop Correspondence
Box 39 of 109	Sheetmetal Shop Correspondence
Box 39 of 109	Mechanical Operations Shop Correspondence
Box 39 of 109	Electric Shop Correspondence
Box 39 of 109	A&I Machine Shop Correspondence
Box 39 of 109	Awards - Sustained Superior Performance Awards (Suggestions, etc.)
Box 39 of 109	Engineering and Construction Division-Budget and Personnel Office - Interoffice Correspondence
Box 39 of 109	Engineering and Construction Division-Employee and Systems Development Office (Training) - Interoffice Correspondence
Box 39 of 109	23 Program Report (2 folders)
Box 39 of 109	Program Manager's Office - Form 23
Box 39 of 109	Program Manager's Office - Equal Employment Opportunity

Box 39 of 109	Engineering and Construction Division-Safety Office - Interoffice Correspondence
Box 39 of 109	Planning
Box 39 of 109	Bicentennial - A&I (Correspondence)
Box 39 of 109	Bicentennial - NHB (Correspondence)
Box 39 of 109	HVAC Complaint - Accounting
Box 39 of 109	OFPE Staff Operating System Handbook
Box 39 of 109	Status Reports
Box 39 of 109	Urban Renewal
Box 39 of 109	Tim - Filing
Box 39 of 109	Work Control Branch
Box 39 of 109	Work Control Branch Procedures
Box 39 of 109	Construction - Restoration and Renovation of Buildings
Box 39 of 109	Allotment - Miscellaneous Reproduction Services
Box 39 of 109	Allotment - Miscellaneous Reproduction Services, FY 1971
Box 39 of 109	Completed Requisitions, FY 1972
Box 39 of 109	Form 4 - FY 1971
Box 39 of 109	Form 4 - FY 1972
Box 39 of 109	PL-480 Building Information - Handicapped People
Box 39 of 109	7500148 Handicapped
Box 39 of 109	Miscellaneous Drawings and Requests
Box 39 of 109	A1715A Finish Interior Painting - A&I, NHB, HTB, and FAPG
Box 39 of 109	Change Orders - Painting Public Areas (A&I, NHB, HTB, FAPG)
Box 39 of 109	Metro - Miscellaneous
Box 39 of 109	Project Reports

Box 39 of 109	Photographs of Awards
Box 39 of 109	Miscellaneous Projects
Box 40	
Box 40 of 109	Weekly Manpower Utilization
Box 40 of 109	Energy Conservation
Box 40 of 109	Budget, FY 1972-FY 1974
Box 40 of 109	Assessment of Ongoing Work, July 1, 1972
Box 40 of 109	FA-708605 Spray Booth
Box 40 of 109	Weekly Manhour Reports
Box 40 of 109	Osteo-Preparatory Facility Environmental Rooms
	Cooper-Hewitt Museum Summary: Cooper-Hewitt Museum
Box 40 of 109	Daily Reports (2 folders)
Box 40 of 109	Attic Ductwork
Box 40 of 109	Fourth Floor Ductwork
Box 40 of 109	Cellar Plan/Existing Conditions, February 21, 1975
Box 40 of 109	Coil Piping Details
Box 40 of 109	HVAC System
Box 40 of 109	Stair #1
Box 40 of 109	Telephones
Box 40 of 109	Part Plan of Cellar Piping
Box 40 of 109	Third Floor Plan
Box 40 of 109	Grilles, Ducts, and Windows
Box 40 of 109	Plumbing
Box 40 of 109	Robertshaw Submittal - Temperature Control

Box 40 of 109	HVAC
Box 40 of 109	Lighting
Box 40 of 109	Passenger Elevator
Box 40 of 109	Second Floor Plan
Box 40 of 109	Part Plan - South Mechanical Room
Box 40 of 109	Hardware
Box 41	
History and Technology Building Summary: History and Technology Building	
Box 41 of 109	Television Studio
Box 41 of 109	First Floor, Central Hall Electrical
Box 41 of 109	Flag Hall Lighting
Box 41 of 109	Motor Control Center Wiring Diagram
Box 41 of 109	Electronic Clock and Air Raid System
Box 41 of 109	Transformer Supervisory System
Box 41 of 109	Hydraulic Lift
Box 41 of 109	Basement Cafeteria
Box 41 of 109	Third Floor Corridor to Flag Hall
Box 41 of 109	Foyer and Reception Room, First Floor
Box 41 of 109	South Lobby, First Floor
Box 41 of 109	Flag Hall
Box 41 of 109	Window Lighting
Box 41 of 109	Transformer Details
Box 41 of 109	Handrail Lighting
Box 41 of 109	Fixtures

Box 41 of 109	Bus Ducts
Box 41 of 109	Brochures
Box 41 of 109	Federal Pacific Instruction Manual
Box 41 of 109	Circuit Breakers
Box 41 of 109	Lighting Fixtures (2 folders)
Box 41 of 109	Underfloor Duct
Box 41 of 109	Basement Electrical Layout (2 folders)
Box 41 of 109	Material Specifications
Box 41 of 109	Transformer Tap Changer
Box 41 of 109	Centrifugal Refrigeration Machine
Box 41 of 109	Trans-o-matic Switches
Box 41 of 109	Bulldog Lighting Duct
Box 41 of 109	3 Phase Distribution Boards
Box 41 of 109	Habirprene Jacketed Cable
Box 41 of 109	Mechanically Held Conductor
Box 41 of 109	Test Cabinet Wiring Diagram
Box 41 of 109	Motor Control Center
Box 41 of 109	Smoke Detectors
Box 41 of 109	Wall Pockets and Plugging Strips
Box 41 of 109	Network Switch
Box 41 of 109	Tapchanger Assembly
Box 41 of 109	Substations and Primary Switchgear (2 folders)
Box 42	

Cooper-Hewitt Museum
Summary: Cooper-Hewitt Museum

Box 42 of 109	Metal Deck Plan and Details
Box 42 of 109	Indirect Incandescent Lamp
Box 42 of 109	Part Plan - Cellar Mechanical Room
Box 42 of 109	Part Basement Plan - Air Conditioning Ductwork
Box 42 of 109	Part Plan - First Floor
Box 42 of 109	Erection Plants
Box 42 of 109	Sprinkler System
Box 42 of 109	Cellar Plan
Box 42 of 109	Sprinklers
Box 42 of 109	Site Plan
Box 42 of 109	Elevations
	Renwick Gallery Summary: Renwick Gallery
Box 42 of 109	Signs of Life: Symbols in the City Exhibition
Box 43	
	History and Technology Building Summary: History and Technology Building
Box 43 of 109	Auditorium Lighting
Box 43 of 109	General Control Panel Wiring Diagram
Box 43 of 109	Transformers
Box 43 of 109	Battery Charging Units
Box 43 of 109	Special Water Wash Booth
Box 43 of 109	Radiator Valves
Box 43 of 109	Direct Drive Package Chillers
Box 43 of 109	Valve Schedule

Box 43 of 109	Steam Condenser
Box 43 of 109	Three-way Vent Valves
Box 43 of 109	Air Filter
Box 43 of 109	Steam Boiler
Box 43 of 109	Induction Motor
Box 43 of 109	Pumps
Box 43 of 109	Exhaust Heads
Box 43 of 109	Sound Absorbing Material in Ducts
Box 43 of 109	Centrifugal Pumps
Box 43 of 109	List of Unit Heaters
Box 43 of 109	Flash Tanks
Box 43 of 109	Basement HVAC Floorplan
Box 43 of 109	Flag Hall Chiller
Box 43 of 109	Pump Out Unit
Box 43 of 109	Oil Pump
Box 43 of 109	Typical Concrete Reinforcement Plan for EC Machine
Box 43 of 109	Centrifugal Refrigeration Machine
Box 43 of 109	Water Piping Diagram
Box 43 of 109	1/4" Relief Connection
Box 43 of 109	Schematic Piping
Box 43 of 109	Storage Receiver
Box 43 of 109	Pumping System
Box 43 of 109	Compressor Unit
Box 43 of 109	Special Neoprene Units

Box 43 of 109	Rubber In-shear Base
Box 43 of 109	Centrifugal Fan Cooling Tower
Box 43 of 109	Cooling Unit
Box 43 of 109	Coil Order
Box 43 of 109	Noiseless Check Valve
Box 43 of 109	Condensing Units
Box 43 of 109	Cooling Tower
Box 43 of 109	Westinghouse Equipment and Drawings (2 folders)
Box 43 of 109	Notifier Alarm and Sprinkler Equipment and Drawings
Box 43 of 109	Barber-Colman Submission (2 folders)
Box 43 of 109	Thermotank Submission
Box 43 of 109	Westinghouse Resubmittal Drawings
Box 43 of 109	Diffusers
Box 43 of 109	Pipe Insulation
Box 43 of 109	Enclosed or Explosion Proof Motors
Box 43 of 109	Storage Heater
Box 43 of 109	Orifice Meter
Box 43 of 109	Spray Water Pumps
Box 43 of 109	Dehumidifiers
Box 43 of 109	Bob Float Valves
Box 43 of 109	Non-Clog Spray Nozzles
Box 43 of 109	Remote Bulb Thermometers
Box 43 of 109	Unit Coolers
Box 43 of 109	Three-break Eliminator

Box 43 of 109	Return Air Register
Box 43 of 109	Basement Louvers
Box 43 of 109	Panel Heating Layout
Box 44	
Box 44 of 109	Snow Melting Coils
Box 44 of 109	Electronic Temperature Indicators
Box 44 of 109	Window Unit Details - Fifth Floor
Box 44 of 109	Chiller Control
Box 44 of 109	Air Conditioning
Box 44 of 109	Vacuum Heating Pump
Box 44 of 109	Shaft Shop Drawings
Box 44 of 109	Catalogue Shop Drawings
Box 44 of 109	Cap Utility Locations
Box 44 of 109	American Standard Plumbing Fixtures
Box 44 of 109	Josam Portfolio
Box 44 of 109	Escalators (2 folders)
Box 44 of 109	Remote Coolers with Pumps
Box 44 of 109	Hot Water Circulating Pumps
Box 44 of 109	Water Tanks
Box 44 of 109	Hydro-pneumatic Pump Control
Box 44 of 109	Single-stage Air Compressors
Box 44 of 109	Air Traps
Box 44 of 109	Vertical Tank
Box 44 of 109	Water Meter

Box 44 of 109	Temperature-Pressure Relief Valve
Box 44 of 109	Sump and Ejector Pumps
Box 44 of 109	Storage
Box 44 of 109	Fire Protection Equipment
Box 44 of 109	Water Chiller
Box 44 of 109	Elevators (6 folders)
Box 44 of 109	Duplex Sewer Ejector
Box 44 of 109	Gutter Drain
Box 44 of 109	Overflow Fittings for Reflector Pool
Box 44 of 109	American Standard Specifications
Box 44 of 109	Central Automatic Sprinkler Company Products
Box 44 of 109	M&H Gate Valves
Box 44 of 109	Buffalo Tank Division Order
Box 44 of 109	Annunciators
Box 44 of 109	Cooling Tower Make-up Valves
Box 44 of 109	Floor and Ceiling Plates
Box 44 of 109	Cooling Tower
Box 45	
Box 45 of 109	Duct Construction Details
Box 45 of 109	Sprinklers
Box 45 of 109	Beam Schedule
Box 45 of 109	First Floor Beams and Slab
Box 45 of 109	Columns (6 folders)
Box 45 of 109	Fifth Floor Beams (3 folders)

Box 45 of 109 Walls

Box 46

Box 46 of 109 Detail Sketches (7 folders)

Box 46 of 109 Second Floor Framing

Box 46 of 109 Main Roof Framing

Box 46 of 109 Second Floor Beams (4 folders)

Box 46 of 109 Third and Fourth Floor Beams

Box 46 of 109 Vault Walls

Box 46 of 109 Ventilating Areas

Box 46 of 109 Cooling Tower

Box 46 of 109 Column Schedule

Box 46 of 109 Elevator and Sump Pits

Box 47

Box 47 of 109 Cafeteria Terrace and Stairs

Box 47 of 109 Trusses

Box 47 of 109 Mining Exhibit Area Mezzanine

Box 47 of 109 Main Roof Beams

Box 47 of 109 Buttresses

Box 47 of 109 Beam and Column Schedule

Box 47 of 109 Chords

Box 47 of 109 First Floor Framing

Box 47 of 109 Hangers

Box 47 of 109 Fifth Floor Framing Plan

Box 47 of 109 First Floor Sections

Box 47 of 109	Girders
Box 47 of 109	Fourth Floor Beams
Box 47 of 109	Third and Fourth Floor Beams
Box 47 of 109	Areaways
Box 47 of 109	Hall of Railroads
Box 47 of 109	Elevators
Box 47 of 109	Door Frames
Box 47 of 109	Basement Partitions
Box 47 of 109	Pipe Railings
Box 47 of 109	Aluminum Rails
Box 47 of 109	Basement Access Doors
Box 47 of 109	Loading Ramp
Box 47 of 109	Smoke Hole
Box 47 of 109	Stairways (2 folders)
Box 47 of 109	Television Studio
Box 47 of 109	Mining Hall
Box 47 of 109	Auditorium
Box 47 of 109	Ramps
Box 47 of 109	Parking Area
Box 47 of 109	Basement Trenches
Box 47 of 109	Galvanized Steel Platforms
Box 47 of 109	Wood Screen
Box 47 of 109	Hall of Heavy Machinery
Box 47 of 109	Hall of Light Machinery

Box 47 of 109	Hall of Electricity
Box 48	
Box 48 of 109	Hall of Chemistry
Box 48 of 109	Eye Bolt
Box 48 of 109	Details
Box 48 of 109	Return Rails
Box 48 of 109	Projection Room
Box 48 of 109	Platforms
Box 48 of 109	Flights (2 folders)
Box 48 of 109	South Lobby
Box 48 of 109	Watercraft Rails
Box 48 of 109	Trap Doors
Box 48 of 109	Underwater History
Box 48 of 109	Hall of Photography
Box 48 of 109	Hall of the Growth of America
Box 48 of 109	Pipe Columns
Box 48 of 109	Stringer Details
Box 48 of 109	Penthouse Roof
Box 48 of 109	Hall of Ceramics
Box 48 of 109	Steel Grating
Box 48 of 109	Steel Channels
Box 48 of 109	Steel Framing
Box 48 of 109	Costume Hall
Box 48 of 109	Hall of Special Exhibits

Box 48 of 109	Coat Room
Box 48 of 109	Hall of Textiles
Box 48 of 109	Pendulum
Box 48 of 109	Hall of Industrial Exhibits
Box 48 of 109	Ship Ladders
Box 48 of 109	Granite Bases
Box 48 of 109	Mosaic Wall
Box 48 of 109	Steel Ladders
Box 48 of 109	Channel Doors
Box 48 of 109	Hall of Tools
Box 48 of 109	Fan Rooms
Box 48 of 109	Allis Chalmers Pistons
Box 48 of 109	Plate Frames
Box 48 of 109	Wall Hung Cases
Box 48 of 109	Case Openings (2 folders)
Box 48 of 109	Expansion Joints
Box 48 of 109	Angle Frames
Box 48 of 109	Hall of Graphic Arts
Box 48 of 109	Stage Steps
Box 48 of 109	Hall of Glass
Box 48 of 109	Hall of Numismatics
Box 48 of 109	Ceiling
Box 48 of 109	Dressing Room
Box 48 of 109	Columns

Box 48 of 109	Curtains
Box 48 of 109	Grid Ceiling
Box 48 of 109	Flag Hall
Box 48 of 109	Plywood and Glass Wall
Box 48 of 109	Catwalks
Box 49	
Box 49 of 109	Ceramic Hall
Box 49 of 109	Display Cases
Box 49 of 109	Hall of Agriculture
Box 49 of 109	Hall of Glass
Box 49 of 109	Hall of Numismatics
Box 49 of 109	Hall of Heavy Machinery
Box 49 of 109	Hall of Light Machinery
Box 49 of 109	Hall of Railroads
Box 49 of 109	Convactor
Box 49 of 109	East Room Windows
Box 49 of 109	Plasters
Box 49 of 109	Chemistry Hall
Box 49 of 109	Photography Hall
Box 49 of 109	Coat Room and Sales Area
Box 49 of 109	Sliding Pocket Doors
Box 49 of 109	Hall of Tools, Civil Engineering, and Mining
Box 49 of 109	Telephone Rooms
Box 49 of 109	Hall of Electricity

Box 49 of 109	Marble Rail
Box 49 of 109	Pendulum and Flag Well
Box 49 of 109	Expansion Joints and Elevators
Box 49 of 109	Sump Pits
Box 49 of 109	Details
Box 49 of 109	Wire Mesh Work
Box 49 of 109	Stair 14
Box 49 of 109	Basement and Exit Ramp
Box 49 of 109	Elevator 7
Box 49 of 109	Guardrails
Box 49 of 109	Reference Prints
Box 49 of 109	Hall of 18th and 19th Century Furnishings
Box 50	
Box 50 of 109	Hall of 18th and 19th Centuries (2 folders)
Box 50 of 109	Thresholds
Box 50 of 109	Statue Pedestal
Box 50 of 109	Garcy Struts
Box 50 of 109	Sales Area and Coat Room
Box 50 of 109	Side Paving Blocks
Box 50 of 109	Free-Standing Cases
Box 50 of 109	Ceiling Light and Air Diffusers
Box 50 of 109	Steel Angle and Plate Guards
Box 50 of 109	First Ladies Hall
Box 50 of 109	Catwalks

Box 50 of 109	Hall of Philately
Box 50 of 109	Peterson Company Schedules
Box 50 of 109	Cafeteria, Dining Room, and Related Areas
Box 50 of 109	Design Laboratory
Box 50 of 109	Auditorium (2 folders)
Box 50 of 109	Basement
Box 50 of 109	Director's Office
Box 50 of 109	Foyer and Adjacent Areas
Box 50 of 109	Musical Instruments
Box 50 of 109	Vestibule and Adjacent Areas
Box 50 of 109	Hall of Physics and Astronomy
Box 50 of 109	First Ladies Hall
Box 50 of 109	Small Exhibit Cases
Box 50 of 109	Newel Post and Handrail
Box 50 of 109	Hall of 18th and 19th Century Furnishings
Box 50 of 109	Costume Hall
Box 50 of 109	Hall of Graphic Arts
Box 50 of 109	Watercraft Hall
Box 50 of 109	Hall of Textiles
Box 50 of 109	Hall of Dentistry, Pharmacy, and Health
Box 50 of 109	Hall of Political History
	Box 51
Box 51 of 109	Hall of Agriculture
Box 51 of 109	Hall of American Costume (2 folders)

Box 51 of 109	Automobile Hall
Box 51 of 109	Ceramics Hall
Box 51 of 109	Schedule
Box 51 of 109	Hall of Chemistry
Box 51 of 109	Hall of Civil Engineering
Box 51 of 109	Hall of Defense
Box 51 of 109	Hall of Electricity
Box 51 of 109	Truck Ramp
Box 51 of 109	Guardhouse
Box 51 of 109	Third Floor Framing Plan
Box 51 of 109	Second Floor Framing Plan
Box 51 of 109	Concrete Marble Supports
Box 51 of 109	Air Exhaust Tunnel
Box 51 of 109	Fourth and Fifth Floor Trusses
Box 51 of 109	First Floor Beams
Box 51 of 109	Electric Cable Room
Box 51 of 109	Slab
Box 51 of 109	Walls
Box 51 of 109	Penthouse Roof
Box 51 of 109	First Floor Plan
Box 51 of 109	Base Details
Box 51 of 109	Second Floor Framing Plan
Box 51 of 109	Elevator Pit
Box 52	

Box 52 of 109 Miscellaneous Details (3 folders)

Box 52 of 109 Pile Caps

Box 52 of 109 Columns (5 folders)

Box 52 of 109 Second Floor Beams (5 folders)

Box 53

Box 53 of 109 Beams (2 folders)

Box 53 of 109 Hall of Tools

Box 53 of 109 Hall of Glass

Box 53 of 109 Hall of Graphic Arts (2 folders)

Box 53 of 109 Hall of the Growth of America

Box 53 of 109 Hall of Heavy Machinery

Box 53 of 109 Hall of Historic Americans

Box 53 of 109 Hall of Industrial Cooperatives

Box 53 of 109 Hall of Light Machinery

Box 53 of 109 Hall of Medicine, Dentistry, Pharmacy, and Health

Box 53 of 109 Hall of Mining

Box 53 of 109 Hall of Musical Instruments

Box 53 of 109 Hall of Numismatics

Box 53 of 109 Hall of Photography

Box 53 of 109 Hall of Political History

Box 53 of 109 Hall of Philately

Box 54

Box 54 of 109 Hall of Physics and Astronomy (2 folders)

Box 54 of 109 Hall of Railroads

Box 54 of 109	Hall of Textiles
Box 54 of 109	Hall of First Ladies (2 folders)
Box 54 of 109	Hall of Underwater History
Box 54 of 109	Hall of Watercraft
Box 54 of 109	Special Rooms (2 folders)
Box 54 of 109	Column Details - Photographs
Box 54 of 109	Hall of Ceramics
Box 54 of 109	Bank D Escalators
Box 54 of 109	Stair 9
Box 55	
Box 55 of 109	Brass Details (5 folders)
Box 55 of 109	Relieving Angles - Marble
Box 55 of 109	Windows and Miscellaneous Steel (2 folders)
Box 55 of 109	Third Floor (3 folders)
Box 55 of 109	Fourth Floor (4 folders)
Box 56	
Box 56 of 109	Fifth Floor (2 folders)
Box 56 of 109	Penthouse Fan Room
Box 56 of 109	Flag Hall Ductwork
Box 56 of 109	Cooling Tower
Box 56 of 109	Carthage Marble Interior Drawings (folders 1-8 of 11)
Box 57	
Box 57 of 109	Carthage Marble Interior Drawings (folders 9-11 of 11)
Box 57 of 109	Granite

Box 57 of 109	Fifth Floor Marble Base
Box 57 of 109	Fourth Floor Marble Base
Box 57 of 109	Terrazzo (2 folders)
Box 57 of 109	Basement (4 folders)
Box 58	
Box 58 of 109	First Floor (5 folders)
Box 58 of 109	Second Floor (4 folders)
	Various Buildings Summary: Various Buildings
Box 58 of 109	Miscellaneous Projects
	History and Technology Building Summary: History and Technology Building
Box 58 of 109	Food Service Equipment (2 folders)
Box 58 of 109	Kitchen Shop Drawings (2 folders)
Box 59	
Box 59 of 109	Elevators (2 folders)
Box 59 of 109	Cafeteria and Locomotive Pit
Box 59 of 109	Capital Bronze Corporation
Box 59 of 109	Escalators
Box 59 of 109	Granite Bases
Box 59 of 109	First Floor Beams
Box 59 of 109	Elevator Pits
Box 59 of 109	Locomotive Pit Walls
Box 59 of 109	Hangers
Box 59 of 109	Third Floor Framing Plan

Box 59 of 109	Plenum Chamber
Box 59 of 109	Fifth Floor Framing Plan
Box 59 of 109	Main Roof Framing Plan
Box 59 of 109	Fourth Floor Framing Plan
Box 59 of 109	Walls
Box 59 of 109	Pile Caps
Box 59 of 109	Slab
Box 59 of 109	Third and Fourth Floor Beams
Box 59 of 109	Third Floor Beams
Box 60	
Box 60 of 109	Second Floor Beams (3 folders)
Box 60 of 109	Beams (2 folders)
Box 60 of 109	Columns (3 folders)
Box 60 of 109	Fourth Floor
Box 60 of 109	Electric Cable Room
Box 60 of 109	Television Studio
Box 60 of 109	Mining Exhibit Area
Box 60 of 109	Truck Dock
Box 60 of 109	Second Floor
Box 60 of 109	Stairs
Box 60 of 109	Projection Room
Box 60 of 109	First Floor
Box 60 of 109	Steam Pipe Tunnel
Box 60 of 109	Fan Rooms

Box 60 of 109	Third Floor
Box 60 of 109	Electric Manhole
Box 60 of 109	Elevators
Box 60 of 109	Miscellaneous Details (2 folders)
Box 61	
Box 61 of 109	Precast Panels
Box 61 of 109	Fourth Floor
Box 61 of 109	Field Work Materials and Details (2 folders)
Box 61 of 109	Machine Rooms
Box 61 of 109	Main Roof
Box 61 of 109	Fifth Floor
Box 61 of 109	Retaining Walls
Box 61 of 109	Reinforcement Plans
Box 61 of 109	Buttresses
Box 61 of 109	Basement
Box 61 of 109	Penthouse
Box 61 of 109	Construction Estimates
Box 61 of 109	Auditorium Steel
Box 61 of 109	Ceco Steel Products Corporation (3 folders)
Box 61 of 109	Narrow Window Lights
Box 61 of 109	Adjustable Light Louvers
Box 61 of 109	Medicine Cabinets - Director's Office Toilets
Box 61 of 109	Hardware and Vaults (3 folders)
Box 61 of 109	Fire Hose and Fire Extinguisher Cabinets

Box 62

Box 62 of 109 Potomac East Stone

Box 62 of 109 J. E. Linck

Box 62 of 109 Brandt (2 folders)

Box 62 of 109 Superior Fireproof (2 folders)

Box 62 of 109 Granite (3 folders)

Box 62 of 109 J. G. Wilson

Box 62 of 109 Clocks

Box 62 of 109 Flooring, Drinking Fountains, and Seating (2 folders)

Smithsonian Institution Building
Summary: Smithsonian Institution Building

Box 62 of 109 FC-800786 No Touch Sprinkler (3 folders)

Box 62 of 109 FC-708613 Exterior Painting and Caulking (3 folders)

Box 63

Box 63 of 109 FC-6-61163 Demolition, Construction, and Specifications for South Yard (7 folders)

Box 63 of 109 FC-5-47966 South Yard Modifications

Box 63 of 109 Remolding Second Floor South Tower

Box 63 of 109 Shutters - Room 507

Box 63 of 109 PN-6-22259 North Tower

Box 63 of 109 FC-6-60745 Fire Detection System (7 folders)

Barney Studio House
Summary: Barney Studio House

Box 63 of 109 7642350 Smoke Detection

Box 63 of 109 7642350 Roof

Box 63 of 109 FC-800776 Roof and Smoke Detection (4 folders)

Fine Arts and Portrait Gallery
Summary: Fine Arts and Portrait Gallery

Box 63 of 109 Time of Our Lives

Box 64

National Air and Space Museum
Summary: National Air and Space Museum

Box 64 of 109 Structural Calculations (10 folders)

Box 64 of 109 Structural Computations - Reinforced Concrete (3 folders)

Box 64 of 109 49266 Structural Computations Plate Girders

Box 64 of 109 49266 Structural Computations (2 folders)

Box 64 of 109 Various Plans for West Court Additions (folders 1-2 of 3)

Box 65

Box 65 of 109 Various Plans for West Court Addition (folder 3 of 3)

Box 65 of 109 RPC-5-32570 Ellenco Fire Alarm and Signal Devices

Box 65 of 109 Paint

Box 65 of 109 RPC-5-32570 Change Order #1 - JJG Construction

Box 65 of 109 RPC-5-32570 Change Order #2 - Marriott Corporation (3 folders)

Box 65 of 109 RPC-5-32570 Change Order #3 - Loren Raap

Box 65 of 109 RPC-5-32570 Change Order #4 - Ceco Corporation

Box 65 of 109 RPC-5-32570 Change Order #5 - Dining Facility (2 folders)

Box 65 of 109 RPC-5-32570 Change Order #6 - Elevators

Box 65 of 109 RPC-5-32570 Food Carousel

Box 65 of 109 RPC-5-32570 HVAC

Box 65 of 109 RPC-5-32570 Partitions

Box 65 of 109 RPC-5-32570 Roof Openings

Box 65 of 109 RPC-5-32570 Fabric Joint Coverings

Box 65 of 109	West Court Addition Furnishings
Box 65 of 109	CP-6-21267 American Museum Construction Corporation
Box 66	
Box 66 of 109	Air Filters (3 folders)
Box 66 of 109	FC-5-51799 Osteo-Preparatory Laboratory (6 folders)
Box 66 of 109	FA-5-53353 Sprinkler Fire Pumping Systems (2 folders)
Box 66 of 109	SI Libraries Expansion, Phase III - Modifications
Box 67	
Box 67 of 109	Floodlighting
Box 67 of 109	Mineral Sciences Security Work Area
Box 67 of 109	FC-6-60737 Fire Pump System
Box 67 of 109	FA-6-62142 West Court Utilities
	History and Technology Building Summary: History and Technology Building
Box 67 of 109	Halon Fire Suppression System for Philately and Numismatics Vaults
Box 67 of 109	Addition to Fire Suppression System
Box 67 of 109	Nation of Nations
Box 67 of 109	Conservation Analytical Laboratory
Box 67 of 109	Basement Receiving Facility
	Arts and Industries Building Summary: Arts and Industries Building
Box 67 of 109	Change Order Proposal
Box 67 of 109	General Conditions
Box 67 of 109	Division 1 - General Requirements
Box 67 of 109	Section 110 - Special Conditions

Box 67 of 109	Section 117 Project Management
Box 67 of 109	Section 330 Concrete
Box 67 of 109	Section 410 Masonry Mortars
Box 67 of 109	Section 420 Masonry
Box 67 of 109	Section 601 Carpentry
Box 67 of 109	Division 7 Moisture Control
Box 67 of 109	Section 810 Metal Doors and Frames
Box 67 of 109	Section 870 Finish Hardware
Box 67 of 109	Section 910 Furring, Lathing, and Plastering
Box 67 of 109	Section 925 Gypsum Wall-Board Systems
Box 67 of 109	Section 950 Acoustical Ceiling Systems
Box 67 of 109	Section 990 Painting and Finishing
Box 67 of 109	Section 1500 or 1501 Mechanical and Electrical Equipment
Box 67 of 109	Section 1515 Vibration Isolation
Box 67 of 109	Section 1590 Refrigeration Systems (Air Conditioning)
Box 67 of 109	Section 1595 Temperature Control
Box 67 of 109	Section 1517 Plumbing
Box 67 of 109	Division 16 Electrical
Box 67 of 109	Change Orders and Proposals (folders 1-4 of 7)
Box 68	
Box 68 of 109	Change Orders and Proposals (folders 5-7 of 7)
Box 68 of 109	Claims
Box 68 of 109	Accidents
Box 68 of 109	Coordination (2 folders)

Box 68 of 109	Sprinkler System
Box 68 of 109	Structural Details
Box 68 of 109	Slab Reinforcement
Box 68 of 109	Southeast Court
Box 68 of 109	Stair Shaft
Box 68 of 109	Northeast Quadrant
Box 68 of 109	Electrical
Box 68 of 109	Northwest Court
Box 68 of 109	Emergency Lighting
Box 68 of 109	Automatic Air Conditioning Network Protector
Box 68 of 109	Standard Electric Time Corporation
Box 68 of 109	General Electric
Box 68 of 109	Taco Heat
Box 68 of 109	Cooling Tower
Box 68 of 109	Fire Alarm
Box 68 of 109	Ductwork
Box 68 of 109	Air Balance Report
Box 68 of 109	Outages
Box 68 of 109	SI Interdepartmental Correspondence
Box 68 of 109	Information Requested by Contractor
Box 68 of 109	General Correspondence
Box 68 of 109	Carpeting
Box 68 of 109	Payment Requests
Box 68 of 109	Working Over Occupied Spaces

Box 68 of 109	Progress Reports and Coordination
	Box 69
Box 69 of 109	Electrical
Box 69 of 109	Walls
Box 69 of 109	General Requirements
Box 69 of 109	Occupational Safety and Health Standards and Interpretations
Box 69 of 109	Millwork
Box 69 of 109	Acrylic Sealant
Box 69 of 109	Masonry
Box 69 of 109	Concrete (2 folders)
Box 69 of 109	C. P. M.
Box 69 of 109	Doors (2 folders)
Box 69 of 109	Increases, Amendments, and Modifications
Box 69 of 109	Electrical
Box 69 of 109	Fire Protection
Box 69 of 109	General Requirements
Box 69 of 109	Glass
Box 69 of 109	Insurance Policies
Box 69 of 109	Key System
Box 69 of 109	Mechanical
Box 69 of 109	Miscellaneous Correspondence
Box 69 of 109	Metals
Box 69 of 109	Occupancy
Box 69 of 109	Paint

Box 69 of 109	Payroll Submittals
Box 69 of 109	Plumbing
Box 69 of 109	Preliminary Phase
Box 69 of 109	Progress Reports
Box 69 of 109	Rotunda Floor
Box 69 of 109	Security
Box 69 of 109	Specialties
Box 69 of 109	Specifications and Guidelines for Drawings
Box 69 of 109	Contract Documents
Box 69 of 109	Correspondence
Box 69 of 109	Sprinkler
Box 69 of 109	Subcontractors
Box 69 of 109	Tenant Relocation
Box 69 of 109	Window Survey
Box 69 of 109	Work Order Requests (Form 23s)
Box 69 of 109	Transmittals
Box 70	
Box 70 of 109	Requests for Photographic Services
Box 70 of 109	Index
Box 70 of 109	Fire Protection Piping Plan
Box 70 of 109	Ductwork (3 folders)
	Renwick Gallery Summary: Renwick Gallery
Box 70 of 109	FC-703557 Exterior Renovation (4 folders)
Box 70 of 109	FC-6-6-69786 Galleries 202, 203, 206, and 207

Box 70 of 109	Decorative Arts of the Americas
Box 70 of 109	Galleries 102 and 103
	Chesapeake Bay Center for Environmental Studies Summary: Chesapeake Bay Center for Environmental Studies
Box 70 of 109	Renovation of Calf Barn
	Freer Gallery of Art Summary: Freer Gallery of Art
Box 70 of 109	Lawn Sprinklers
Box 70 of 109	Fire Detection System
	Fine Arts and Portrait Gallery Summary: Fine Arts and Portrait Gallery
Box 70 of 109	New Light Track System in the South and East Wing of Second Floor
Box 70 of 109	Emergency Generator
Box 70 of 109	Third Floor Electrical Work
	Smithsonian Institution Building Summary: Smithsonian Institution Building
Box 70 of 109	Fire Detection System Phase I
Box 70 of 109	South Yard Lawn Sprinklers
Box 70 of 109	South Yard Development Plan
Box 70 of 109	Photography Laboratory and Equipment
	Box 71
	National Air and Space Museum Summary: National Air and Space Museum
Box 71 of 109	Watermain
Box 71 of 109	Redesign
Box 71 of 109	Excavation
Box 71 of 109	Fire Protection

Box 71 of 109	Metal Deck
Box 71 of 109	Photographs
Box 71 of 109	Security System
Box 71 of 109	Structural Steel
Box 71 of 109	Telephone and Equipment Room
Box 71 of 109	Apollo to the Moon
	Arts and Industries Building Summary: Arts and Industries Building
Box 71 of 109	Specifications (6 folders)
Box 71 of 109	Northwest Range, Ground Floor Classroom
Box 71 of 109	Smoke Detection - Archives
Box 71 of 109	Preparation for Bicentennial
Box 71 of 109	Watchman's Tour System
Box 71 of 109	Stencils
Box 71 of 109	Interior Painting
Box 71 of 109	Timeline
	Various Buildings Summary: Various Buildings
Box 71 of 109	Invoices, Transmittals, and Correspondence (3 folders)
Box 71 of 109	Security Support
Box 71 of 109	Festival of American Folklife, 1975
Box 71 of 109	Festival of American Folklife, 1976
	Box 72
Box 72 of 109	Recommendations
Box 72 of 109	Trane Heating Catalogues (2 folders)

Box 72 of 109	Hillwood Property
Box 72 of 109	Museum Shops
Box 72 of 109	Design Ideas
	History and Technology Building Summary: History and Technology Building
Box 72 of 109	Numismatics Reference Collection
Box 72 of 109	Fountain
Box 72 of 109	Cafeteria
	Natural History Building Summary: Natural History Building
Box 72 of 109	Mineral Laboratory
Box 72 of 109	Demolition of Dibner Library
	Silver Hill Summary: Silver Hill
Box 72 of 109	Building 24 Mezzanine Office - Lighting and Air Conditioning
Box 72 of 109	Relocation of Weld Shop
	Fine Arts and Portrait Gallery Summary: Fine Arts and Portrait Gallery
Box 72 of 109	Granite Gallery
Box 72 of 109	HVAC for Kitchen, Dining Facility, and Storage Area
Box 72 of 109	Conduit Layout
	Anacostia Museum Summary: Anacostia Museum
Box 72 of 109	HVAC, etc.
	Freer Gallery of Art Summary: Freer Gallery of Art
Box 72 of 109	37312 Auditorium - Doors and Mechanical

	Smithsonian Institution Building Summary: Smithsonian Institution Building
Box 72 of 109	Common Room Floor Plan
Box 72 of 109	Room 314 Partition
	History and Technology Building Summary: History and Technology Building
Box 72 of 109	7830117 Closing Wall Opening, 1/4/1978
Box 72 of 109	7930127 Carmichael Auditorium Modifications, 8/2/1979
Box 72 of 109	7930126 HVAC Room 5108-A, 12/13/1979
Box 72 of 109	7930124 Hall of Electricity - Electricity Sign, 11/14/1979
Box 72 of 109	7930122 HVAC Room 4402, 12/12/1979
Box 72 of 109	7930120 Associated Builders - Automated Entrance Doors, 8/29/1979
Box 72 of 109	7930117 Health Unit HVAC Humidifier Installation, 4/26/1979
Box 72 of 109	7930109 Hanging Textile Sculpture, 4/4/1979
Box 72 of 109	7930105 Labor Force Offices, 4/10/1979
Box 72 of 109	7930103 East Drive Repairs, 2/2/1979
Box 72 of 109	7930102 Postal History "X" Frame Cases, 1/30/1978
Box 72 of 109	7830112 Hall of American Maritime Enterprises Timeline, 6/19/1978
Box 72 of 109	7730110 AE Records Retrieval for MHT
Box 72 of 109	7630387 Welch and Rushe - Replace Air Conditioning Units 4 and 5, 1/11/1978
Box 72 of 109	7630343 Construction Services, Inc., Printing and Photographic Services Office Modifications, 12/6/1977
Box 72 of 109	7630314 Vestibule Lighting, 11/29/1978
Box 72 of 109	7630250 Alec J. Hedquist Company, Overhead Door Grilles, 4/5/1977

Box 73

Box 73 of 109	7730107 Associated Builders - Refrigerated Trash Room, 10/20/1978 (3 folders)
Box 73 of 109	7730119 Weiss Construction - Maritime Hall Pilot House (3 folders)
Box 73 of 109	7530118 Associated Builders - Automatic Entrance Doors, 4/30/1979 (2 folders)
Box 73 of 109	7630104 Borg Warner - Replace Coils, 6/15/1979
Box 74	
Box 74 of 109	7630116 Sixth Floor Library (Dibner), 4/7/1980 (5 folders)
Box 74 of 109	7630232 Health Vestibule, 11/20/1979
Box 74 of 109	763239 Suburban Restoration - Waterproofing Fourth Floor, 4/26/1979 (2 folders)
Box 74 of 109	7630391 Air Filter Study, 4/11/1977
Box 74 of 109	7630393 Person to Person Exhibit, 3/13/1978
Box 74 of 109	7730101 Olomana Locomotive, 3/24/1977
Box 74 of 109	7730102 Humidifiers and Exhaust Fan Replacement, 9/8/1977
Box 74 of 109	7730104 Borg Warner - Coil Replacement, 6/15/1979
Box 75	
Box 75 of 109	7730112 Interrogatories (Watts Fall Case), 6/30/1978
Box 75 of 109	7730114 Flammable Liquid Storage, 2/9/1979
Box 75 of 109	7730116 South Terrace Planting, 8/4/1977
Box 75 of 109	7730117 Noise Pollution in Conservation Analytical Laboratory, 7/12/1977
Box 75 of 109	7730120 Plastic Shop Ventilation, 1/11/1978
Box 75 of 109	7730121 Presidential Suite Smoke and Fire Alarms, 4/19/1978
Box 75 of 109	7730123 Foundation Cracks, 9/20/1978
Box 75 of 109	7730124 Paint Shop Exhaust, 4/10/1978
Box 75 of 109	7730125 Electromyograph Inspection - Medical Science Hall, 10/17/1977

Box 75 of 109	7730434 Grease Trap cleaning, 10/17/1977
Box 75 of 109	7830101 Employee Cafeteria, 11/28/1979
Box 75 of 109	7830103 Welch and Rushe - Replace Air Conditioning Units 2 and 6, 5/22/1979
Box 75 of 109	7830104 Replace City Water Booster Pumps, 11/1/1977
Box 75 of 109	7830106 Additional Fire Pump, 4/19/1978
Box 75 of 109	7830107 Everyday Life Exhibit Smoke Detection, 4/19/1978
Box 75 of 109	7830108 Director's Conference Room Exhibit Cases, 8/25/1978
Box 75 of 109	7830109 McGraw Hill Office Area, 12/15/1977
Box 75 of 109	7830111 Soldier's Home Bandstand, 7/26/1978
Box 75 of 109	7830118 Majestic Lantern, 2/27/1978
Box 75 of 109	7830121 Jorss Iron Works - Photograph Library, 9/29/1978
Box 75 of 109	783012 Exterior Traffic Signage, 8/7/1978
Box 75 of 109	7830124 Transferred to OPlantS - Work Station Modification in Conservation Analytical Laboratory, 5/1/1978
Box 75 of 109	7830125 Dibner Library HVAC, 5/17/1979
Box 75 of 109	7830127 Associated Builders - Dibner Library Remodeling, 8/2/1978
Box 75 of 109	7830128 McGraw Hill Bookstore Modifications, 3/3/1979
Box 75 of 109	7830129 Red Room Expansion - First Ladies Hall, 12/1/1978
Box 75 of 109	7830130 Turnstiles, 12/7/1978
Box 75 of 109	1930108 Director's Suite, Secretary's Office, 12/29/1978
Box 75 of 109	7930114 Division of Ceramics and Glass Modifications, 2/21/1979
Box 75 of 109	7930116 Exhaust/Intake Cross Contamination, 3/27/1979
Box 75 of 109	7930123 Postal History Area - High Voltage Ionization Detector System, 8/13/1979
Box 75 of 109	7730113 Queen's Silver Jubilee Exhibit, 3/27/1977

Box 75 of 109	7730105 Atom Smasher Exhibit, 11/23/1977
Box 75 of 109	7730109 Perfect Likeness Exhibit, 3/25/1977
Box 75 of 109	7730122 Steam Engine Graphics Exhibit, 9/21/1977
Box 75 of 109	7830114 Art and Science, 1/3/1977
Box 75 of 109	7830113 Malspine Exhibit, 1/3/1977
Box 75 of 109	7830115 Chase Manhattan "Money," 12/13/1978
Box 75 of 109	7830116 Military History, 1/3/1977
Box 75 of 109	7830119 Automaton Case, 1/31/1977
Box 75 of 109	7830123 Mitchell's Telescope Base, 6/22/1978
Box 75 of 109	7830126 Bunker Furniture Case, 5/22/1978
Box 75 of 109	7930104 Einstein Exhibit, 11/14/1978
Box 75 of 109	7930110 New Curtains Room 4020, 2/2/1979
Box 75 of 109	7930118 Office and Storage Space Modifications - Musical Instruments Hall, 2/14/1979
Box 75 of 109	7930121 Rail of Electricity, 8/30/1979
Box 75 of 109	7830131 Earthenware - Remensnyder Collection, 9/19/1978
Box 75 of 109	8030109 Afro-American Tradition in the Decorative Arts, 11/14/1979
Box 75 of 109	8030113 Draperies - Fourth and Eighth Floors, 10/26/1979
Box 75 of 109	7930115 Agriculture Hall - Broken Fire Line
Box 75 of 109	North Terrace Water Control
Box 76	
Natural History Building Summary: Natural History Building	
Box 76 of 109	7531110 West Court, 12/23/1979 (2 folders)
Box 76 of 109	7531190 Rotunda Dome and Skylight, 7/27/1977

Box 76 of 109	7531196 East Range Tunnel and Library Floor Settlement, 12/28/1976
Box 76 of 109	7631101 Replace Heat Valves, 7/11/1977
Box 76 of 109	7631105 American Craft Shop, 11/1/1977
Box 76 of 109	7631237 Prince Construction Company - South Loop Sprinkler System, 8/4/1977
Box 76 of 109	7631245 Fur Storage, 9/26/1977
Box 76 of 109	7631257 J. W. Conway - East Wing Roof Repair, 7/18/1978
Box 76 of 109	7631262 Ingberg Mechanical - HVAC Repairs
Box 76 of 109	7631283 South Entrance Safety Nets, 10/4/1977
Box 76 of 109	7631310 A/E Selection for North and South Portals, 7/20/1978
Box 76 of 109	7631346 Spike Builders - Sprinkler System, 1/21/1977
Box 76 of 109	7631372 North Corridor Passages, 7/25/1979
Box 76 of 109	7631376 Fan Coil Unit Replacement, 8/22/1977
Box 76 of 109	7631388 East Wing Floor Loading Analysis, 5/31/1977
Box 76 of 109	7631389 Museum Shop Office, 3/14/1978
Box 76 of 109	7631400 West Court Roof Screens, 6/30/1977
Box 76 of 109	7631408 Conservation Analytical Laboratory Temperature and Humidity, 10/28/1976
Box 76 of 109	7631414 FJR Builders - West Court Stairs, 11/30/1978 (2 folders)
Box 77	
Box 77 of 109	7731103 Elevator Automation, 7/12/1978
Box 77 of 109	7731105 Prince Construction Company - Sprinkler System for Hall of Beautiful Things, 10/14/1977
Box 77 of 109	7631246 Registrar/Mail Room Expansion
Box 77 of 109	7731108 Paleo Laboratory Sink Relocation, 8/15/1977
Box 77 of 109	7731109 Exhaust System Rock Crusher Room, 9/15/1977

Box 77 of 109	7731112 Osteo Preparation Laboratory Hoist, 6/3/1977
Box 77 of 109	7731113 Kalmia Construction Company - Hall 26, 5/31/1978
Box 77 of 109	7731114 Prince Construction Company - Hall 10, 5/8/1979 (2 folders)
Box 77 of 109	7731115 Anthropological Office, 11/14/1978
Box 77 of 109	7731118 Baird Auditorium Partitions, 5/27/1977
Box 77 of 109	7731119 Museum Shop Electrical Service, 4/12/1977
Box 77 of 109	7731120 East Wing Lighting Renovation, 6/28/1978
Box 77 of 109	7731121 Baird Auditorium Stage Curtain, 9/26/1977
Box 77 of 109	7731124 Perennial Flower Bed, 7/25/1977
Box 77 of 109	7731125 Library Modifications Phases I, II, and III, 8/22/1977
Box 77 of 109	7731126 United States Geological Service Fume Hood Installation, 11/3/1977
Box 77 of 109	7731428 National Restoration - Exterior Repairs, 6/13/1978
Box 77 of 109	7831102 Transferred to OPlantS, Stage Downlight Switch System, 7/11/1979
Box 77 of 109	7831103 Hydraulic Lift Capacity, 12/2/1977
Box 77 of 109	7831104 SEM Laboratory HVAC, 10/1/1979
Box 77 of 109	7831105 Plant Shop in Museum Shop, 10/14/1977
Box 78	
Box 78 of 109	7831106 Mexican Masks Exhibit, 2/15/1979 (2 folders)
Box 78 of 109	7831107 Attic Floor Loading - Hall 10, 12/20/1977
Box 78 of 109	7831108 Replace Return Pumps, 11/1/1977
Box 78 of 109	7831109 Loading Dock Hose Headers, 11/1/1977
Box 78 of 109	7831110 Sound Levels, 12/20/1978
Box 78 of 109	7831111 Ground Fault Protection - Insect Zoo, 1/9/1978

Box 78 of 109	7831113 AE-Klepper, Marshall, and King - Baird Auditorium Acoustics, 4/2/1979
Box 78 of 109	7831114 Transferred to OPlantS, Staff Dining Area Ceiling, 8/28/1978
Box 78 of 109	7831115 Handicapped Restrooms, 2/3/1978
Box 78 of 109	7831116 Hall 16 Balcony Renovation, 1/9/1978
Box 78 of 109	7831117 Suburban Contractors - Hall 2 Handicapped Access, 6/21/1978
Box 78 of 109	7831120 Schmidlein Company - Sewage Ejector Spray Booth, 1/5/1979
Box 78 of 109	7831122 Office Cubicles, 6/22/1978
Box 78 of 109	7831123 Preparation of Drawings, 4/5/1979
Box 78 of 109	7831124 Photography Laboratory Renovation, 4/25/1978
Box 78 of 109	7831125 Lighting Redesign, 5/1/1978
Box 78 of 109	7831126 Hall 10 Attic Access, 6/1/1978
Box 78 of 109	7831127 Naturalist Center Modifications, 8/15/1978
Box 78 of 109	7831128 Museum Shops Office Expansion, 11/28/1978
Box 78 of 109	7831129 Exhibit Halls Humidity, 9/29/1978
Box 78 of 109	7831130 Computer Room Sound Barrier, 7/17/1978
Box 78 of 109	7831131 Stairwell Repair, 3/8/1979
Box 78 of 109	7831132 Transferred to OPlantS, Fume Hood and Sink Installation - Room EG4, 10/17/1978
Box 78 of 109	7831133 Loading Dock and Shop Storage Opening, 3/21/1979
Box 78 of 109	7831135 Transferred to OPlantS, West Wing Light Switch Additions, 1/14/1980
Box 78 of 109	7831136 ASAS Company - Sprinkler Sectional Control Valves, 2/15/1979
Box 78 of 109	7831137 Concrete Building Signs, 4/17/1979
Box 78 of 109	7831101 Sringar: An Exhibition of Indian Costumes, 11/7/1977
Box 78 of 109	7931117 Discovery Room, 5/7/1979

Box 78 of 109	7931105 Room 85 Air Quality Improvement, 2/8/1979
Box 78 of 109	7931106 Painting - West End of Whale Hall, 1/22/1979
Box 78 of 109	7931107 Baird Auditorium Stage, 4/27/1979
Box 78 of 109	7931108 Mall Entrance Safety Net Repair, 6/19/1979
Box 78 of 109	7931109 Fume Hood Installation, 3/14/1979
Box 78 of 109	7931111 Rest Room Facility - West Loading Dock, 4/10/1979
Box 78 of 109	7931113 Silkscreen Exhaust Facilities, 11/20/1979
Box 78 of 109	7931115 Craft Services Shop/Storage Facility, 5/30/1980
Box 78 of 109	7931116 Fume Exhaust System Improvements, 7/3/1979
Box 78 of 109	7931120 Hall 4 Ramp, 12/4/1979
	Smithsonian Institution Building Summary: Smithsonian Institution Building
Box 78 of 109	7532228 Lighting Renovation - Rooms B4, B5, and B5A, 8/30/1976
Box 78 of 109	7532348 Dentzel Carousel Photographs
Box 78 of 109	7632313 Louvered Shutter Blinds - Room 507, 4/13/1979
Box 78 of 109	7632378 American Museum Company, South Tower Renovation, 4/15/1977
Box 79	
Box 79 of 109	7632390 and 7732121 Prince Construction Company - North Tower Sprinkler System, 2/23/1978
Box 79 of 109	7732102 Joseph Henry Landscaping, 8/10/1977
Box 79 of 109	7732103 HVAC - Room 117, 5/18/1977
Box 79 of 109	7732104 Room 304 Division
Box 79 of 109	7732105 Clyde Dent - Commons Acoustics, 8/7/1978
Box 79 of 109	7732106 Rooms 457 and 458, 10/3/1977
Box 79 of 109	7732107 South Garden Fountain, 10/19/1979

Box 79 of 109	7732108 Fire Monitoring System, 10/25/1977
Box 79 of 109	7732109 Snack Bar Renovation, 11/15/1977
Box 79 of 109	7732401 Exterior Painting, 9/16/1977
Box 79 of 109	7732430 Herring Electric Company - Emergency Generator, 10/30/1979
Box 79 of 109	7832102 Sun Control, 12/12/1977
Box 79 of 109	7832103 Porte Cochere Repair, 4/24/1978
Box 79 of 109	7832104 Office of Protection Services Modifications, 9/8/1978
Box 79 of 109	7832105 Conduit Installation - Basement Corridor and Tunnel, 8/30/1978
Box 79 of 109	7832106 Flag Tower Smoke Detection, 1/3/1979
Box 79 of 109	7832108 Electrical Repair, 6/6/1978
Box 79 of 109	7932101 Deli Bar, 2/13/1979
Box 79 of 109	7932103 Remodel Rooms 133A, 133 B, and 133 C, 12/5/1978
Box 79 of 109	Microfilming Transmittals
	Arts and Industries Building Summary: Arts and Industries Building
Box 79 of 109	7733116 South Group Building Plans, 6/14/1977
Box 79 of 109	7733117 Photography Laboratory, 3/14/1978
Box 79 of 109	7733118 Steam Tunnels, 5/25/1978
Box 79 of 109	7733402 Office of Protection Services Office Space, 3/29/1976
Box 79 of 109	7733435 Air Conditioning - SI Magazine, 5/10/1978
Box 79 of 109	7733200 Microfilming
Box 79 of 109	7833191 OPersA Noise Suppression, 11/14/1977
Box 79 of 109	7833102 Archives Roof Leaks, 9/1/1978
Box 79 of 109	7833106 Security Storage Area, 5/11/1978
Box 79 of 109	7833107 Security Lighting, 1/20/1978

Box 79 of 109	7833109 Puppet Theatre, 10/31/1979 (2 folders)
Box 79 of 109	7833110 Room 1190A, 2/9/1979
Box 79 of 109	7833111 Computer Room Roof Leaks, 10/18/1979
Box 79 of 109	7833112 Hoist in Room 3269, 11/13/1979
Box 79 of 109	7833113 Wooden Doors, 8/3/1978
Box 79 of 109	7833114 HF Dolan Inc. - Personnel Office Reception Room, 9/9/1979
Box 80	
Box 80 of 109	7833115 Wooden Doors, 8/1/1978
Box 80 of 109	7833116 Window Survey, 6/20/1978
Box 80 of 109	7833117 Restrooms, 6/16/1978
Box 80 of 109	7833118 Suburban Contractors - Window Shutters, 2/13/1979
Box 80 of 109	7833119 Museum Shop Ventilation, 10/20/1978
Box 80 of 109	7833121 Anderson Notter/Mariani - Roof Study, 7/2/1979
Box 80 of 109	7833122 Office of Museum Programs Television Studio, 1/29/1979
Box 80 of 109	7833123 Air Conditioning Room 3351, 12/18/1978
Box 80 of 109	7933101 Exhibit Hall Ceiling Painting, 1/25/1979
Box 80 of 109	7933102 Suburban Glass Company - Sliding Doors and Window, Third Floor Modifications, 7/23/1979
Box 80 of 109	7933103 Associated Builders - Acoustical Treatment Room 2320, 10/31/1979
Box 80 of 109	7933104 Dolan - Personnel Office Reception Area, 8/9/1979
Box 80 of 109	7933105 Archives - Protection, 7/20/1979
Box 80 of 109	7933107 Ventilate Office of Protection Services Conference Room, 4/20/1979
Box 80 of 109	7933108 HVAC Room 1190A, 3/16/1979
Box 80 of 109	7933109 Personnel Office Space Requirements, 6/11/1979

Box 80 of 109	7933111 SI Press Bookstore Needs, 8/6/1979
Box 80 of 109	7933113 Rotunda Arc Lighting, 7/6/1979
Box 80 of 109	7933114 Office of Public Affairs Partitions, 7/12/1979
Box 80 of 109	7933115 Computer Center Drainage, 3/20/1980
Box 80 of 109	8033103 Smoke Detection, 10/18/1979
Box 80 of 109	8033104 Sprinkler Protection, 10/18/1979
Box 80 of 109	7733119 Air Conditioning Rooms 1260 and 1261
Box 80 of 109	7933107 Protection Office - Second Floor, West-North Range
Box 80 of 109	Archives
Box 80 of 109	7633365 Northern Virginia Construction Roof Restoration (Design Phase) (4 folders)
Box 80 of 109	7633210 SITES Kitchen, 4/12/1977
Box 81	
Box 81 of 109	7633217 Computer Room Modifications 4/7/1977
Box 81 of 109	7633223 Office Space Renovation, 5/3/1977
Box 81 of 109	7633301 Wishing Well - East Garden, 6/20/1979
Box 81 of 109	7633304 South Hall Passage Closures, 7/16/1976
Box 81 of 109	7633286 OPersA Office Modifications, 5/23/1977
Box 81 of 109	7633366 Information Booth, 11/20/1978
Box 81 of 109	7633380 Spiral Staircase Gates, 3/17/1977
Box 81 of 109	7633384 Arc Light Fixtures, 11/21/1977
Box 81 of 109	7633435 Free State Builders SI Magazine Offices, 2/10/1978
Box 81 of 109	7633436 Air Conditioning Modifications to East-South Range, 1/25/1977
Box 81 of 109	7733104 HVAC Northeast Range, 1/26/1977
Box 81 of 109	7733105 Shipping and Receiving Study, 4/20/1977

Box 81 of 109	7733108 Computer Installation, 11/9/1977
Box 81 of 109	7733110 HVAC Study, 7/29/1977
Box 81 of 109	7733111 Testing Device, 3/30/197
Box 81 of 109	7733112 SITES Kitchen, 8/22/1977
Box 81 of 109	7733113 Associates Travel Program, 2/24/1977
Box 81 of 109	7733114 Shutters - Room 2209, 10/21/1977
Box 81 of 109	7733115 Archives/SITES Soundproofing, 9/11/1978
Box 81 of 109	7633397 Casework for SITES
Box 81 of 109	Associates Classrooms
Box 81 of 109	7633365 Photographs and Construction Supervision Files of the Northern Virginia Construction Company - Roof Restoration (folders 1-3 of 9)
Box 82	
Box 82 of 109	7633365 Photographs and Construction Supervision Files of the Northern Virginia Construction Company - Roof Restoration (folders 4-9 of 9)
Box 82 of 109	7833120 Resident Associate Space Plan - Rooms 1230 and 1236, 10/2/1978
Box 82 of 109	7833108 Horticulture Offices, 11/28/1977
Box 82 of 109	7833600 Pre-microfilming Drawing Review
	American Art and Portrait Gallery Summary: American Art and Portrait Gallery
Box 82 of 109	7934125 Harry Betoia Sculpture, 11/26/1979
Box 82 of 109	7934124 Rearrange First Floor Corridor, 7/12/1979
Box 82 of 109	7934120 Redesign Miniature Gallery, 5/16/1979
Box 82 of 109	7934112 Robert Edge Pine Exhibit, 7/25/1979
Box 82 of 109	7934111 Sculpture and the Federal Triangle, 4/2/1979
Box 82 of 109	7934108 Jack Dempsey Exhibit, 1/19/1979

Box 82 of 109	7934106 Associated Builders - Return to Albion, 3/28/1979
Box 82 of 109	7934104 Western States Biennial Exhibit, 4/12/1979
Box 82 of 109	7934103 Jackson Pollock, 10/20/1978
Box 82 of 109	7934102 Collages by Irwin Kreman, 10/20/1978
Box 82 of 109	7934101 William Henderson, 10/20/1978
Box 82 of 109	7834131 Seymour Lipton Exhibit, 10/23/1978
Box 82 of 109	7834124 Corning Construction - Adams Area, 8/25/1978
Box 83	
Box 83 of 109	7834119 Provincetown Woodcuts, 3/13/1978
Box 83 of 109	7834118 Alaskan Arts Exhibit, 3/13/1978
Box 83 of 109	7834111 Nineteenth Century Landscape, 1/31/1978
Box 83 of 109	7834110 Wall Panel, 1/31/1978
Box 83 of 109	7834109 "Past and Present," 4/14/1978
Box 83 of 109	7834105 Salemme Exhibit, 1/11/1978
Box 83 of 109	7734107 "Embroidery Through the Ages," 8/23/1978
Box 83 of 109	7734104 "California Painting and Sculpture," 3/2/1977
Box 83 of 109	Report by Universal Engineering Company, September 1967
Box 83 of 109	7934127 Rewiring for Entrex Installation, 9/25/1977
Box 83 of 109	7934123 Library Lighting Modifications, 8/17/1979
Box 83 of 109	7934122 Archival Storage Room, 6/1/1979
Box 83 of 109	7934121 Building Manager Office Relocation, 12/21/1979
Box 83 of 109	7934119 Archives of American Art Fire Doors, 5/30/1979
Box 83 of 109	7934118 Storage Area Construction, 5/16/1979
Box 83 of 109	7934117 Second Floor Gallery, 8/10/1979

Box 83 of 109	7934116 Fourth Floor Library Modifications, 7/18/1979
Box 83 of 109	7934115 Repainting Granite Gallery, 5/8/1979
Box 83 of 109	7934114 Basement Conversion, 6/27/1979
Box 83 of 109	7934113 Koffler Collection, 5/8/1979
Box 83 of 109	7934110 Archives of American Art Modifications, 1/12/1979
Box 83 of 109	7934107 A/E Contract Requirement, 12/5/1979
Box 83 of 109	7934105 Light Fixtures Room B-41, 12/4/1978
Box 83 of 109	7834133 Exhaust System Photography Laboratory, 2/25/1980
Box 83 of 109	7834132 Dust Collector, 3/5/179
Box 83 of 109	7834130 Haptic Room, 11/14/1978
Box 83 of 109	7834129 Archives of American Art Move, 11/7/1978
Box 83 of 109	7834128 Hot Water Heater for Kiosk, 7/7/1978
Box 83 of 109	7834127 Room 348 Lighting, 12/19/1979
Box 83 of 109	7834126 Archives of American Art - Washington Center, 9/27/1978
Box 83 of 109	7834123 Library Lighting, 11/28/1978
Box 83 of 109	7834122 Film Installation Gallery, 2D, and 2G, 5/19/1978
Box 83 of 109	7834121 Compugraphic Typesetting Room, 3/8/1979
Box 83 of 109	7834120 Courtyard Kiosk Sink Installation, 6/7/1978
Box 83 of 109	7834117 Rose Valley Construction Company - "The Time of Our Lives," 3/28/1978
Box 83 of 109	7834116 Modifications - Room B-58, 4/6/1978
Box 83 of 109	7834114 "Past and Present," 1/31/1978
Box 83 of 109	7834113 Enlarge Hanging Space, 3/20/1978
Box 83 of 109	7834108 Restroom Modifications for Handicapped, 9/5/1979
Box 83 of 109	7834107 Steam Condensation Room 111, 1/10/1978

Box 83 of 109	7834106 Sound Levels, 12/20/1978
Box 83 of 109	7834103 Welch and Rushe Inc., Replace Domestic Water Valves, 4/2/41979
Box 83 of 109	7834102 Third Floor Mexxanine Storage, 1/3/1978
Box 83 of 109	7834101 South Portico Cafe, 11/13/1978
Box 83 of 109	7734440 Valve Leakage, 2/22/1977
Box 83 of 109	7734438 Toilet Modifications, 2/23/1977
Box 83 of 109	7734111 Large Painting Storage Area, 2/27/1978
Box 83 of 109	7734110 B. R. A. Contractors - Painting, 12/9/1977
Box 83 of 109	7734109 UVAC Rooms 116, 210, 211, and 313, 4/19/1978
Box 84	
Box 84 of 109	7734108 Associated Builders - Silkscreen and Paint Room, 6/21/1978
Box 84 of 109	7734103 A/E Board for HVAC Study, 4/17/1978
Box 84 of 109	7734102 Mueller Associates - HVAC, 4/18/1979 (2 folders)
Box 84 of 109	7734404 Garage Conversion, 8/30/1976
Box 84 of 109	7634352 Associated Builders - Automated Entrance Doors, 8/23/1979
Box 84 of 109	7634333 Attic Asbestos, 2/10/1977
Box 84 of 109	7634253 South Portico Repair, 1/23/1978
Box 84 of 109	7634101 Ductwork Insulation, 2/10/1977
Box 84 of 109	7634251 Exterior Repairs and Painting, 7/11/197
Cooper-Hewitt Museum Summary: Cooper-Hewitt Museum	
Box 84 of 109	7936106 Buildings Reborn: New Uses, Old Places, 2/6/1979
Box 84 of 109	7936109 Basement Modifications, 7/11/1979
Box 84 of 109	7936104 The Art of Russia, 1/12/1979

Box 84 of 109	7936103 Olaf Skoogfors, 1/18/1979
Box 84 of 109	7936102 Clay, 11/27/1978
Box 84 of 109	7936101 Galleries 202, 203, and 207, 12/12/1978
Box 84 of 109	7936111 New stained Glass, 7/13/1978
Box 84 of 109	7936110 Clay Figures and Mexican Masks, 7/13/1978
Box 84 of 109	7936107 Printed, Painted, and Dyed, 5/18/1978
Box 84 of 109	7936104 Ronald Pearson: Recent Works in Metal, 1/13/1978
Box 84 of 109	7836103 Treasures of Belgian Jewelry, 1/13/1978
Box 84 of 109	7836101 French Folk Art, 9/8/1977
Box 84 of 109	7736109 Iron/Solid Wrough/USA, 4/21/197
Box 84 of 109	7736108 Contemporary Musical Instruments, 4/15/1977
Box 84 of 109	7736107 Frank Lloyd Wright Exhibit, 9/23/1977
Box 84 of 109	7736104 Grass Exhibition, 6/3/1977
Box 84 of 109	7736103 Polish Textile Exhibit, 4/6/1977
Box 84 of 109	7736101 Decorated American Furniture, 1/18.1977
Box 84 of 109	7936111 Repair/Replace Wooden Window Frames, 8/16/197
Box 84 of 109	7936110 Exterior Floodlights, 8/16/1977
Box 84 of 109	7936108 Grand Salon Occupancy Limits, 12/5/1979
Box 84 of 109	7936107 Scotchtint Gallery 204, 3/13/1979
Box 84 of 109	7936105 Grand Salon Floor Receptacles, 1/22/1979
Box 84 of 109	7836115 Lift Platform, 8/16/1978
Box 84 of 109	7836109 Basement Modifications, 8/20/1979
Box 84 of 109	7836108 Scotchtint, 7/13/1978
Box 84 of 109	7836105 Restroom Modifications, 4/11/1978

Box 84 of 109	7836102 Construction Services Inc., Galleries 104 and 105, 5/19/1978
Box 84 of 109	736441 Basement Rooms B6 and B26, 4/12/1977
Box 84 of 109	7636278 Lighting Modifications, 3/21/1977
Box 85	
	Freer Gallery of Art Summary: Freer Gallery of Art
Box 85 of 109	7837103 Storm Windows, 11/1/1977
Box 85 of 109	7837101 Exhibit Galleries Renovation, 11/9/1977
Box 85 of 109	7737273 Consolidated Elevator Company - Elevator Modifications, 9/26/1978
Box 85 of 109	7737203 Stone Joint Maintenance, 7/28/1977
Box 85 of 109	7737103 Steam Station, 7/15/1977
Box 85 of 109	7737102 Cloak Room, 6/28/1978
Box 85 of 109	7537137 Construction Services Inc. - Handrails, 8/25/1978
Box 85 of 109	7937102 Pilot Test for Lighting, 11/8/1979
Box 85 of 109	Freer Doors
Box 85 of 109	Hartman-Cox Feasibility Study for the Freer Courtyard Enclosure
Box 85 of 109	Lee-Thorp Study of Roofing and Skylight Systems
	Silver Hill Summary: Silver Hill
Box 85 of 109	7638259 Associated Builders - New Paint Booth, Building 10, 2/27/1979
Box 85 of 109	7738101 Hanlon Construction Company, Inc. - Roof Storage, Building 10, 2/27/1979
Box 85 of 109	7738103 and 7738116 Applicators Inc. - Road Repairs and Water Main, 9/21/1978
Box 85 of 109	7738104 Building 10 Office Space, 1/4/1978
Box 85 of 109	7738105 Associated Builders - Modifications to Various Buildings, 2/1/1979 (3 folders)

Box 85 of 109	7738106 VVKR Partnership - Building 10, Locker Room and Storage Area, 5/9/1977
Box 85 of 109	7738107 Refurbish Offices, 3/31/1977
Box 85 of 109	7738108 Preservation Area - Building 10, 5/25/1977
Box 85 of 109	7738110 Concrete Pad Between Buildings 1 and 10, 5/9/1977
Box 85 of 109	7738111 Overhead Doors - Building 10, 4/12/1978
Box 86	
Box 86 of 109	7738112 Building 8 Modifications, 5/25/1977
Box 86 of 109	7738113 New Buildings 13 and 14, 11/9/1979
Box 86 of 109	7738114 Concrete Pad for Polaris Missile, 7/6/1977
Box 86 of 109	7738117 Roadway Between Buildings 11 and 12, 8/3/1977
Box 86 of 109	7738118 Frick Electric - New Wiring, 10/26/1978
Box 86 of 109	7738119 Dust Collector Enclosure, 3/30/1977
Box 86 of 109	7738120 Prefabricated Office - Building 21, 8/21/1978
Box 86 of 109	7738116 Supplemental Fire Protection System
Box 86 of 109	738121 Heat, 9/19/1977
Box 86 of 109	7738122 Moore Electric Company - Building 13, Silkscreen Exhaust, 9/27/1978
Box 86 of 109	7738123 Insulation - Buildings A and B, 3/30/1978
Box 86 of 109	7738323 Liner - Building 10, 8/15/1977
Box 86 of 109	7738405 Suburban Contractors - Egress Doors, 9/1/1977
Box 86 of 109	7738446 Vent Fans, 3/1/1977
Box 86 of 109	7838102 Compressor Shed, 3/8/1978
Box 86 of 109	7838103 Prince Construction Company - Fire Protection System and Water Line Extension, 9/29/1978
Box 86 of 109	7838104 Welch and Rushe - Replace Heaters, Building 10, 6/19/1979

Box 87

Box 87 of 109 7838105 Associated Builders - Fiberglass Insulation Panels, 9/27/1978

Box 87 of 109 7838106 Paving MHT Area, 5/25/1978

Box 87 of 109 7838101 Building 18, 12/8/1978

Box 87 of 109 7838102 Asbestos Confinement, 11/9/1979

Box 87 of 109 7938108 Environmental Control Chambers, 10/30/1977

Barney Studio House
Summary: Barney Studio House

Box 87 of 109 Barney House Photographs

Box 87 of 109 7642350 Suburban Contractors - Emergency Stairs and Escape Ladder, 4/30/1979 (3 folders)

Chesapeake Bay Center for Environmental Studies
Summary: Chesapeake Bay Center for Environmental Studies

Box 87 of 109 7744101 Precision Piping - Sewage System, 8/11/1978

Box 87 of 109 7744600 Wetlands, 8/17/1977

Box 87 of 109 7844102 Wilson's Welding Service - Silo Modifications, 9/21/1978

Box 87 of 109 7844103 Jack Malakatis - Jefferson Island Lodge, 7/21/1978

Box 87 of 109 7844105 Old Dominion Building Renovation, 5/24/1978

Box 87 of 109 7844106 Topographic Survey, 9/18/1978

Box 87 of 109 7844107 Jefferson Island Shore Protection, 9/4/1979

Box 87 of 109 7844108 Old Dominion Building Modifications, 11/21/1978

Box 87 of 109 7944101 Silo Modifications - Phase II, 5/9/1979

Box 87 of 109 7944102 Water System Upgrading, 9/16/1979

Box 88

Box 88 of 109 7844600 Composite Map

Box 88 of 109 764253 CBCES Space Requirements, 6/8/1975

Hirshhorn Museum and Sculpture Garden
Summary: Hirshhorn Museum and Sculpture Garden

Box 88 of 109	7645200 Garden, 12/1/1977
Box 88 of 109	7645284 Hamilton and Spiegel - Roof Repairs, 12/8/1978
Box 88 of 109	7645101 Helmut Guenschel - Freight Elevator Doors, 4/19/1977
Box 88 of 109	7745102 Prince Construction - Auditorium Smoke Detection, 12/14/1977
Box 88 of 109	7745103 Window Washing Safety Device, 3/23/1977
Box 88 of 109	7745105 Subsidence in Jefferson Drive, 9/28/1979
Box 88 of 109	7745106 Air Contamination, 6/17/1977
Box 88 of 109	7745107 Glass Partition Wall, 8/26/1977
Box 88 of 109	7745108 Settlement Cracks, 7/19/1978
Box 88 of 109	7745109 DiSuvero Sculpture, 6/12/1978
Box 88 of 109	7745447 Restrooms, 10/22/197
Box 88 of 109	7845101 Noise Levels, 12/20/1978
Box 88 of 109	7845102 Associated Builders - Cracked Plaza, 11/5/1979
Box 88 of 109	7845103 Plaza Security Lighting, 11/13/1978
Box 88 of 109	7845104 Underground Tunnel, 1/19/1978
Box 88 of 109	7845107 Museum Shop Modifications, 3/2/1978
Box 88 of 109	7845110 Harmonic Hum, 5/30/1978
Box 88 of 109	7845111 Smoke Detection Reliability, 5/9/1978
Box 88 of 109	7845115 Electrical Systems, 9/22/1978
Box 88 of 109	7845116 Partition Wall, 2/14/1979
Box 88 of 109	7845118 Plaza Plantation, 8/21/1978
Box 88 of 109	7845119 Energizing Power for Communications/Alarm, 7/16/1979
Box 88 of 109	7945108 Balcony Cracks, 11/2/1979

Box 88 of 109	7945109 Skylights, 6/27/1979
Box 88 of 109	7945111 Projection Booth Modifications/Speaker Installation, 6/29/1979
Box 88 of 109	7945104 Niizuma Sculpture Base, 2/9/1977
Box 88 of 109	7845105 Europe in the 1970s, 1/24/1978
Box 88 of 109	7845106 El Guatre Gat, 2/14/1978
Box 88 of 109	7845108 Mexican Show, 2/27/1978
Box 88 of 109	7845109 Quinn Exhibit, 3/22/1978
Box 88 of 109	7845112 Phillip Evergood, 4/28/1978
Box 88 of 109	7845113 Grosz, 4/28/1978
Box 88 of 109	7845114 Henry Moore, 4/28/1978
Box 88 of 109	7945102 Calder Exhibit, 11/17/1978
Box 88 of 109	7945105 Directions, 3/14/1979
Box 88 of 109	7945106 Ambulatory Installation Scheduling, 3/26/1979
Box 88 of 109	7945110 Gorky Exhibit, 7/10/1979
Box 88 of 109	8045101 Miro Exhibit, 7/10/1979
	Anacostia Neighborhood Museum Summary: Anacostia Neighborhood Museum
Box 88 of 109	7846106 "Out of Africa," 11/1/1978
Box 88 of 109	7946102 Anna Cooper Exhibit, 7/9/1979
Box 88 of 109	8046101 Research Relocation, 10/31/1979
	Box 89
Box 89 of 109	7646260 Basement Ventilation, 9/14/1977
Box 89 of 109	7646269 Air Conditioning, 4/13/1977
Box 89 of 109	7646373 Weiss Construction Inc. - Design and Production Laboratory Fire Damage Repair, 6/7/1978

Box 89 of 109	7646383 Golden Construction - New Paint Spray Booth, 9/17/1979
Box 89 of 109	7846101 Moisture Proof Basement Walls, 11/1/1977
Box 89 of 109	7846102 Dust Control - Photography Laboratory, 3/28/1978
Box 89 of 109	7846103 Hot Water for Silkscreen Room, 3/13/1979
Box 89 of 109	7846105 Noise Pollution - Multi-purpose Room, 1/12/1979
	Various Buildings Summary: Various Buildings
Box 89 of 109	7632287 Fourth Floor Camponile Tower
Box 89 of 109	Proposals for Various Buildings (5 folders)
	Cooper-Hewitt Museum Summary: Cooper-Hewitt Museum
Box 89 of 109	7548106 Grenadier Corporation - Carnegie Mansion Renovation, 1/8/1979
Box 89 of 109	7648345 New-Again Construction Company - Fourth Floor Renovation, 1/12/1977
Box 89 of 109	7648427 Textile Study Center, 6/9/1978
Box 89 of 109	7848103 New-Again Construction Company - Caulking, 6/29/1979
Box 89 of 109	7748105 Maintenance Lounge Redesign, 3/7/1977
Box 89 of 109	7748106 Exterior Lighting, 3/24/1977
Box 89 of 109	7848101 Miller House Smoke Detection, 1/24/1978
Box 89 of 109	7848192 Paper Conservation Laboratory, 12/12/1978
Box 89 of 109	7848103 New-Again Construction Company - Parking Area Beams, 6/13/1979
Box 89 of 109	7848104 Water Intrusion - Carnegie Mansion, 10/20/1978
Box 89 of 109	7948102 Space Utilization Survey, 8/8/1979
Box 89 of 109	7948113 Miller House Flashing, 5/14/1979
Box 89 of 109	7948114 Textile Conservation Laboratory Materials, 4/24/1979

Box 89 of 109	7948117 Staff Entrance Steps, 5/5/1979
Box 89 of 109	7948119 Skid Proofing, 4/20/1979
Box 89 of 109	7948120 Granite Tread Main Entrance, 4/20/1979
Box 89 of 109	7748107 Palladio Exhibit, 4/25/1977
Box 89 of 109	7748108 Two Hundred Years of American Architecture, 4/25/1977
Box 89 of 109	7748109 Cooper-Hewitt Collections, 3/17/1977
Box 89 of 109	7748111 More Than Meets the Eye, 4/23/1977
Box 89 of 109	7748112 Subways (Immovable Objects), 10/31/1977
Box 89 of 109	7748105 Ludwig of Bavaria, 1/18/1979
Box 90	
Box 90 of 109	7748103 Brighton Exhibit
Box 90 of 109	7648427 Textile Study Center and Paper Conservation Laboratory
Box 90 of 109	7648345 Rooms 401, 408, 409, and 410
Box 90 of 109	7848600 Index to Drawing of Carnegie Mansion
Box 90 of 109	7848106 Embroidery Through the Ages, 5/5/1978
Box 90 of 109	7848108 Place, Product, and Packaging, 12/20/1977
Box 90 of 109	7848109 Shopping Bag Design, 12/20/1977
Box 90 of 109	7848110 Museum of Drawers, 1/9/1978
Box 90 of 109	7848111 EC Looks at LA, 6/29/1978
Box 90 of 109	7848112 Ornaments of the Twentieth Century, 9/25/1978
Box 90 of 109	7848114 Design from the Movies, 6/15/1978
Box 90 of 109	7848116 Artists Postcards, 10/5/1978
Box 90 of 109	7948101 Shopping Bag Exhibit, 11/6/1978
Box 90 of 109	7948103 Advertising Design, 2/26/1978

Box 90 of 109	7948104 Space = Time in Japan, 2/16/1979
Box 90 of 109	7948105 Japanese Collections of the Cooper-Hewitt, 12/13/1978
Box 90 of 109	7948106 Roma Interlotta, 2/15/1979
Box 90 of 109	7948107 Fantastic Illustration and Design in Britain, 12/13/1978
Box 90 of 109	7948108 Alvar Aalto, 5/16/1979
Box 90 of 109	7948109 Museum Shops Renovation, 12/18/1979
Box 90 of 109	7948110 Product Design, 2/26/1979
Box 90 of 109	7948111 Porcelain Show, 2/22/1979
Box 90 of 109	7848113 Cross Currents, 7/31/1978
Box 90 of 109	7848115 Vienna Moderne, 10/19/1978
Box 90 of 109	7948122 Glass from the Cooper-Hewitt Collection, 8/14/1979
Box 90 of 109	7948121 Urban Open Spaces, 6/18/1979
	Smithsonian Tropical Research Institute Summary: Smithsonian Tropical Research Institute
Box 90 of 109	8050110 Seawater System Tank Repairs, 6/6/1980
Box 90 of 109	8050105 Bulkheading/Fuel Storage, 6/6/1980
Box 90 of 109	8050104 Naos Island Pier Painting and Repair, 6/27/1980
Box 90 of 109	7950101 STRI Dormitory, 4/15/1980
Box 90 of 109	7950103 Ancon Library Furnishings, 6/29/1979
Box 90 of 109	7950104 Gorgas Laboratory Interior, 6/28/1979
Box 90 of 109	7750102 Library Renderings, 8/16/1977
Box 90 of 109	7850104 Electrical Repairs, 11/8/1978
Box 90 of 109	7850103 Air Conditioning System for Lower Laboratory Building, 12/3/1977
Box 90 of 109	7850102 Demolish Parocino House, 11/1/1977

Box 90 of 109	7850101 Renovate Vitola House, 11/1/1977
Box 90 of 109	7750101 STRI Interior, 5/17/1978
Box 90 of 109	7650227 Library, 3/7/1979
Box 91	
Box 91 of 109	7650143 Tram Lift, 4/4/1979
Box 91 of 109	7650141 Tivoli Renovation, 2/16/1978
Smithsonian Astrophysical Observatory Summary: Smithsonian Astrophysical Observatory	
Box 91 of 109	7551145 Mount Hopkins - Electrical Distribution System Expansion
Box 91 of 109	7551146 Mount Hopkins Road Water Systems (4 folders)
Chesapeake Bay Center for Environmental Studies Summary: Chesapeake Bay Center for Environmental Studies	
Box 91 of 109	7644258 Laboratory Addition (folders 1-2 of 5)
Box 92	
Box 92 of 109	7644258 Laboratory Addition (folders 3-5 of 5)
Various Buildings Summary: Various Buildings	
Box 92 of 109	7500300 Exhibit Case Review, 3/1/1978
Box 92 of 109	7600220 Goff's Office Modifications, 3/1/1977
Box 92 of 109	7600317 Silkscreen Room - SISC (Smithsonian Institution Service Center), 5/13/1976
Box 92 of 109	7600322 HVAC at SISC, 5/10/1978
Box 92 of 109	7600407 Third Floor Dust Collecting System, 8/30/1977
Box 92 of 109	7600443 MAO Modifications, 11/19/1976
Box 92 of 109	7700103 Last Site on Mall, 1/7/1977
Box 92 of 109	7700104 Smoke Detection Plans, 11/21/1977

Box 92 of 109	7700109 Preventative Maintenance on Transformers and Switchgears, 2/3/1977
Box 92 of 109	7700110 As-built Drawings - Soldiers Home Greenhouse, 10/20/1977
Box 92 of 109	7700111 Museum Shop Case Modifications, 3/17/1977
Box 92 of 109	7700112 Reading is Fundamental Space Analysis, 11/0/1977
Box 92 of 109	7700114 Plastic Greenhouse Construction, 5/31/1977
Box 92 of 109	7700115 OFPES Office Modifications, 8/22/1978
Box 92 of 109	7700116 Renovation of Audiovisual Equipment, 3/8/1978
Box 92 of 109	7800101 NAFC Dehumidifier, 11/17/1977
Box 92 of 109	7800102 HVAC Modifications - Third Floor, SISC, 4/3/1979
Box 92 of 109	7800103 OFPES Office Modifications, 8/22/1978
Box 92 of 109	7800104 Belmont Game Room Modifications, 9/26/1978
Box 92 of 109	7800105 Vapor Removal from Cooking Equipment, 12/1/1977
Box 92 of 109	7800106 SISC Sprinkler System Modifications, 11/1/1977
Box 92 of 109	7800108 Fourth Floor Space Modifications - SISC, 4/5/1978
Box 92 of 109	7800109 Tariff Commission Building, 7/12/1979 (2 folders)
Box 93	
Box 93 of 109	7800111 Office of Exhibits Central - SISC, 3/22/1978
Box 93 of 109	7800113 Accounting Modifications, 9/21/1978
Box 93 of 109	7800114 Conservation Fume Hood - SISC, 5/8/1978
Box 93 of 109	7800115 Mail Order Warehouse Modifications, 12/27/1978
Box 93 of 109	7800116 Defective Sprinkler Heads, 6/23/1978
Box 93 of 109	7800118 Peace Corps Office, 5/26/1978
Box 93 of 109	7800119 Belmont Site Work, 8/24/1978
Box 93 of 109	7800120 Lansburgh Building, 11/6/1978

Box 93 of 109	7800122 Study of OFPES, 12/12/1978
Box 93 of 109	7800123 SI Involvement - Historic Preservation, 10/27/1978
Box 93 of 109	7800124 SISC Storage Door Height, 7/11/1980
Box 93 of 109	7800125 Fire Detectors, 6/2/1978
Box 93 of 109	7800126 Audits Office Modifications, 9/26/1978
Box 93 of 109	780129 Darwin Construction Company - Steam Supply, 5/25/1979
Box 93 of 109	7800130 Belmont Storm Windows, 6/26/1979
Box 93 of 109	7800131 Air Quality Plan, 12/13/1978
Box 93 of 109	7900101 SISC Partition, 2/12/1980
Box 93 of 109	7900102 GIAD Office Modifications, 11/8/1978
Box 93 of 109	7900104 Electric Transformer study, 11/7/1978
Box 93 of 109	7900106 Pension Building, 4/6/1979
Box 93 of 109	7900107 Hazardous Waste Guidelines, 2/23/1979
Box 93 of 109	7900108 Access Control, 1/5/1979
Box 93 of 109	7900109 OFPES Camera Room, 11/11/1978
Box 93 of 109	7900110 Old Central Library, 12/22/1978
Box 93 of 109	7900111 Federal Capital Improvements Program, 4/6/1979
Box 93 of 109	7900112 Site Utilities - Folklife Festival, 8/27/1979
Box 93 of 109	7900113 Programmable Lighting System, 3/1/1979
Box 93 of 109	7900114 Bedroom Modifications at Belmont, 7/10/1980
Box 93 of 109	7900116 MAO's Word Processing Room, 5/9/1979
Box 93 of 109	7900117 Security Office at L'Enfant, 9/25/1979
Box 93 of 109	7900120 Computer Room Data Distribution Station, 7/31/1979
Box 93 of 109	7900121 AIA Request, 8/24/1979

Box 94

Box 94 of 109	7900122 Washington Woodworking - Parking Ticket Depositories, 10/8/1979
Box 94 of 109	7900123 and 7900124 Electric Meters for A&I, SI Building, and FGA, 8/29/1979
Box 94 of 109	7900128 L'Enfant 2600 Modifications, 11/16/1978
Box 94 of 109	L'Enfant, Suite 3300
Box 94 of 109	7800117 Folklife Festival Mining Exhibit, 9/20/1978
Box 94 of 109	7800127 Grants and Insurance Office Modifications, 1/30/1979
Box 94 of 109	7900105 Department of Public Affairs Office Modifications, 1/30/1979
Box 94 of 109	7900115 Professional Registration Roster, 4/6/1979
Box 94 of 109	7900119 Accounting Office Modifications, 7/5/1979
	National Air and Space Museum Summary: National Air and Space Museum
Box 94 of 109	7635374 SWG Inc. - Flagpole, 3/24/1977
Box 94 of 109	7635419 Delta Solar Sculpture, 10/30/1979
Box 94 of 109	7735000 Miscellaneous, 5/20/1977
Box 94 of 109	7735101 Electrical System, 1/24/1977
Box 94 of 109	7735102 Weiss Construction - Gallery 207, 1/9/1978
Box 94 of 109	7735103 MNH Construction - Third Floor Ceiling Access Doors, 11/19/1979
Box 94 of 109	7735107 Exterior Grounds Maintenance Water Problems, 11/3/1977
Box 94 of 109	7735108 Spacearium Signage, 3/2/1977
Box 94 of 109	7735109 J. F. Ulrich and Sons - Granite Planter, 12/8/1978
Box 94 of 109	7735113 Descent to Venus, 6/6/1978
Box 94 of 109	7735114 Spacearium Overheating, 5/12/1978

Box 94 of 109	7735115 C and L Construction - Air Conditioning Audiovisual Room, 3/15/1979
Box 94 of 109	7735116 Air Transportation Exhibit, 5/17/1977
Box 94 of 109	7735117 H. F. Dolan Company - Cafeteria Renovation, 2/6/1978
Box 94 of 109	7735120 Projector Lamp Cooling, 2/15/1979
Box 94 of 109	7735122 Linkous Contracting Company - Paver Removal, 6/27/1979
Box 94 of 109	7735123 Suburban Contractors - Library, 1/26/1978
Box 94 of 109	7735124 Sandwich Carousel, 3/17/1978
Box 95	
Box 95 of 109	7735125 Revolving Doors, 1/19/1978
Box 95 of 109	7735127 Wind Screens and Guard Booth, 9/8/1977
Box 95 of 109	7735419 Delta Solar Sculpture, 9/9/1977
Box 95 of 109	7835101 Health and Safety Inspection, 3/23/1978
Box 95 of 109	7835102 Enclosure of Cash Register Area, 10/14/1977
Box 95 of 109	7835103 Rear Screen Projection, 10/18/1977
Box 95 of 109	7835104 Suburban Contractors - Stairwell Wind Screen, 1/17/1978
Box 95 of 109	7835106 Trash Room, 11/7/1977
Box 95 of 109	7835107 East Terrace Changes, 11/14/1978
Box 95 of 109	7835108 Recaulking North Wall, 1/16/1978
Box 95 of 109	7835110 Rogay Inc. - Garage Signage, 12/12/1978
Box 95 of 109	7735119 Monorail
Box 95 of 109	7835114 Water Line Surging, 11/2/1978
Box 95 of 109	7835116 Beverage Trailer, 7/27/1978
Box 95 of 109	7835118 Galaxy Sculpture, 3/3/1978
Box 95 of 109	7835119 Theatre Ceiling Fixtures, 5/8/1976

Box 95 of 109	7835120 Precision Piping - Condenser Water Strainer, 11/2/1979
Box 95 of 109	7835121 Theatre Load capacity, 11/14/1978
Box 95 of 109	7835123 NASM Drawings, 4/12/1978
Box 95 of 109	7835124 Vent Fan - Museum Shop Office, 5/8/1978
Box 95 of 109	7835125 Projection Booth Access Door, 9/21/1978
Box 95 of 109	7835127 Laserium Plumbing and Electrical, 7/19/1978
Box 95 of 109	7835130 Hoist Installation, 5/5/1978
Box 95 of 109	7835131 Portable Aluminum Ramps, 6/13/1978
Box 95 of 109	7835132 Carbon Dioxide Monitoring Garage, 5/11/1978
Box 95 of 109	7835133 Sprinkler System, 2/16/1979
Box 95 of 109	7835137 Apollo to the Moon, 9/4/1978
Box 95 of 109	7835138 Associated Builders - Ticket Booth and Railings Barrier, 9/27/1978
Box 95 of 109	7835141 Southern Insulation - Insulate Ductwork, 10/30/1978
Box 95 of 109	7835142 Roof Study, 12/10/1979
Box 95 of 109	7835143 Escalators Guard, 5/30/1979
Box 95 of 109	7835144 Rear Projection Screen, 10/3/1978
Box 95 of 109	7935101 Mechanical and Electrical Room - Smoke Detection, 9/29/1978
Box 95 of 109	7935103 New Parking Equipment, 2/12/1979
Box 95 of 109	7935104 Double Eagle II Gondola, 11/20/1978
Box 95 of 109	7935109 Swinging Doors, 3/15/1979
Box 95 of 109	7935113 Loading Dock Overhead Door, 6/20/1979
Box 95 of 109	7935114 Precision Piping - Condenser Water Strainers and Piping, 7/2/1979
Box 95 of 109	7735111 Spacearium Shop, 4/8/1977

Box 95 of 109	7735112 Lindbergh Exhibit, 4/15/1977
Box 95 of 109	7835105 Doolittle Exhibit, 11/16/1977
Box 95 of 109	7835109 Sound for Rocketry and Space Flight, 1/11/1978
Box 95 of 109	7835111 Leoning Memorial Exhibit, 2/1/1978
Box 95 of 109	7835112 Education Office and Classrooms, 10/12/1979
Box 95 of 109	7835113 Vertical Flight, 7/10/1978
Box 95 of 109	7835117 West Gallery - Operating Balloon Base, 4/27/1978
Box 95 of 109	7835126 Apollo Stamp Cases, 4/27/1978
Box 95 of 109	7835135 Live Demonstrations, 7/10/1978
Box 95 of 109	7835136 Art Gallery 211, 8/31/1978
Box 96	
Box 96 of 109	7935106 MNJ Construction - Gallery 107, 11/9/1979
Box 96 of 109	7935110 Cash Stand, 4/25/1979
Box 96 of 109	7935111 Live Demonstration Theatre, 8/9/1977
Box 96 of 109	7935115 Apollo 11 - Tenth Anniversary, 6/13/1979
Box 96 of 109	7935120 Viking Lander Platform, 9/4/1979
Various Buildings Summary: Various Buildings	
Box 96 of 109	7800121 Special Mall Parking Study by DeLeuw Cather Company
Arts and Industries Building Summary: Arts and Industries Building	
Box 96 of 109	General
Box 96 of 109	AIA (Historic Preservation Awards Program)
Box 96 of 109	7633397 SITES Casework
Box 96 of 109	East Doors

Box 96 of 109	Life on Earth Exhibit
Box 96 of 109	7633355 Northwest Entrance (2 folders)
Box 96 of 109	7633360 Handrails
Box 96 of 109	Museum Shop Area
Box 96 of 109	Paint Colors - Halls/Rotunda
Box 96 of 109	East Yard
Box 96 of 109	Electrical - Tower Offices
Box 96 of 109	33403 Computer Room - Electrical Wiring
Box 96 of 109	Watch Tour System
Box 96 of 109	7733106 Humidity
Box 96 of 109	Computer Facility - Air Conditioning
Box 96 of 109	Peerless 820 Pump
Box 96 of 109	Voltage in Main Halls
Box 96 of 109	Painting of Decorative Stencils
Box 96 of 109	33367 East-North Range - "1876"
Box 96 of 109	33356 Air Conditioning - Southeast Range
Box 96 of 109	South Hall - Barrier
Box 96 of 109	SI Press Relocation
Box 96 of 109	Fire Protection System
Box 96 of 109	7733102 Checkroom
Box 96 of 109	Electrical Feeders
Box 96 of 109	FC-6-60605 North Hall Lights
Box 96 of 109	Sprinkler System
Box 96 of 109	Steam Engine Platform - West Hall

Box 96 of 109	Air Conditioning Modification to East-South Range
Box 96 of 109	Information Booths
Box 96 of 109	Rotunda Lights
Box 96 of 109	7633418 Archives - Detector System
Box 96 of 109	OEO Move
Box 96 of 109	Archives Move
Box 96 of 109	7733103 South Tower
Box 96 of 109	Associates Classroom Move
Box 96 of 109	Ventilation
Box 96 of 109	Space
Box 96 of 109	South Entry R&R - Grunley-Walsh
Box 96 of 109	Grunley-Walsh Claim
Box 96 of 109	Tile
Box 96 of 109	R&R (folder 1 of 5)
Box 97	
Box 97 of 109	R&R (folders 2-5 of 5)
	Various Buildings Summary: Various Buildings
Box 97 of 109	7530208 Mall Sidewalks
	Smithsonian Institution Building and South Yard Summary: Smithsonian Institution Building and South Yard
Box 97 of 109	General Information
Box 97 of 109	South Yard Development (2 folders)
Box 97 of 109	Fire and Smoke Detection
Box 97 of 109	7663328 South Yard Development

Box 97 of 109	Commons Kitchen
Box 97 of 109	Crypt Gates
Box 97 of 109	Carousel Project
Box 97 of 109	Nursery - Greenhouse Operation
Box 97 of 109	Southeast Areaway Steps
Box 97 of 109	FA-6-69936 Alteration of Staff Facility for Ball/Henry Library
Box 97 of 109	Bell Henry Papers - Change Orders
Box 97 of 109	Windows for East Wing
Box 97 of 109	Humidification System
Box 97 of 109	Space
Box 97 of 109	7632313 Shutter Blinds for Room 507
Box 97 of 109	Joseph Henry Papers - Change Orders
Box 97 of 109	Grade of Independence Avenue
Box 98	
Box 98 of 109	Lawn Sprinkler System
Box 98 of 109	Exterior Stairs, Northeast Doors - Guard Rails
Box 98 of 109	Room 507 Shutters
	Woodrow Wilson Center Summary: Woodrow Wilson Center
Box 98 of 109	Study for Building Program
	Anacostia Neighborhood Museum Summary: Anacostia Neighborhood Museum
Box 98 of 109	General (Production and Design Laboratory)
Box 98 of 109	Exhibits Laboratory Building
Box 98 of 109	Mezzanine Guard Rail - Exhibits Laboratory

Belmont Mansion
Summary: Belmont Mansion

Box 98 of 109 Conference

Box 98 of 109 Security

Box 98 of 109 General

Chesapeake Bay Center for Environmental Studies
Summary: Chesapeake Bay Center for Environmental Studies

Box 98 of 109 General Information

Box 98 of 109 Jefferson Island (2 folders)

Box 98 of 109 Visitor Center/Dormitory

Box 98 of 109 Calf Barn

Box 98 of 109 Project Development

Box 98 of 109 Facility Plan

Box 98 of 109 Waste Disposal System

Cooper-Hewitt Museum
Summary: Cooper-Hewitt Museum

Box 98 of 109 Carnegie Mansion

Box 98 of 109 Change Orders

Box 98 of 109 Carnegie Renovation (2 folders)

Fine Arts and Portrait Gallery
Summary: Fine Arts and Portrait Gallery

Box 98 of 109 General

Box 98 of 109 Paint Exterior Doors, Trim, and Sash, June 1975

Box 98 of 109 Toby Exhibit

Box 98 of 109 First Floor Renovation

Box 98 of 109 RLA - Pedestrian Plans

Box 98 of 109 Cracking - Metro Construction

Box 98 of 109	Restaurant and Kitchen - Air Conditioning
Box 98 of 109	Second Floor - New Light System
Box 98 of 109	Stone Steps and Handrail
Box 98 of 109	34381 Granite Gallery - Redevelopment Plans
Box 98 of 109	Emmanuel Leutze Exhibition
Box 98 of 109	Third Floor Renovation
Box 98 of 109	34439 Kitchen Exhaust
Box 98 of 109	34440 Leaky Valves
Box 98 of 109	7th Street Renovation
Box 98 of 109	Renovation of 9th Street Steps
Box 98 of 109	Modified Renovations of Printing Study - Room 153
Box 98 of 109	FC-4-65805 Gallery 341 - "Made in Chicago" Exhibit
Box 98 of 109	Smoke Detection System
Box 98 of 109	Court Improvements
	Freer Gallery of Art Summary: Freer Gallery of Art
Box 98 of 109	Fire Detection System
Box 98 of 109	General
Box 98 of 109	7537186 South Lobby Wall
Box 98 of 109	7537177 Water Line Replacement
Box 98 of 109	37312 Four Doors - Auditorium, West Side
Box 98 of 109	Roof and Skylights
	Film Storage Vault Summary: Film Storage Vault
Box 98 of 109	Anthropological Film Center

Hillwood Mansion
Summary: Hillwood Mansion

Box 98 of 109 General

L'Enfant Plaza
Summary: L'Enfant Plaza

Box 98 of 109 Move of MAO

Box 98 of 109 General

Hirshhorn Museum and Sculpture Garden
Summary: Hirshhorn Museum and Sculpture Garden

Box 98 of 109 Progress Reports

Box 98 of 109 General Information - Correspondence

Box 98 of 109 Food Concessions

Box 98 of 109 Museum Shop

Box 98 of 109 Security Systems

Box 98 of 109 Correspondence - Kewaunee Scientific Equipment

Box 98 of 109 45395 Fire Detection System

Box 98 of 109 FC-6-62286 Planters

Box 98 of 109 Humidity Controls - Fans 1-3 and 8

Box 98 of 109 Fountain - Etching

Box 99

Box 99 of 109 Information Desk

Box 99 of 109 Statuary (Pedestals)

Box 99 of 109 Joseph Henry Landscaping

Box 99 of 109 Security System

Smithsonian Institution Service Center
Summary: Smithsonian Institution Service Center

Box 99 of 109 1111 North Capitol Street

	History and Technology Building Summary: History and Technology Building
Box 99 of 109	General Information
Box 99 of 109	American Political History Exhibition - Second Floor, Section C
Box 99 of 109	1876 Centennial-style Benches
Box 99 of 109	Centennial Exhibit - Antietam Platform
Box 99 of 109	Health Unit
Box 99 of 109	Juley Collection
Box 99 of 109	7530249 Fumigation Room HVAC
Box 99 of 109	Physical Science Modifications
Box 99 of 109	Folk Art Plans
Box 99 of 109	Huber Tractor and John Bull Locomotive
Box 99 of 109	Person to Person Exhibit
Box 99 of 109	Person to Person - Change Orders
Box 99 of 109	7630375 Audiovisual Equipment Room - Nation of Nations Hall
Box 99 of 109	Ramp and Canopy - Nation of Nations
Box 99 of 109	7630314 Lobby Ceiling
Box 99 of 109	Sidewalk Repair
Box 99 of 109	Nation of Nations
Box 99 of 109	Pilot House
Box 99 of 109	2A1000-73 Opening Between G. O. U. S. (Growth of the United States) and Everyday Life Halls
Box 99 of 109	Sixth Floor Library (Dibner)
Box 99 of 109	Modifications - Executive Dining Room
Box 99 of 109	Cafeteria Renovation

Box 99 of 109	Exhibit - "Of the People, By the People, For the People"
Box 99 of 109	Fire Protection System
Box 99 of 109	Fourth Floor Telephone Equipment
Box 99 of 109	Receiving Facility - Basement
Box 99 of 109	Modifications - Post Office (Handicapped)
Box 99 of 109	Renovation of Musical Instruments
Box 99 of 109	Suiting Everyone Exhibit
Box 99 of 109	Numismatics and Philately
Box 99 of 109	Renovation - Conservation Analytical Laboratory Space
Box 99 of 109	Engineer Room in Maritime Hall
Box 99 of 109	History of American Banking
Box 99 of 109	Museum Shops
Box 99 of 109	Statue of Freedom
Box 99 of 109	South Terrace Safety Netting
Box 99 of 109	HTB751A Health Unit (3 folders)
Box 99 of 109	Solar Energy
Box 99 of 109	FC-4-61680 Claim - Grunley-Walsh
Box 99 of 109	MHT662C Fountain (2 folders)
Box 100	
Box 100 of 109	Fountains and Snow Melting System (3 folders)
	Natural History Building Summary: Natural History Building
Box 100 of 109	Correspondence
Box 100 of 109	7531151 Heating and Air Conditioning Ventilation
Box 100 of 109	Baird Auditorium

Box 100 of 109	Discovery Room
Box 100 of 109	First Floor, Hall 6
Box 100 of 109	Room 326
Box 100 of 109	Health Unit
Box 100 of 109	Power Operators/Sliding Doors
Box 100 of 109	Survey of Hall 23 for Exhibit Design and Construction
Box 100 of 109	Hall 23 - Smoke Detection System
Box 100 of 109	Demolition of Hall 26
Box 100 of 109	7731106 North Hall (Ceiling)
Box 100 of 109	South Retaining Wall
Box 100 of 109	Filter System
Box 100 of 109	South Doors
Box 100 of 109	Sprinkler and Duct Work
Box 100 of 109	South Entrance - Benches
Box 100 of 109	Completed Projects
Box 100 of 109	Meteorite Saw
Box 100 of 109	Mineral Preparation Laboratory - Change Orders
Box 100 of 109	East Court Development
Box 100 of 109	Hall 29 - Insect Zoo
Box 100 of 109	Study of Man
Box 100 of 109	CP-6-21267 West Court - Millwork (Review)
Box 100 of 109	Elevator Modifications
Box 100 of 109	Cloak Room
Box 100 of 109	FA-6-60973 North Sprinkler Fire Pump Loop - Main

Box 100 of 109	Mineral Preparation Laboratory
Box 100 of 109	Osteo Preparation Facility - Change Order
Box 100 of 109	Rotunda and Ambulatory Restoration
Box 100 of 109	East Court - Osteo Preparatory Facility
Box 100 of 109	West Court
Box 101	
Box 101 of 109	Botany Greenhouse (3 folders)
Box 101 of 109	262 HVAC Coil Replacement
Box 101 of 109	HVAC Problems in West Court
Box 101 of 109	7631388 East Wing Floor Loading
Box 101 of 109	7631362 West Court - Audit (American Construction Company)
Box 101 of 109	Naturalist Center
Box 101 of 109	West Court Eating Facility (Marriott)
Box 101 of 109	Lighting System
Box 101 of 109	Detector System and Related Additions and Extension to Fire Alarm
Box 101 of 109	Escalators
Box 101 of 109	Fire Pumping System
Box 101 of 109	West Court Addition - Rotunda Level Plan
Box 101 of 109	"Our Changing Land" Exhibit - Ecology 200 (Bicentennial)
Box 101 of 109	7631415 Fire Doors
Box 101 of 109	Hall 20 - Lunar Geology
Box 101 of 109	South Portal Air Curtain
Box 101 of 109	Registrar's Office - West Entrance
Box 101 of 109	Viking Study

National Air and Space Museum
Summary: National Air and Space Museum

Box 101 of 109	General - Correspondence
Box 101 of 109	Construction - Progress
Box 101 of 109	Escalators
Box 101 of 109	Spacearium Turntable
Box 101 of 109	Sculpture - Maquette
Box 101 of 109	Apollo Project
Box 101 of 109	Theater - Specifications and Parameters
Box 101 of 109	World War II Exhibition
Box 101 of 109	Pylon for Milestones of Flight
Box 101 of 109	The Evolution of the Spacesuit
Box 101 of 109	35417 Overflow Alarms and Waterproofing - Third Floor Air Handling Units
Box 101 of 109	Parking Facility
Box 101 of 109	FC-6-60354 Height Detector Signs
Box 101 of 109	Security Systems
Box 101 of 109	Fire Detection System
Box 101 of 109	Sales Shop
	Silver Hill Facility Summary: Silver Hill Facility
Box 101 of 109	General File
Box 101 of 109	Demolition - Festival Barn
Box 101 of 109	Loading Dock
Box 101 of 109	Guardrails
Box 101 of 109	Building 13 and 14

Box 101 of 109	Building 23
Box 101 of 109	7538198 Concrete Slab Between Buildings 14 and 16
Box 101 of 109	38349 Hanging Load Analysis
Box 101 of 109	Flammable Liquid Storage Building
Box 101 of 109	Building 24
Box 101 of 109	7738445 Parking Lot Paving
Box 101 of 109	Building 25
Box 101 of 109	Statuary Storage
Box 101 of 109	7638382 Roadway Repairs
Box 101 of 109	Street Paving
Box 101 of 109	7638310 Relocate Weld Shop in Building 10

Box 102

	Barney Studio House Summary: Barney Studio House
Box 102 of 109	General
Box 102 of 109	Fire Escape
	Tariff Commission Building Summary: Tariff Commission Building
Box 102 of 109	General
	Old Post Office Building Summary: Old Post Office Building
Box 102 of 109	General
	Pension Building Summary: Pension Building
Box 102 of 109	General
	Renwick Gallery Summary: Renwick Gallery

Box 102 of 109	Paley Gates
Box 102 of 109	General
Box 102 of 109	7735101 Decorated American Furniture
Box 102 of 109	Hall 206
Box 102 of 109	7636210 Catwalk Above Grand Stair
Box 102 of 109	Basement Leaks
Box 102 of 109	Modern Consciousness Exhibit
Box 102 of 109	Signs of Life - 1976 Exhibit
Box 102 of 109	Roof and Railing Repairs
Box 102 of 109	H. H. Richardson Exhibit
Box 102 of 109	Area and Walk Shelters
Box 102 of 109	Exterior
	Willard Hotel Summary: Willard Hotel
Box 102 of 109	General
	24th Street Summary: 24th Street
Box 102 of 109	General
	Smithsonian Astrophysical Observatory Summary: Smithsonian Astrophysical Observatory
Box 102 of 109	Mount Hopkins
Box 102 of 109	General - Correspondence
	Smithsonian Tropical Research Institute Summary: Smithsonian Tropical Research Institute
Box 102 of 109	Master Facilities Plan
Box 102 of 109	Photographs, January 1967

Box 102 of 109	Photographs, undated
	National Zoological Park Summary: National Zoological Park
Box 102 of 109	Recommended Parking and Traffic Improvements
	South Quadrangle Summary: South Quadrangle
Box 102 of 109	Development Project - CS&D-BFLT Proposal
Box 102 of 109	Development Project - Faulkner, Fryer, and Vanderpool/Anderson Notter/ Mariani Proposal
Box 102 of 109	Development Project - Benhan-Blair Affiliates, Inc./Navy, Marshall, and Gordon/E. Verner Johnson and Associates Inc. Proposal
Box 102 of 109	Development Project - Edward Larabee Barnes/Perkins and Will Partnership Proposal
Box 102 of 109	Development Project - Helmuth, Obata, and Kassabaum Proposal
	Administrative Records and Various Buildings Summary: Administrative Records and Various Buildings
Box 102 of 109	Energy Conservation Program
Box 102 of 109	Minutes of Executive Committee Meeting
Box 102 of 109	Environmental Engineering Committee
Box 102 of 109	General - Administrative Officer
Box 102 of 109	Staff Meetings
Box 102 of 109	OSHA Training Data
Box 102 of 109	Annual Report - Fiscal Year
Box 102 of 109	Policies and Procedures
Box 102 of 109	General Information
Box 102 of 109	Status - Projects
	Box 103
Box 103 of 109	Budget Information

Box 103 of 109	General - Small Jobs
Box 103 of 109	Elevator Repairs
Box 103 of 109	General - Change Orders
Box 103 of 109	Staff Meetings - Mr. Ault
Box 103 of 109	All Building - Fire Protection
Box 103 of 109	Management Study of the Buildings Management Department
Box 103 of 109	Organization of the Buildings Management Department
Box 103 of 109	Service Bulletin of the Office of Engineering Services
Box 103 of 109	Development of Policies and Procedures
Box 103 of 109	Buildings Management Department Study and Reorganization
Box 103 of 109	Responsibilities and Procedures
Box 103 of 109	Maintenance Capabilities for Museum and Building Directors
Box 103 of 109	Buildings Management Report and Implementation
Box 103 of 109	General Correspondence
Box 103 of 109	Filing - Old Files
Box 103 of 109	Standard Standing Unit Cases
Box 103 of 109	7900107 Environmental Requirements (2 folders)
Box 103 of 109	Silver Hill Foundation and Slab - Building 25
Box 103 of 109	Parham 64 Office Park - Phase I
Box 103 of 109	Anchor Bolt Setting Plan
Box 103 of 109	Museum Support Facility - Dalton Dalton Little Newport Proposal
Box 103 of 109	GSA Bulletins and Regulations
Box 103 of 109	Mall - Master Plan
Box 103 of 109	Washington Mall Parking Facilities Feasibility Analysis

Box 103 of 109	Folklife Festival - Mall
Box 103 of 109	WMATA - General and Bus Rider Shelter
Box 103 of 109	Memoranda - Announcements and Recruit Sheets
Box 103 of 109	Memoranda, Announcements, and Recruiting Information for All Personnel (2 folders)
Box 104	
Box 104 of 109	Critical R&R Project Reports (2 folders)
Box 104 of 109	R&R Projects Status Reports
Box 104 of 109	Construction Projects Reports
Box 104 of 109	Physical Plants Improvements Policy
Box 104 of 109	R&R Construction - Ten Year Plant
Box 104 of 109	Construction, Facilities, and Plant Operations
Box 104 of 109	SI Policy - Exhibits and Construction
Estimating/Planning Files, 1975-1978 Summary: Estimating/Planning Files, 1975-1978	
Box 104 of 109	Anacostia Neighborhood Museum (2 folders)
Box 104 of 109	7650145 Inclined Lift - Barro Colorado Island
Box 104 of 109	7800115 Springfield Warehouse
Box 104 of 109	7800124 SISC Collection Storage Modifications
Box 104 of 109	7800121 Parking Study
Box 104 of 109	7500176 and 7500177 Museum of African Art
Box 104 of 109	Miscellaneous
Box 104 of 109	NMNH West Court
Box 104 of 109	NMNH North Hall
Box 104 of 109	NMNH Bicentennial Exhibition

Box 104 of 109	NMNH Escalators
Box 104 of 109	NMNH Botany Greenhouse
Box 104 of 109	NMNH Miscellaneous
Box 104 of 109	NMNH Exterior Lighting
Box 104 of 109	NMNH West Court Utilities
Box 104 of 109	STRI (3 folders)
Box 104 of 109	NMNH West Court Dining (Marriott)
Box 105	
Box 105 of 109	A&I (3 folders)
Box 105 of 109	HMSG (2 folders)
Box 105 of 109	Renwick (2 folders)
Box 105 of 109	CBCES (2 folders)
Box 105 of 109	SI Building (2 folders)
Box 105 of 109	FAPG
Box 105 of 109	FGA
Box 105 of 109	Silver Hill Facility (2 folders)
Box 105 of 109	Barney House
Box 105 of 109	CHM, Carnegie Mansion
	Conditions and Specifications Summary: Conditions and Specifications
Box 105 of 109	Sprinkler Piping for Conservation Analytical Laboratory
Box 105 of 109	A&I South Entrance
Box 105 of 109	A&I Museum Shop
Box 105 of 109	NMNH West Court Addition - Cabinetwork
Box 106	

Box 106 of 109	General (2 folders)
	Estimating/Planning Files, 1975-1978 Summary: Estimating/Planning Files, 1975-1978
Box 106 of 109	Osteo Preparation Laboratory
Box 106 of 109	A&I (3 folders)
Box 106 of 109	HTB Nation of Nations
Box 106 of 109	A&I Interior Painting
Box 106 of 109	MHT Central Health Unit
Box 106 of 109	HTB Entrance Doors
Box 106 of 109	MHT History of Banking
Box 106 of 109	Silver Hill Reconstruction of Festival Barn
Box 106 of 109	Anacostia Neighborhood Museum - Handicapped Access
Box 106 of 109	NHB Hall 23 - Acoustical Tile Ceiling
Box 106 of 109	FGA and SI Building Smoke Detection Systems
Box 106 of 109	SISC Smoke Detection System
Box 106 of 109	A&I Roof
Box 106 of 109	Archives
Box 106 of 109	Associates Classrooms
Box 106 of 109	A&I West Hall
Box 106 of 109	Anacostia Neighborhood Museum
Box 106 of 109	A&I Museum Shop
Box 106 of 109	HMSG Handicapped Ramp
Box 106 of 109	Joseph Henry Papers
Box 106 of 109	SITES
Box 106 of 109	A&I Plumbing and Electrical

Box 106 of 109	A&I Southwest Court
Box 106 of 109	A&I Accounting Division
Box 106 of 109	NHB Slab
Box 106 of 109	A&I Rotunda
Box 106 of 109	SI Building - Basement Lighting
Box 106 of 109	A&I South Entrance
Box 106 of 109	A&I North Entrance
Box 106 of 109	FGA Elevator
Box 106 of 109	A&I Elevator
Box 106 of 109	SI Building Elevator
Box 106 of 109	NHB Elevator
Box 106 of 109	NMNH Hall 20 - Lunar Geology
Box 106 of 109	NMNH Sprinkler Additions
Box 106 of 109	NHB Roofing System
Box 107	
Box 107 of 109	NMNH West Court Office of Education and School Tours
Box 107 of 109	NMNH Meteorite Saw
Box 107 of 109	NHB Miscellaneous (2 folders)
Box 107 of 109	CBCES Laboratory Building Addition
Box 107 of 109	Anacostia Neighborhood Museum, Exhibit Design and Production Laboratory
	Conditions and Specifications Summary: Conditions and Specifications
Box 107 of 109	South Yard Development
Box 107 of 109	A&I Interior Painting

Box 107 of 109	NMNH West Court
Box 107 of 109	MHT Dibner Interium Library
Box 107 of 109	NHB Greenhouse
Box 107 of 109	STRI Building 401 (Ancon)
Box 107 of 109	HTB Numismatics and Philately Reference Collection Vaults - Fire Extinguishing System
Box 107 of 109	NHB - SI Library HVAC Modifications
Box 107 of 109	NMNH Sprinkler Fire Pumping System
Box 107 of 109	SI Building Fire Detection System - Phase I
	Natural History Building Summary: Natural History Building
Box 107 of 109	7631414 Modification - Stair 2, West Court
Box 107 of 109	753110 Odor Problems - West Court Addition, 12/9/1977
Box 107 of 109	7631246 Mezzanine Room 63A, 5/30/1979 (2 folders)
Box 107 of 109	7631351
	Box 108
Box 108 of 109	771107 North Foyer Smoke Detection, 12/1/1977
Box 108 of 109	773117 Catwalks, 10/25/1977
Box 108 of 109	773122 Fire Protection Master Plan, 12/12/1978
Box 108 of 109	7831118 Hall 2, 4/14/1980
	Box 109
Box 109 of 109	7731123 Coral Reef, 12/27/1979
Box 109 of 109	7931192 Attic Rework - Halls 2, 10, and 12, 2/16/1979
Box 109 of 109	7931103 Rotunda Acoustics, 12/13/1979
Box 109 of 109	7931104 Redesign Museum Shops Office Space, 2/7/1979

Box 109 of 109 7931110 Women's Locker Room, 6/13/1979

Various Buildings
Summary: Various Buildings

Box 109 of 109 Historic Photographs of Various Buildings and the Mall

Arts and Industries Building
Summary: Arts and Industries Building

Box 109 of 109 Stenciling

Hirshhorn Museum and Sculpture Garden
Summary: Hirshhorn Museum and Sculpture Garden

Box 109 of 109 Proposed Site Plan